

Marcus Foster Arboricultural Design & Consultancy

BA (Hons) | NDArb | Techcert (AA) | MArborA

Arboricultural Survey & Report

Site:

12A Lancaster Grove London NW3 4NX

Client:

LBMV Architects

Date of Report:

July 2023

Date Reference:

AR/MF/0131/23

Report Prepared by:

Marcus Foster BA (Hons) | TechCert (AA) | MArborA



Marcus Foster Arboricultural Design & Consultancy

Tel: + 44 (0) 7812 024 070
Email: marcus@mfdesignconsultancy.com
Web: www.marcus-foster.com

Report Contents

- 1. Instructions
- 2. Introduction
- 3. Survey details and scope
- 4. Survey limitations
- 5. Tree Survey Summary
- 6. Tree Works Schedule
- 7. Appendices

Tree Survey Report - Reference: AR/MF/0131/23 Site: 12A Lancaster Grove, London, NW3 4NX

Prepared for: LBMV Architects

1.0 Instructions

1.1 This report has been instructed by LBMV Architects to survey, make assessment and provide recommendations for 4 no. trees (T1-T4) within the rear of the subject property -12A Lancaster Grove, London, NW3 4NX.

2.0 Introduction

- 2.1 A site visit was made on 6th July 2023 to survey and assess the site and tree in relation to the property. The weather at the time of inspection was bright and mild with tree in late spring mode.
- 2.2 The details of the subject trees are set out in the tree survey table in Appendix A. The trees were surveyed on the date and time shown above and the tree survey assessment information for the trees describing size, condition and surroundings is found in this appendix.
- 2.3 The trees surveyed are shown in a site plan, Appendix B, and this corresponds to the tree survey schedule, Appendix A.
- 2.4 Photographs of the tree can also be found in Appendix C.
- 2.5 This report and the opinions within it have been produced without prejudice by Marcus Foster; a qualified arboriculturist and professional member of the Arboricultural Association (MArborA) holding a National Diploma in Arboriculture, and the Arboricultural Association's Technicians Certificate as well as the Professional Tree Inspection Certificate (LANTRA). Marcus Foster also holds a degree in History and Society (University of Exeter). Work experience within the industry includes work as a Contracts Manager for an Arboricultural Association Approved Company, a Local Authority Tree Preservation Officer and an independent Arboricultural Consultant.

Tree Survey Report - Reference: AR/MF/0131/23 Site: 12A Lancaster Grove, London, NW3 4NX

Prepared for: LBMV Architects

3.0 Survey Details and Scope

- 3.1 The site survey for the purposes of this report includes 4 no. trees (T1-T4) as shown in the survey, Appendix A, and also highlighted on the site plan, Appendix B.
- 3.2 The survey has been undertaken to determine:
 - (i) Tree Management Strategy
 - (ii) Mitigation for recommendaions
- 3.3 The trees have been surveyed from ground level only. The height of the trees have been estimated.
- 3.4 The following information was recorded for the tree and is shown in the Tree Schedule included in Appendix A refer to full tree schedule key:
 - Number: an identity number which cross references locations shown on the plan in Appendix A with the schedule in Appendix B.
 - Species: listed by common names
 - Tree Height: approximate height in metres
 - Tree Spread: approximate height in metres
 - Stem diameter: measured in millimetres (mm) and taken at 1.5m above ground level
 - Age Class: Y (young); EM (early-mature); M (mature); OM (over-mature)
 - Physiological Condition:: G (good); F (fair); P (poor); D (dead)
 - Structural Condition: G (good); F (fair); P (poor); D (dead)
 - General Comments: Specific comments relating to each tree
 - Management recommendations
 - NHBC Categorisation (Chpt 4.2 2021)¹
 - Work Priority Ratings
 - Inspection Frequency
- 3.5 The information contained within the report reflects the condition of the specimen examined at the time of the inspection. As the inspection was only visual no guarantee can be given concerning the condition of the wood at present in any of the trees inspected and furthermore that no future problems or deficiencies may arise.
- 3.6 Information recorded in the tree survey is expanded in the report findings and a management programme specified in the recommended schedule of works has been included.

Tree Survey Report - Reference: AR/MF/0131/23 Site: 12A Lancaster Grove, London, NW3 4NX

Prepared for: LBMV Architects

¹ NHBC, Chapter 4.3 - Building near Trees (2021)

4.0 Survey Limitations

- 4.1 No soil excavation or root inspection has been carried out.
- 4.2 This report only considers conditions at the time of inspection and is a visual inspection.
- 4.3 No internal decay devices/ invasive tools were used during this site survey.
- 4.4 Soil conditions have been researched but have not been physically investigated.
- 4.5 It should be noted that trees and vegetation are dynamic organisms and are subject to environmental change / alterations further to site condition changes.
- 4.6 The report does not purport to make structural engineering recommendations or assessments. Should there be any future structural movement the situation regarding the tree and / or vegetation should be re-assessed.

Tree Survey Report - Reference: AR/MF/0131/23 Site: 12A Lancaster Grove, London, NW3 4NX

Prepared for: LBMV Architects


5.0 <u>Tree Survey Findings</u>

Overview

5.1 The trees surveyed are located at 12A Lancaster Grove, London, NW3 4NX. The property is located within the London Borough of Camden. The following statutory checks have been made for the site:

CONSERVATION AREA STATUS
Belsize Conservation Area
TREE PRESERVATION ORDER (TPO) STATUS
None applicable

5.2 The site location and statutory protection is confirmed as below:



Extract from: https://ssa.camden.gov.uk/connect/analyst/mobile/#/main? mapcfg=%2FMapProjects%2FCamdenConservation

5.3 As viewed July 2023 http://www.ukso.org show the property to be located on a medium to heavy soil mix consisting mainly of clayey loam to silty loam, meaning that plasticity levels of the soil are generally low to moderate.



Extract from: ukso.org

Tree Survey Report - Reference: AR/MF/0131/23 Site: 12A Lancaster Grove, London, NW3 4NX

Prepared for: LBMV Architects

Findings

5.4 Summary of the 4 no. trees (T1-T4) surveyed is confirmed below:

Tree No: T1

Species: Bull bay Magnolia (Magnolia grandiflora)

NHBC Rating: Low

Management History: Selective management - crown lifting

Tree No: T2

Species: Elder (Sambucus nigra)

NHBC Rating: None applicable - shrub form

Management History: Limited

Tree No: T3

Species: Cherry (*Prunus spp*) NHBC Rating: Moderate Management History: Limited

Tree No: T4

Species: Holm oak (Quercus ilex)

NHBC Rating: High

Management History: Limited - sapling

5.5 Summary photographs are shown below:



Tree T1 viewed from within rear garden to north east



Tree T2 viewed from within rear garden to



Tree T4 viewed from within rear garden to north



Overview of northern boundsary

Tree Survey Report - Reference: AR/MF/0131/23 Site: 12A Lancaster Grove, London, NW3 4NX

Prepared for: LBMV Architects

5.6 For the removal of the trees / shrub 1 no. replacement tree is recommeded to mitigate and provide replacement amenity value within the site location shown within DWG T001 and as shown below:



Proposed location for replacement tree planting

- 5.7 The replacement planting proposal this shall be of a species in accordance with the following:
 - Climate change resilience
 - Pest and disease resilience
 - Future occupancy consideration for rear garden
 - Implementation scheme to BS8545 (Trees: From Nursery to Independence in the Landscape, 2014)
 - Aftercare and establishment programme

The replacement planting must be a minimum 10-12cm Select standard size

Summary

- 5.8 The recommended management plan as included within Section 6 applies the following recommendations:
 - (i) Tree works applicable for T1-T4 as a management plan for removal; scheduled to be undertaken as a 'Moderate' priority (within 1 year)
- 5.9 With removal of T1-T4 mitigation is for replacement of 1 no. tree to be a minimum 10-12cm Select standard size
- 5.10 The report does not make reference to or provide structural engineering recommendations and should there be any future structural movement of the property the situation regarding the tree should be re-assessed.

Tree Survey Report - Reference: AR/MF/0131/23 Site: 12A Lancaster Grove, London, NW3 4NX

Prepared for: LBMV Architects

6.0 Tree Works Schedule

6.1 Any tree work should be carried out to BS 3998; 2010 Recommendations for Tree Work. Permissions from the Local Authority, are not applicable as statutory protection is not relevant for the subject property.

TREE WORKS SCHEDULE: 12A Lancaster Grove, London, NW3 4NX									
Tree No.	Common Name	Tree Works	Reasons for works	Priority Rating					
T1	Bull bay Magnolia	Transplant from southern boundary to northern boundary (Within dormant season: November - March)	Improved location	М					
T2	Elder	Fell to ground level	Inappropriate location	М					
Т3	Cherry	Fell to ground level Provide 1 no. replacement planting - minimum 10-12cm Select standard size	Inappropriate location	М					
T4	Holm oak	Fell to ground level	Inappropriate location	М					

NOTE: Wildlife & Habitat Protection Guidelines

The tree work specifications included within this report do not provide an exemption from the requirements to comply with the Wildlife and Countryside Act 1981, the Habitats Regulations 1994 and the Countryside and Rights of Way Act 2000, or any acts offering protection to wildlife. Of particular note is the protection offered to bats, birds and their nests, whilst being built or in use. It must be noted that failure to comply with the Acts may result in a criminal prosecution.

Tree Survey Report - Reference: AR/MF/0131/23 Site: 12A Lancaster Grove, London, NW3 4NX

Prepared for: LBMV Architects

Appendices Appendix A: Tree Schedule

Key to Tree Schedule

Identity number which cross reference locations shown on the plan in Appendix A with the schedule in Appendix B also

Species:
Listed by Latin name and / or common names as deemed appropriate

Tree Spread:

Height in metres

Stem diameter: Measured in millimetres (mm) and taken at 1.5m above ground level

Age Class:

Y (young)

Recently planted or established tree - less than 150mm diameter

SM (semi-mature)

SM (semi-mature)

Established tree but with significant growth to reach optimum size and form
EM (early-mature)

A tree at maturity but with potential for increased girth and spread which will continue to develop size and form
M (mature)

A mature specimen within final third of lifespan; limited increase in size and/or development of form

OM (over-mature)

OM (over-mature)

A declining tree within latter stages of lifespan. Increased frequency within crown of structural defects and/or lower vigour are likely

V (Veteran)

A tree of significant physical, biological, cultural or aesthetic value which has lived beyond the typical lifespan relative to species. Structural defects are likely a prominent feature and require appropriate management in relation to the importance of the tree

Dead

The tree is dead and cannot be categorised within any of the above

Vitality

Witality:
G (good)
Generally in good health and condition - relative to species - and requiring no remedial action
Minor deadwood may be evident although extent relative to species
Leaf size, extension growth and crown density normal for species
F (fair)

Tree is showing signs of stress including, although not exhaustive of - lowered crown density, excessive deadwood, excessive epicormic growth, selective dieback, pests and diseases,

The is showing signs of stress including, authority in the extraostrive of a lowered crown feeting, excessive deadwood, excessive epicornic growth, selective depeats, pests and disease abnormal leaf size / extension growth

The condition may be alleviated with remedial works / plant health care although these works should not be prioritised in relation to health and safety P (poor)

Tree is showing signs of signifient physiological decline including overall crown dieback, stag headed form, very poor crown density, limited extension growth, bud burst and decline thereafter, pest infestation

Remedial work is unlikely to provide improvement in physiological condition

D (dead)

The tree is no longer alley with no physiological attributes evident

The tree is no longer alive with no physiological attributes evident

Structural condition:

G (good)

Few minor defects with overall good structural condition
Showing no adverse risk of failure/s

F (fair) A tree which has a structural defect (major in early / semi maturity or developing stages of life and minor in full maturity) which requires remedial action

A free which has a structural defect (major in early / semi maturity or developing stages of lite and minror in full maturity) which requires remedial action

Structural defects could include significant compression forks, co-dominant stems, major deadwood, poor previous pruning, storm damage, limb failure, cavities, decay

Tree may repair via self optimisation which could be dependant on species / age of tree. Or remedial tree works specified for management of defect

P (poor)

Tree's structural integrity compromised from poor structural condition

Major structural defects may include decay, cavity, fungal fruiting bodies, significant dead wood, hanging limbs, major storm damage, excessive and significant pruning wounds D (dead)

Comments & Observations

Further to inspection comments which relate to both the physiological and structural condition of the tree and any important site factors also

Management recommendations
Tree Works Specification in accordance with BS3998:2010 and where appropriate BS8545:2014

NHBC Rating:

H (High) M (Moderate) L (Low)

Work Priority Rating: U (Urgent) Immediately / Make safe within 24 hours

VH (Very High)

Within 5 Days
Also appropriate where significant site constraints / infrastructure organisate
H (High)
Within 30 Days ation exists to enable implementation, including 5 day notice

M (Moderate

Utilin 1 year
L (Low)
Within 2 years
May refer to works related to aesthetics of the tree where deemed appropriate / previously implemented

Inspection Frequency

U (Urgent)
Carry out as soon as possible - likely for an aerial inspector VH (Very High)

Within 30 days H (High)
Within 6 months
M (Moderate) Annually L (Low) Every 3 years

Tree Survey Report - Reference: AR/MF/0131/23 Site: 12A Lancaster Grove, London, NW3 4NX


Prepared for: LBMV Architects

Marcus Foster _ BA (Hons) NDArb. Tech.Cert (AA) MArborA

	Inspection Frequency	1	1	1	1
	Work Priority Rating	V	W	×	Σ
	NHBC Category Rating	L	L	Σ	Σ
VEY SCHEDULE	Recommendations	Transplant from southern boundary to northern boundary (Within dormant season: November - March)	Fell to ground level	Fell to ground level Provide 1 no. replacement planting	Fell to ground level
MARCUS FOSTER ARBORICULTURAL DESIGN & CONSULTANCY - TREE SURVEY SCHEDULE Survey Site: 12A Lancaster Grove, London, NW3 4NX Survey Date: 6th July 2023	Comments	Ornamental. Open crown habit	Sited on boundary. Large shrub / small tree	Ornamental; lean to south, supressed form	Young; one-sided crown to north west. 0.5m distance from boundary wall; 5m from southern building elevation of 12a Lancaster Grove
RBORICULTUR Survey Site: 12 St	Structural Condition	Ŧ	F	Ŧ	O
US FOSTER A	Physiological Condition	Ł	4	Ł	¥
MARC	Age Class	>	ν	SM	>
	Crown Spread (m)	4	Ŋ	4	ဗ
	Stem Diameter (mm)	80	210	110	100
	Height (m)	Ŋ	2	Ŋ	ω
	Species	Bull bay Magnolia	Elder	Cherry	Holm oak
	Tree No.	Т1	T2	T3	T4

Tree Survey Report - Reference: AR/MF/0131/23 Site: 12A Lancaster Grove, London, NW3 4NX Prepared for: LBMV Architects Date: July 2023

Appendix B: Tree Survey Site Plan: DWG T001



Tree Survey Report - Reference: AR/MF/0131/23 Site: 12A Lancaster Grove, London, NW3 4NX Prepared for: LBMV Architects

Appendix C: References

- 1. Principles of Tree Hazard Assessment and Management, Lonsdale, D. (Department for Transport, Local Government and the Regions, 1999)
- 2. The Body Language of Trees, Mattheck, C. and Breloer, H. (HMSO, 1994)
- 3. Trees in Britain, Philips, R. (Pan Books, 1978).
- 4. Diagnosis of III Health in Trees, Strouts, R. and Winter, (TSO, 1994)
- 5. NHBC, Chapter 4.3 Building near Trees (2021)

END OF REPORT PREPARED BY Marcus Foster MArbora

Tree Survey Report - Reference: AR/MF/0131/23 Site: 12A Lancaster Grove, London, NW3 4NX

Prepared for: LBMV Architects