

## Cumberland Terrace (No. of Trees: 43)

Tree No (old tag)	Vegetation type	Species	No. of stems	Height (m)	Crown spread	DBH (cm)	Life stage	Vitality	Physiological Condition	Structural Condition	Safe Life Expectancy	Access	CAVAT value (£)/ Crown area (m2)
T240 (130)	Tree	1 Prunus cerasifera 'Pissardii' Pissard's Plum	1	9.0	8.5	34	Mature	Low	Fair	Fair	10-20 yrs	Fair	£17265.22 / 56.74m2
Site Features	Targets		Conditions				Notes					Survey date/ Surveyor	
	Footpath within falling distance of tree. Seating area within falling distance of tree.		Base / stems obscured - Vegetation. Buttresses / buttress roots - Minor adaptive growth / moderate development. Die-back - Mid crown. Deadwood - Major. Decay / structural defect - Minor. Decay / structural defect - Bole. Epicormic growth - Crown. Epicormic growth - Base / bole / principal stems. Fork - Weak with included bark. Girdling roots - Minor. Rubbing limbs. Stems - Co-dominant.				Decay fungi - Stereum sp. on pruning wounds. Crown - Significant dieback observed in crown. See media. 11.07.23. Visibility of the base and lower stem is inhibited due to dense shrubs.W3W: 240					2024-08-08. /Matthew Barker.	
Recommendation	<b>- Remove faulted limb / limbs heavily declining limb to the east at 2.5 m back to live upright mature epicormic stem 1.5 m out from the main stem union. Also remove any further deadwood throughout crown.</b>						Purpose of works		<b>- Appropriate</b>		Safety Action Date		
Risk assessed	Branch failure on to other target(s)						Risk of harm range		1/10 000 - 1/1 000 000		Risk category		1
Tree No (old tag)	Vegetation type	Species	No. of stems	Height (m)	Crown spread	DBH (cm)	Life stage	Vitality	Physiological Condition	Structural Condition	Safe Life Expectancy	Access	CAVAT value (£)/ Crown area (m2)
T240 (130)	Tree	1 Prunus cerasifera 'Pissardii' Pissard's Plum	1	9.0	8.5	34	Mature	Low	Fair	Fair	10-20 yrs	Fair	£17265.22 / 56.74m2

Cumberland Terrace (No. of Trees: null)

Site Features	Targets	Conditions	Notes			Survey date/ Surveyor
	Footpath within falling distance of tree. Seating area within falling distance of tree.	Base / stems obscured - Vegetation. Buttresses / buttress roots - Minor adaptive growth / moderate development. Die-back - Mid crown. Deadwood - Major. Decay / structural defect - Minor. Decay / structural defect - Bole. Epicormic growth - Crown. Epicormic growth - Base / bole / principal stems. Fork - Weak with included bark. Girdling roots - Minor. Rubbing limbs. Stems - Co-dominant.	Decay fungi - Stereum sp. on pruning wounds. Crown - Significant dieback observed in crown. See media. 11.07.23. Visibility of the base and lower stem is inhibited due to dense shrubs.W3W: 240			2024-08-08. /Matthew Barker.
Recommendation	<b>- Remove faulted limb / limbs heavily declining limb to the east at 2.5 m back to live upright mature epicormic stem 1.5 m out from the main stem union. Also remove any further deadwood throughout crown.</b>		Purpose of works	- <i>Appropriate</i>	Safety Action Date	
Risk assessed	Branch failure on to other target(s)		Risk of harm range	1/10 000 - 1/1 000 000	Risk category	1

## Cumberland Terrace (No. of Trees: 43)

Tree No (old tag)	Vegetation type	Species	No. of stems	Height (m)	Crown spread	DBH (cm)	Life stage	Vitality	Physiological Condition	Structural Condition	Safe Life Expectancy	Access	CAVAT value (£)/ Crown area (m2)
T244 (125)	Tree	1 Malus sp. Apple sp.	1	6.5	6.0	15	Mature	Low	Poor	Fair	<5 yrs	Fair	£610.99 / 28.27m2
Site Features	Targets		Conditions				Notes					Survey date/ Surveyor	
	Footpath within falling distance of tree. Seating area within falling distance of tree.		Base / stems obscured - Vegetation. Buttresses / buttress roots - Minor adaptive growth / moderate development. Decay / structural defect in crown limb / limbs - Localised. Deadwood - Minor. Decay / structural defect - Base. Decay / structural defect - Bole. Epicormic growth - Base. Pruning wounds - Decayed. Suppressed crown - Minor. Twin-stemmed. Unbalanced crown - Minor.				Crown - Dieback of most lower limbs reminiscent of fireblight.W3W: 244					2024-08-08. /Matthew Barker.	
Recommendation	<b>- Remove faulted limb / limbs (suspected fireblight) removing all dead and declining lower limbs and shoots to facilitate more detailed monitoring of crown health. All arisings should be contained and disposed of in a suitable manner and location for fireblight infected materials.</b>						Purpose of works	<b>- Necessary</b>			Safety Action Date		
Risk assessed							Risk of harm range				Risk category	1	

Tree No (old tag)	Vegetation type	Species	No. of stems	Height (m)	Crown spread	DBH (cm)	Life stage	Vitality	Physiological Condition	Structural Condition	Safe Life Expectancy	Access	CAVAT value (£)/ Crown area (m2)
T244 (125)	Tree	1 Malus sp. Apple sp.	1	6.5	6.0	15	Mature	Low	Poor	Fair	<5 yrs	Fair	£610.99 / 28.27m2
Site Features	Targets		Conditions				Notes					Survey date/ Surveyor	
	Footpath within falling distance of tree. Seating area within falling distance of tree.		Base / stems obscured - Vegetation. Buttresses / buttress roots - Minor adaptive growth / moderate development. Decay / structural defect in crown limb / limbs - Localised. Deadwood - Minor. Decay / structural defect - Base. Decay / structural defect - Bole. Epicormic growth - Base. Pruning wounds - Decayed. Suppressed crown - Minor. Twin-stemmed. Unbalanced crown - Minor.				Crown - Dieback of most lower limbs reminiscent of fireblight.W3W: 244					2024-08-08. /Matthew Barker.	

Cumberland Terrace (No. of Trees: null)

Recommendation	- Remove faulted limb / limbs (suspected fireblight) removing all dead and declining lower limbs and shoots to facilitate more detailed monitoring of crown health. All arisings should be contained and disposed of in a suitable manner and location for fireblight infected materials.	Purpose of works	- Necessary	Safety Action Date	
Risk assessed		Risk of harm range		Risk category	1

Cumberland Terrace (No. of Trees: 43)

Tree No (old tag)	Vegetation type	Species	No. of stems	Height (m)	Crown spread	DBH (cm)	Life stage	Vitality	Physiological Condition	Structural Condition	Safe Life Expectancy	Access	CAVAT value (£)/ Crown area (m2)
T268 (T6)	Tree	1 Platanus x hispanica London Plane	1	16.0	18.5	68	Mature	Moderate	Fair	Fair	20-40 yrs	Fair	£100452.21 / 268.80m2
Site Features	Targets		Conditions				Notes					Survey date/ Surveyor	
Grass.	Footpath within crown spread. Road within falling distance of tree. Main drive within or adjacent to canopy. Seating area within falling distance of tree. Street lamp within crown spread. Car parking within falling distance of tree.		Base / stems obscured - Vegetation. Branch weight - Heavy. Branch - Suspended. Buttresses / buttress roots - Major adaptive growth / strong development. Deadwood - Minor. Fork - Suspected structurally sound. Form - Large sail area / crown extent. Leaning trunk - Minor. Pruning wounds - Historic. Root damage - Mower. Raised surface roots. Stems - Co-dominant.				Jelly ear fungus fruiting on lowest pruning wound on stem. Currently not structurally significant. Deadwood - Small dead Massaria twigs attached and suspended, risk assessed as minimal. Pest & Disease - Minor anthracnose damage to foliage.W3W: 268					2024-08-08. /Matthew Barker.	
Recommendation	<b>- Prune from adjacent structure to clear lamp column by 1.5 m also lightly tip prune low hanging branches to the east overhanging and encroaching upon the driveway to maintain a clearance of 4 m.</b>						Purpose of works		<b>- To manage nuisance</b>		Safety Action Date		
Risk assessed	Branch failure on to footpath						Risk of harm range		<1/1 000 000		Risk category	1	

Tree No (old tag)	Vegetation type	Species	No. of stems	Height (m)	Crown spread	DBH (cm)	Life stage	Vitality	Physiological Condition	Structural Condition	Safe Life Expectancy	Access	CAVAT value (£)/ Crown area (m2)
T268 (T6)	Tree	1 Platanus x hispanica London Plane	1	16.0	18.5	68	Mature	Moderate	Fair	Fair	20-40 yrs	Fair	£100452.21 / 268.80m2
Site Features	Targets		Conditions			Notes							Survey date/ Surveyor
Grass.	Footpath within crown spread. Road within falling distance of tree. Main drive within or adjacent to canopy. Seating area within falling distance of tree. Street lamp within crown spread. Car parking within falling distance of tree.		Base / stems obscured - Vegetation. Branch weight - Heavy. Branch - Suspended. Buttresses / buttress roots - Major adaptive growth / strong development. Deadwood - Minor. Fork - Suspected structurally sound. Form - Large sail area / crown extent. Leaning trunk - Minor. Pruning wounds - Historic. Root damage - Mower. Raised surface roots. Stems - Co-dominant.			Jelly ear fungus fruiting on lowest pruning wound on stem. Currently not structurally significant. Deadwood - Small dead Massaria twigs attached and suspended, risk assessed as minimal. Pest & Disease - Minor anthracnose damage to foliage.W3W: 268							2024-08-08. /Matthew Barker.
Recommendation	<b>- Prune from adjacent structure to clear lamp column by 1.5 m also lightly tip prune low hanging branches to the east overhanging and encroaching upon the driveway to maintain a clearance of 4 m.</b>						Purpose of works		<b>- To manage nuisance</b>		Safety Action Date		

Cumberland Terrace (No. of Trees: null)

Risk assessed	Branch failure on to footpath	Risk of harm range	<1/1 000 000	Risk category	1
---------------	-------------------------------	--------------------	--------------	---------------	---