

Site Investigation Report

Auger Ref:

176136.1.2.BSI



Job Information

Client	Structural Surveys Ltd
Client ref	QG1S1287571
Visit date	07/11/2024
Report date	29/11/2024

Job Summary

- ✓ CCTV survey undertaken. [Read more.](#)
- ! Drainage repairs required. [Read more.](#)
- ! Trial Hole depth not reached. [Read more.](#)



Job Information

Overview

Brief

Auger were commissioned by Structural Surveys Ltd to undertake a site investigation and CCTV inspection of the underground drainage within the area of concern (AOC) at the property.

Findings

Trial Hole Findings

Trial Hole 1

Within TH1 we revealed the footing but we were unable to reach the required depth in TH1 because we encountered rocky ground which our engineer could not auger through at 1.4m. The Trial Hole was excavated in the proposed location. We took soil and root samples. These measurements are shown in Trial Hole Log 1 below.

Trial Hole 2

Within TH2 we revealed the footing but we were unable to reach the required depth in TH2 because we encountered rocky ground which our engineer could not auger through at 1.4m. The Trial Hole was excavated in the proposed location. We took soil and root samples. These measurements are shown in Trial Hole Log 2 below.

Aborted Trial Hole

The proposed trial hole at the front of the property was to gain the footing of the main house and the bay window, however upon attending site we found a large amount of vegetation preventing access, we also found there is a cellar in the area.

If the loss adjuster wishes for the trial hole in this location a specialist should remove large amounts of vegetation and 2 men can return to excavate a deep trial hole in the area,

Drain Survey

We carried out a CCTV survey of the below ground drainage system, our findings of which are as follows:

Line 1 - From MH1 upstream to WG1

Our survey of line 1 revealed root ingress and the WG connection bossed into the main line restricting flow and allowing an escape of water, we have therefore been unable to survey upstream on the main line.

Line 2 - From MH1 upstream to RWG1

Our survey of line 2 revealed root ingress to the cast iron pipework 5m upstream to the gully. The survey also revealed broken pipework directly upstream of MH1

Line 3 - From MH1 downstream to MH2

Our survey of line 3 revealed no significant defects to the pipework on this line which could be allowing an escape of water. This pipework has previously been lined.

We found MH2 was holding water, extensive jetting was successful in clearing the main trap and also revealed the rodding cap stuck in the line prevent flow which we have now removed, there is a connection within the MH we have been unable to survey due the MH being 1.7m deep, this line runs to a WC internally.

Recommendations

<p>Refer Back to Client</p>	<p>It is recommended that the following repairs are carried out to prevent an escape of water from the system:</p> <p>Line 1 Excavate and replace WG1 and 1m of 100mm pipework including a branch connection at a depth no greater than 1.0m through concrete.</p> <p>Install a 100mm patch directly upstream of MH1 to the branch.</p> <p>We will then need to conduct a further CCTV investigation upstream on this line.</p> <p>Line 2 Excavate and replace RWG1 and 3m of 100mm pipework at a depth no greater than 1.0m through concrete.</p> <p>Install a 100mm patch liner directly upstream of MH1 to seal the pipework into the cast iron.</p> <p>MH2 Deep MH entry required to survey the connection.</p> <p>Please note that the further CCTV investigation may reveal additional defects to the drainage system. This will be reported whilst on-site and could potentially cause an increase in repair costs and provide further inconvenience to the customer/occupants.</p> <p>Auger have not allowed or will not be held responsible for any alteration or modification to the above ground drainage following the removal of the existing gully and reinstatement of a new gully. The customer must ensure that the above ground drainage correctly expels into the gully pot and avoids overcrowding the gully with numerous downpipes which could lead to the gully overflowing.</p> <p>During the clean-up/reinstatement process we will endeavour to leave the area we are working in clean and tidy and as close to how we found it as possible. There will always be an element of general debris/mud/waste that will build up in the area which cannot be prevented. There may however be elements of this process that are outside our remit i.e., Repainting or cleaning. If this is the case, then we will need to speak to the customer's insurers to help in this regard.</p> <p>We will now refer the claim back to the client in order to progress the claim.</p>
<p>Repair Caveats</p>	<p><i>Once repairs have been undertaken the customer should ensure the drainage system is periodically inspected in the future for any deterioration and kept free flowing / free of blockages. Any damage noted during future inspections should be repaired immediately in accordance with current Building Regulations.</i></p> <p><i>With any repair process, complications and unforeseen circumstances can arise. These scenarios will be reported whilst on-site and could potentially cause an increase in repair costs and inconvenience.</i></p> <p><i>Where any excavation reinstatement of the surface is required, the reinstatement will always attempt to match the previous surface patterns and colouring, however we cannot guarantee an exact match.</i></p> <p><i>If any of the above lining recommendations fail then excavation and replacement of the pipework would be required. This would severely increase the cost of repairs and would provide greater inconvenience to the residents. The relining of a severe joint displacement is normally unadvised due to the potential for complications in the future.</i></p> <p><i>Recommendations have been made to reline or patch reline sections of the drainage system at the property. This process combines a number of chemicals in a resin, which then harden in a fibreglass matting to create a new section of drain within the original. The reaction creates a strong smell which can linger for up to 72 hours once works are completed - this is not harmful. It is recommended that any areas where smells are experienced are kept well ventilated until the odour subsides.</i></p> <p><i>The above recommendations allow for the replacement of gullies & connected underground drainage only. The insured should be made aware that the aesthetic appearance of this gully may be different from what is currently in place.</i></p>

Photographs

Trial Hole 1

Fig 1.1: Trial Hole 1 Location



Fig 1.2: Trial Hole 1 Footing



Trial Hole 2

Fig 2.1: Trial Hole 2 Location



Fig 2.2: Trial Hole 2 Footing



CCTV Stills

Fig 3.1: Root ingress and bossed in connection



Site Photos

Fig 4.1: Rear of the property



Fig 4.2: Vegetation in the proposed area of trial hole



Fig 4.3: Vegetation to be removed




Fig 4.4: MH2 blocked, now clear


























Fig 4.5: MH1





This drawing should be used for diagrammatic purposes only. Auger are not responsible or liable for any 3rd party works undertaken using the details outlined in this drawing. Confirmation of the drainage configuration can only be confirmed by excavation or detailed technical survey.

LEGEND


				
				
				
				
				



Trial Hole Log No.1

Location: Rhs rear corner of extension

Job Ref:
176136.1.2.BSI


Depth (m)	Symbolic Log	Strata Description	Insitu Tests		Soil Sample	Root Sample
			SV(19)			
0.0		Ground Level				
		Concrete				
		Brickwork				
		Double Step				
0.5		Moist Brown fine to medium gravelly silty CLAY	74kpa		Soil @ 0.5m	Root @ 0.5m
1.0		Very dry Brown fine to medium gravelly silty CLAY	140kpa		Soil @ 1m	Root @ 1m
1.5		TRIAL HOLE TERMINATED				



Trial Hole Log No.2

Location: Rear left corner of extension

Job Ref:
176136.1.2.BSI

Depth (m)	Symbolic Log	Strata Description	Insitu Tests		Soil Sample	Root Sample
			SV(19)			
0.0		Ground Level				
		Concrete				
		Brickwork				
		Double Step				
0.5		Moist Brown fine to medium gravelly silty CLAY	82kpa		Soil @ 0.5m	Root @ 0.5m
1.0		Very dry Brown fine to medium gravelly silty CLAY	140kpa		Soil @ 1m	Root @ 1m
1.5		TRIAL HOLE TERMINATED				

Unit 3 & 4,
 Heol Aur,
 Dafen Ind Estate,
 Dafen
 Llanelli,
 Carmarthenshire,
 SA14 8QN

***The testing results contained within this report have been performed by GSTL a UKAS accredited laboratory on behalf of Auger.**

**Auger House,
 Cross Lane,
 Wallasey,
 Wirral,
 CH45 8RH**

Summary Of Claim Details

Policy Holder

GSTL Job Reference

75802

SI Date

Issue Date

Report Date

19/11/2024

Auger Reference

176136.1.4.RSS

Insurance Company

Folgate Insurance

LA Claim Reference

QG1S1287571

LA Co. Reference


Structural Surveys Ltd

This certificate is issued in accordance with the accreditation requirements of the United Kingdom Accreditation Service. The results reported herein relate only to the material supplied to the laboratory. This certificate shall not be reproduced except in full, without the prior written approval of the laboratory.


Checked and approved

19/11/2024

R.John



PLASTICITY CHART FOR CASAGRANDE CLASSIFICATION
BS 5930:1999+A2:2010



Modified Plasticity Index (PI) <10 : Non Classified
 Modified PI = 10 to <20 : Low volume change potential (LOW VCP)
 Modified PI = 20 to <40 : Medium volume change potential (Med VCP)
 Modified PI = 40 or greater : High volume change potential (HIGH VCP)

The Atterberg Limits May also be used to classify the volume change potential of fine soils using the National House building system, as given in the NHBC's Standards Chapter 4.2 (2003) "Building Near Trees"

Test Operator

Jason Smith


GSTL Contract Number	75802	
Report Date	19/11/2024	
Auger Reference	176136.1.4.RSS	
Remarks	D - Disturbed (Recompacted 2.5kg Rammer), U - Undisturbed Sample	

TH Trial Hole	Depth (m)	Filter Paper Location	Filter Paper	Sample Prep Method	Test Duration (Days)	Water Content (%)	Soil Suction Pk (kPa)	Average Soil Suction Pk (kPa)	Cumulative Heave Potential (mm) from bottom of the hole
TH1	0.50	Top	I	D	5	44.5	119	117	23
TH1		Middle	II	D	5	44.6	117		
TH1		Bottom	III	D	5	44.7	115		
TH1	1.00	Top	I	D	5	29.9	958	951	17
TH1		Middle	II	D	5	29.9	951		
TH1		Bottom	III	D	5	30.0	945		

Heave potential is calculated from the bottom of the hole and heaves above the bottom of the hole are reported as a cumulative value.

The values reported for heave above only apply to the strata the suction and plasticity have been performed on. The shallowest depth reported is assumed to be a strata thickness to GL and Heave is calculated based on that layer thickness, if the next sample is in 0.5m increments the heave is calculated based on the layer thickness of 0.5m and depths 1m from the sample above will include heave over 1m.

Consideration should be made for other stratas where values are not reported and when working out the heave potential over the entire trial hole.



Test Operator
Jason Smith


GSTL Contract Number	75802	
Report Date	19/11/2024	
Auger Reference	176136.1.4.RSS	
Remarks	D - Disturbed (Recompacted 2.5kg Rammer), U - Undisturbed Sample	

TH Trial Hole	Depth (m)	Filter Paper Location	Filter Paper	Sample Prep Method	Test Duration (Days)	Water Content (%)	Soil Suction Pk (kPa)	Average Soil Suction Pk (kPa)	Cumalative Heave Potential (mm) from bottom of the hole
TH2	0.50	Top	I	D	5	75.4	25	24.6	22
TH2	0.50	Middle	II	D	5	75.7	25		
TH2	0.50	Bottom	III	D	5	75.9	24		
TH2	1.00	Top	I	D	5	30.6	868	861	22
TH2	1.00	Middle	II	D	5	30.6	861		
TH2	1.00	Bottom	III	D	5	30.7	854		

Heave potential is calculated from the bottom of the hole and heaves above the bottom of the hole are reported as a cumulative value.

The values reported for heave above only apply to the strata the suction and plasticity have been performed on. The shallowest depth reported is assumed to be a strata thickness to GL and Heave is calculated based on that layer thickness, if the next sample is in 0.5m increments the heave is calculated based on the layer thickness of 0.5m and depths 1m from the sample above will include heave over 1m.

Consideration should be made for other stratas where values are not reported and when working out the heave potential over the entire trial hole.



Test Operator
Jason Smith



Richardson's Botanical Identifications

Root identification
Vegetation surveys
Tree/Building investigations
Plant taxonomy

Dr Ian B K Richardson
BSc, MSc, PhD, MRSB, FLS
James Richardson
BSc (Hons. Biology)

Auger Solutions

Auger House

Cross Lane

WALLASEY

Wirral CH45 8RH

Enterprise House
49-51 Whiteknights Road
Reading
RG6 7BB

22/11/2024

Your ref: 176136-1-3

Our ref: 89/0309

Dear Sirs

Root ID

The samples you sent in relation to the above on 07/11/2024 have been examined. Their structures were referable as follows:

TH1, 0.5m		
2 no.	Examined root: the family SALICACEAE (Salix (Willows) and Populus (Poplars)).	Alive, recently*.
1 no.	Examined root: a SHRUB. We cannot rule out BUDDLEJA (bushes, sometimes large, with spikes consisting of tiny pink, white or blue scented flowers) - or - ARBUTUS (includes 'Strawberry tree' - large evergreen shrubs/small trees with tiny bell-shaped flowers and strawberry-like fruits that appear in Autumn). Slightly tentative.	Alive, recently*.
5 no.	Unfortunately all with insufficient cells for identification.	
TH1, 1.0m		
3 no.	Examined root: the family SALICACEAE (as listed above).	Alive, recently*.
2 no.	Both samples revealed too few cells for microscopic identification.	
TH2, 0.5m		
4 no.	Examined root: the family SALICACEAE (as listed above).	Alive, recently*.
1 no.	Examined root: FRAXINUS (Ash).	Alive, recently*.
TH2, 1.0m		
3 no.	Examined root: the family SALICACEAE (as listed above).	Alive, recently*.
2 no.	Both samples revealed too few cells for microscopic identification.	

Click here for more information: [FRAXINUS](#) [SALICACEAE](#)

I trust this is of help. Please call us if you have any queries; our Invoice is enclosed.

Yours faithfully

Dr Ian B K Richardson

* Based mainly on the Iodine test for starch. Starch is present in some cells of a living woody root, but is more or less rapidly broken down by soil micro-organisms on death of the root, sometimes before decay is evident. This result need not reflect the state of the parent tree.

Identified with no information on vegetation, on or off site.