

Broad Oak Tree Consultants Limited

Laurel House, Burwash Road, Broad Oak, Heathfield, East Sussex TN21 8SS Tel: 01435 862444 Email: broadoaktrees@btconnect.com

> REPORT ON INSPECTION OF LIME TREE

> > AT

96 SOUTH HILL PARK LONDON NW3

ΒY

Tim Laddiman BSc.(Hons) M.I.C.For. M.Arbor.A. Chartered Arboriculturist

> Our ref: J43.20 6th April 2011

CONTENTS

Page No.

1.	INTRODUCTION	1
2.	TREE LOCATION	1
3.	DATA COLLECTION	1
4.	RISK ASSESSMENT - INFORMATIVES	2
5.	RESULTS OF TREE INSPECTIONS	2
6.	BS CALCULATED ROOT PROTECTION AREAS (RPAs)	3
7.	SUMMARY	3

APPENDICES:

- EXPLANATORY SHEETS, TREE INSPECTION SHEET TREE CONSTRAINTS PLAN, DRAWING NO. J43.20/01 1.
- 2.

1. INTRODUCTION

- 1.1 Broad Oak Tree Consultants Ltd. have received instructions from Smith Lam Architects Ltd. to undertake an inspection of a lime tree located at No. 96 South Hill Park, London, NW3. The purpose of the inspection was to produce a base inventory of the tree, advise on any safety issues, calculate BS root protection area and produce a Tree Constraints Plan that can be used for advising potential development layouts.
- 1.2 At the time of reporting it is understood that the tree stands in the South Hill Park Conservation Area and is covered by Tree Preservation Order No. 105, 1983.

2. TREE LOCATION

2.1 The lime tree is situated in the rear garden of No. 96 South Hill Park, being the left hand end of a terrace of properties that back onto a lake. The properties are built into ground that slopes down significantly from front to rear. To the immediate left of the garden is a tarmac surfaced alley leading into the park beyond. The boundary with the garden is marked by a large brick wall, within which is set an access gate to the rear garden. Growing against this brick wall within the rear garden 2.7m across from the rear wall of the building is a mature lime tree, the subject of this report.

3. DATA COLLECTION

- 3.1 The lime tree was inspected from the ground and no climbing or specialist investigations were undertaken. The lime tree was inspected to the requirements of Section 4.2.6 of BS 5837:2005 "Trees in Relation to Construction Recommendations".
- 3.2 The tree survey includes only one tree, no. 1, lime. This tree number, together with BS recommended colour coding of condition, has been added to the Tree Constraints Plan, our drawing no. J43.20/01 in Appendix 2. This drawing also includes its crown spread based on four compass points and BS calculated root protection area.
- 3.3 The following categories of information were obtained for the tree. A separate detailed tree survey sheet is attached in Appendix 1, together with comprehensive explanatory sheets which cover the details of the categories listed below.
 - (1) Tree reference number
 - (2) Species
 - (3) Height in metres
 - (4) Stem count
 - (5) Stem diameter in millimetres
 - (6) Branch spread in metres
 - (7) Age class
 - (8) Height of crown clearance in metres
 - (9) Physiological condition
 - (10) Estimated remaining contribution in years
 - (11) Category grading
 - (12) Structural condition
 - (13) Preliminary management recommendations

3.4 Within the assessment of physiological condition and remaining contribution, a visual inspection of the lime tree was undertaken to assess the crown and stem for any weak structures, deadwood, hollows, forks or other defects that might affect its stability and safety. The base of the tree was also visually inspected, together with tapping and probing, to search for signs of root lifting, bark death or decay.

4. RISK ASSESSMENT - INFORMATIVES

- 4.1 Although the potential risk to someone passing beneath the lime tree when the tree or part of it fails is relatively remote, the risk is present. This increases significantly in areas of consistent and regular usage on a year round basis, such as footpaths, gardens and roadways. Where static structures exist, the risks become constant and an assessment is made as to whether complete or partial failure of the tree could potentially cause physical damage to such structures.
- 4.2 Within the scope of any tree survey it is a fact that not all risks of stem or crown failure can be covered, particularly in relation to freak occurrences of weather when even healthy trees can suffer stem snap or windblow. There is also a well known propensity for mature trees to occasionally shed limbs for no discernible reason, even on calm days. Although relatively rare, limbs may occasionally be shed and this should be acknowledged as a risk that cannot entirely be mitigated.

5. **RESULTS OF TREE INSPECTIONS**

- 5.1 The lime tree has been classified as BS category B retention desirable, with a useful lifespan/contribution of between 20-40 years. The tree has visual landscape amenity though is located too close to the houses for such a large growing specimen. Consequently much of its crown is developed out to the south west over the alley and adjoining rear garden.
- 5.2 Within the last two years the crown of the tree has been reduced and epicormic shoots removed from the stem and internal branch structure. Rapid regrowth has occurred from all cut points and outer shoots are close to touching walls/roofs.
- 5.3 The tree has several potentially weak compression stem unions which can represent a risk of failure, particularly where stems are leaning out with an offset centre of gravity. The recent crown reduction works will have reduced loading on the stems and regular recutting will be necessary for this reason and to avoid possible damage to roof structures. Consideration should be given to loose cable bracing the stems together at height using a "Cobra" or similar system to minimise risks of stem failures occurring.
- 5.4 A previous report prepared by CBA Trees in September 2007 refers to part of the wall adjacent to the lime tree having collapsed and been replaced with fencing and to the area around the tree being paved.
- 5.5 At the time of inspecting the lime tree the brick wall has been rebuilt, with the brickwork touching the stem. This could in future damage the stem as it continues to expand or cause further lateral pressure to the wall and damage. To the west of the tree a new gate with pillars has been built into the wall, together with a low brick built store. Around the base of the tree the ground is now loose gravel.

6. BS CALCULATED ROOT PROTECTION AREAS (RPAs)

6.1 The table below has been calculated using the measured stem diameter and the formula in Table 2 "Calculating the RPA" in BS 5837:2005. This is represented as a basic circle on the Tree Constraints Plan. Where buildings, walls, services and hard surfacing exist within the indicated RPA it is likely that the architecture of the root system will have been affected. Foundations to walls and buildings can completely obstruct root development, depending on their depth and the nature of the underlying soils. In the absence of detailed site investigations the indicated RPA circle should be used for guidance only within any redevelopment proposals.

Tree no.	Species	BS Category	BS calc. radial equiv. root protection area (m.)	BS calc. total RPA (m²)
1	Lime	В	7.2	162.9

7. SUMMARY

- 7.1 The lime tree is in reasonable health and growth response to recent tree surgery is good. There are structural weaknesses in stem joins and regular pruning and/or loose cable bracing of stems at height will be required.
- 7.2 The Constraints Plan provides guidance on the potential rooting area of the tree though existing constraints means that much of the rooting area may have extended into the open garden to the west. Any open areas of ground around the building footprint and within the rear garden will be important areas to protect within any potential redevelopment if the tree is to be safely retained.

Tim Laddiman Chartered Arboriculturist Broad Oak Tree Consultants Ltd.

APPENDIX 1

TREE SURVEY EXPLANATORY SHEET

in metres (estimated where ground uneven or access

Height

restricted). Stem count number of stems Stem diameter in mm. at 1.5m. above ground level. Above Root Flare – diameter of multi-stemmed trees (ARF) measured at this level. Branch spread radial spread in metres at four main compass points (estimated where no access). Age class Young Υ -Middle aged -MA Mature -Μ Over mature -OM Veteran -V Height of crown in metres. Normally range of heights of outer branches clearance above ground level, e.g. 2-4m. Physiological condition Good, Fair, Poor, Dead Estimated remaining in years contribution e.g. less than 10, 10-20, 20-40, 40+ Category grading see attached sheet Structural condition comment on presence of defects, decay, crown form, past management, deadwood, other features worthy of note. N.B. If trees are ivy clad, no full structural assessment will have been possible. requirements of further investigations, works necessary to Preliminary management alleviate potential hazards based on current setting and recommendations levels of access. NB: Works that may be necessary in relation to development are not included here


CASCADE CHART FOR TREE QUALITY ASSESSMENT

		TREES FOR REMOVAL		
Category and definition		Identification on plan		
Category R Those in such a condition that any existing value would be lost within 10 years and which should, in the current context, be removed for reasons of sound arboricultural management	 Trees that have a serious, irremedi that will become unviable after removal cannot be mitigated by pruning) Trees that are dead or are showing Trees infected with pathogens of si low quality trees suppressing adjacent NOTE Habitat reinstatement may be 	DARK RED		
	TREES			
		Criteria - Subcategories		
Category and definition	1. Mainly arboricultural values	3. Mainly cultural values, including conservation	Identification on plan	
Category A Those of high quality and value: in such a condition as to be able to make a substantial contribution (a minimum of 40 years is suggested)	Trees that are particularly good examples of their species, especially if rare or unusual, or essential components of groups, or of formal or semi-formal arboricultural features (e.g. the dominant and/or principal trees within an avenue)	Trees, groups or woodlands which provide a definite screening or softening effect to the locality in relation to views into or out of the site, or those of particular visual importance (e.g. avenues or other arboricultural features assessed as groups)	Trees, groups or woodlands of significant conservation, historical, commemorative or other value (e.g. veteran trees or wood-pasture)	LIGHT GREEN
Category B Those of moderate quality and value: those in such a condition as to make a significant contribution (a minimum of 20 years is suggested)	Trees that might be included in the high category, but are downgraded because of impaired condition (e.g. presence of remediable defects including unsympathetic past management and minor storm damage)	Trees present in numbers, usually as groups or woodland, such that they form distinct landscape features, thereby attracting a higher collective rating than they might as individuals but which are not, individually, essential components of formal or semi-formal arboricultural features (e.g. trees of moderate quality within an avenue that includes better, A category specimens), or trees situated mainly internally to the site, therefore individually having little visual impact on the wider locality	Trees with clearly identifiable conservation or other cultural benefits	MID BLUE
Category C Those of low quality and value: currently in adequate condition to remain until new planting could be established (a minimum of 10 years is suggested), or	Trees not qualifying in higher categories	Trees present in groups or woodland, but without this conferring on them significantly greater landscape value, and/or trees offering low or only temporary screening benefit.	Trees with very limited conservation or other cultural benefits	GREY
young trees with a stem diameter below 150mm.	NOTE Whilst C category trees will usu trees with a stem diameter of less than			

Tree		11-1-1-4	01	Stem	Br	anch sp	oread (I	m.)		Ht. of crown		Estimated remaining	0-1-			Preliminary
ref.	. .	Height	Stem	diameter		-	_		Age	clearance	Physiological	contribution	Cate			management
no.	Species	(m.)	count	(mm.)	N	E	S	W	class	(m.)	condition	(years)	grad	ling	Structural condition	recommendations
															Twin stemmed at 2.6m with	
															weak compression join.	
															Becomes four stems at c.4.5-	
															5m with weak unions. Main	
															crown structure to W. Crown	
															reduced in past two years with	
															vigorous regrowth. Epicormic	
															shoots on lower stem from 2m	bracing stems
															to 6m and up into main branch	together at
1	Lime	14	1	600	3.5	2	5	5	М	2+	Fair	20-40	В	1	structure	height

APPENDIX 2

Actual rooting zone likely to be constrained by wall and building foundations and possible extension of area into open garden to west.



Brond Oct Tree Consultants to Brand Note Partial State Ti Tree number I Tree number I I Tree number I S Category of Condition A I I BS Co BS Co BS Co BS Co BS Condition B Co BS Condition B Co BS Condition C Co
