Table 1 Damage Categories after Burland (1995)

Category of damage	Limiting tensile strain	Normal degree of severity	Description of typical damage (Ease of repair is printed <i>italit</i>) Note: Crack width is only one factor in assessing category of damage and should not be used on its own as a direct measure of it
0	0-0.05	Negligible	Hairline cracks less than about 0.1 mm
1	0.05-0.075	Very slight	Fine cracks which are easily treated during normal decoration. Damage generally restricted to internal wall finishes. Close inspection may reveal some cracks in external brickworks or masonry. Typical crack widths up to 1mm.
2	0.075-0.15	Slight	Cracks easily filled. Re-decoration probably required. Recurrent cracks can be masked by suitable linings. Cracks may be visible externally and some repointing may be required to ensure weathertightness. Doors and windows may stick slightly. Typical crack width up to 5 mm.
3	0.15-0.3	Moderate ¹	The cracks require some opening up and can be patched by mason. Repointing of external brickwork and possibly a small amount of brickwork to be replaced. Doors and windows sticking. Service pipes may fracture. Weathertightness often impaired. Typical crack widths are 5 to 15 mm or several up to 3 mm.
4	>0.3	Severe	Extensive repair work involving breaking-out and replacing sections of walls, especially over doors and windows. Windows and door frames distorted, floor sloping noticeably ² . Walls leaning2 or bulging noticeably, some loss of bearing in beams. Service pipes disrupted. Typical crack widths are 15 to 25 mm but also depends on the number of cracks.
5		Very severe	This requires a major repair job involving partial or complete rebuilding. Beams lose bearing, walls lean badly and require shoring. Windows broken with distortion. Danger of instability. Typical crack widths are greater than 25 mm but depends on the number of cracks.

¹ Note: Boscardin & Cording (1989) describe the damage corresponding to the tensile strain in the range 0.015 - 0.3%. as 'moderate to severe'. However, none of the cases quoted by them exhibit severe damage for this range of strains. There is therefore no evidence to suggest that tensile strains up to 0.3% will result in severe damage.

² Note: Local deviation of slope, from the horizontal or vertical, of more than 1/100 will normally be clearly visible. Overall deviations in excess of 1/150 are undesirable.



New College Parade-PL Damage Categories after Burland

1 message

"New College Parade 1235"

Tue, Jun 24, 2014 at 10:36

AM

<newcollegeparade1235@davysmitharchitects.co.uk>
To: Eimear.Heavey@camden.gov.uk

Cc: Bethany.Arbery@camden.gov.uk

Bcc: New College Parade 1235 < newcollegeparade 1235@davysmitharchitects.co.uk >, Jamie Arva < jamiea@koopmans.co.uk >

Dear Eimear

New College Parade - Damage Categories after Burland

As requested, would you please find attached the 'Damage Categories after Burland' and below email from Conisbee for your information.

Regards

Peter Smith

stephen davy architects peter smith

Stephen Davy Peter Smith Architects Ltd

Fanshaw House, Fanshaw Street, London N1 6HX T: 020 7739 2020 W: www.davysmitharchitects.co.uk

Company Registration no: 3883463

SDPSA Ltd is a registered ISO 9001 & ISO 14001 company and has Exor & Constructionline accreditation

THINK GREEN - please do not print this email unless you really need to

This email and any attached files are confidential. If you are not the intended recipient, please notify the sender immediately by replying to this e-mail and delete this email and any attachments from your computer and network. Any unauthorised copying, disclosure or distribution of the material in this email is strictly forbidden. Stephen Davy Peter Smith Architects Ltd (SDPSA) cannot accept responsibility for the accuracy or completeness of this message as it has been transmitted over a public network. In particular, SDPSA does not accept responsibility for changes made to this email or any attached files after they were sent. The contents may contain personal views and opinions, which are not the views of SDPSA unless specifically stated and are not intended to create legal relations with the recipient.

From: Helen Hawker < helen.hawker@conisbee.co.uk >

Date: Tue, Jun 24, 2014 at 10:18 AM

Subject: 130607 - 9-12 New College Parade, Finchley Road, NW3 5EP

To: "newcollegeparade1235@davysmitharchitects.co.uk" <newcollegeparade1235@

davysmitharchitects.co.uk>

Cc: Dave Richards Dave.Richards@conisbee.co.uk, Helen Hawker Helen.hawker@conisbee.co.uk, John Segrott John.segrott@conisbee.co.uk

Dear Lucy,

Further to your feedback from Camden and our 'phone conversation, please find attached the 'Damage Categories after Burland'.

We confirm that the proposed basement works at Nos 9-12 New College Parade, if carried out be a competent and experienced contractor in accordance to the detailed design drawings and to all relevant British and/or European Standards, should impact no more than a category 0-1 of the attached table.

Kind regards,

Helen Hawker

Principal Engineer

conisbee

020 7700 6666

DD 020 7697 7255



London 1-5 Offord Street London N1 1DH

Telephone 020 7700 6666 Fax 020 7700 6686

Norwich

2 Woolgate Court St.Benedicts Street Norwich NR2 4AP

Telephone 01603 628 074

Cambridge

47-51 Norfolk Street Cambridge CB1 2LD

Telephone 01223 656058

helen.hawker@conisbee.co.uk www.conisbee.co.uk

ISO 9001:2008 | ISO 14001:2004 | INVESTOR IN PEOPLE

Please consider the environment before printing this email

Conisbee is a trading name of Alan Conisbee & Associates Ltd Registered in England No. 3958459 Vat no. 393852807

This e-mail and any attachment contains private and confidential information and is intended for the named recipient(s) only. If you are not named then you are not authorised to read, copy or use this e-mail or any attachment. If you have received this e-mail in error, please notify the sender by return e-mail and then destroy it.

