

#### **FURTHER INVESTIGATION REPORT:**

6 Nutley Terrace,

London NW3 5BX

#### REPORT PREPARED FOR:

Mr Shamim Shafi

6 Nutley Terrace,

London, NW3 5BX

### REPORT PREPARED BY

Adam Hollis

MSc ARB MICFor FArbor A MRICS C Env

Ref: SHF/NTL/PCS/02

Date: 1ST December 2014

The content and format of this Report are for the exclusive use of the Client. It may not be sold, lent, hired out or divulged to any third party, not directly involved in the subject matter without Landmark Trees written consent.

**Web:** www.landmarktrees.co.uk **e-mail:** info@landmarktrees.co.uk

**Tel:** 0207 851 4544











The statements in this Report do not take account of the effects of extremes of climate, vandalism or accident, whether physical, chemical or fire cannot therefore accept any liability in connection with these factors, nor where prescribed work is not carried out in a correct and professional manner in accordance with current good practice. The authority of this Report ceases at any stated time limit within it, or if none stated after two years from the date of the survey or when any site conditions change, or pruning or other works unspecified in the Report are carried out to, or affecting, the subject tree(s), whichever is the sooner.

# **Limitations of Use and Copyright:**

The content and format of this Report are for the exclusive use of the client. It may not be sold, lent, hired out or divulged to any third party not directly involved in the subject matter without our written consent.

<u>Site Address:</u> 6 Nutley Terrace, London, NW3 5BX.

Client: Mr Shamim Shafi 6 Nutley Terrace, London, NW3 5BX

**Instruction:** Carry out Picus Tomograph Decay detection on the main stem of a Poplar tree.

Date of Inspection: 20th November 2014

**Species**: Hybrid Poplar. (*Populus 'Serotina'*)

**Height:** 14.2m Diameter at 1.5m above ground level (agl) 1390mm

## **General Observations:**

The tree (T3 on enclosed plan: 6 Nutley Terrace - REV-TCP - Dec 2014 - BO - 6 Nutley Terrace A2 Landscape) is situated in the rear garden of No 6 Nutley Terrace on the northern boundary, very close to a brick wall.

At the base of the tree to the north west and west, there are old brackets of tinder fungus (Fomes fomentarius). Around the sites of the fungus, the stem sounds hollow when tapped.

The tree has been pollarded with lots of old wounds with new regrowth in the crown.


### **Picus Sonic Tomography**

The Picus Sonic Tomograph is made by a German company called Argus-Electronic-Gmbh. It is a specialised electronic instrument which can 'look' internally into a branch or tree trunk and display a computer generated image of its condition. It achieves this by measuring the speed that sound travels through the wood in a number of different positions and directions. Sound travels fastest through solid wood. Decayed wood will slow its path. By measuring the speed that sound takes to pass through a tree, an idea of its condition can be obtained.

The PICUS Sonic Tomograph consists of 8 to 14 sonic sensors. These sensors are spaced out evenly around the circumference of the trunk. They detect stress waves induced by manual impact propagated through the wood. Time-of-sound-transmissions are used to generate two-dimensional pictures that document decay and cavities.

The sounds are generated manually by tapping on a number of metal nails with a hammer. Special sensors fixed around the stem read the interval the sound takes to travel through the wood. Once all nails have been tapped, and recordings taken, the computer software works out a visual image that requires professional assessment to assess decay.

# Picus Tomograph Results:



Test at 30cm agl

The Tomograph shows the cavity to the over most of the section coloured blue. There is a small amount of decay coloured purple and some incipient, early decay coloured green. The straight line from point 11 to point 1 is where the tree was close to the perimeter wall.

# **Conclusion:**

The Tomograph shows that the cavity and decay is extensive and could affect the structural integrity of the tree.

# **Recommendations:**

Fell as soon as practically possible. This work to be carried out by a full qualified and insured tree surgeon to British standard BS3998 (2010), Tree work.