

Chelmer Site Investigations

Unit 15, East Hanningfield Industrial Estate
Old Church Road, East Hanningfield, Essex CM3 8AB


Telephone: 01245 400 930 **Fax:** 01245 400 933

Email: info@siteinvestigations.co.uk **Website:** www.siteinvestigations.co.uk



Factual Report

Client:	Zurich Insurance C/o Pyle Consulting
Site:	56 Parkway London NW1 7AH
CSI Ref:	FACT/4137/Visit 1
Dated:	7 th January 2014



Chelmer Site Investigations

Unit 15, East Hanningfield Industrial Estate
Old Church Road, East Hanningfield, Essex CM3 8AB

Telephone: 01245 400 930 **Fax:** 01245 400 933

Email: info@siteinvestigations.co.uk **Website:** www.siteinvestigations.co.uk

FACTUAL REPORT CONTENT

- 1.0 SITE PLAN
- 2.0 TRIAL PITS / BOREHOLE LOGS
- 3.0 ROOT IDENTIFICATION
- 4.0 GEOTECHNICAL SOIL TESTING
- 5.0 CCTV DRAINAGE REPORT
- 6.0 REPORT NOTES


Chelmer Site Investigations

Unit 15 East Hanningfield Industrial Estate
 Old Church Road, East Hanningfield, Essex CM3 8AB
 Telephone: 01245 400930 Fax: 01245 400933

Email: info@siteinvestigations.co.uk Website: www.siteinvestigations.co.uk



Client: Pyle Consulting	Scale: N.T.S.	Sheet: 1 of 1	Date: 01.12.13
Location: 56 Parkway, London NW1 7AR	Job No: 4137	Weather: Overcast	Drawn by: MM Checked by: ME



Notes:

Key:

-  Tree/Shrub
-  Borehole
-  Trial Pit
-  Gully
-  Tree Stump
-  Rain Water/
Soil Pipe
-  MH
Manhole


Chelmer Site Investigations

Unit 15 East Hanningfield Industrial Estate
 Old Church Road, East Hanningfield, Essex CM3 8AB
 Telephone: 01245 400930 Fax: 01245 400933

Email: info@siteinvestigations.co.uk Website: www.siteinvestigations.co.uk



Client: Pyle Consulting	Scale: N.T.S.	Sheet No: 1 of 1	Date: 07.12.13
Location: 56 Parkway, London NW1 7AR	Job No: 4137	Trial Pit No: 1	Weather: Overcast
Excavation Method: Hand tools		Drawn by: BU	Checked by: ME



FOR STRATA BELOW 700mm SEE BH1 Log

Remarks:	Key:	
	D Small disturbed sample B Bulk disturbed sample U Undisturbed sample (U100) N Standard Penetration Test Blow Count	J Jar sample V Pilcon Vane (kPa) M Mackintosh Probe W Water Sample

Chelmer Site Investigations

Unit 15 East Hanningfield Industrial Estate
 Old Church Road, East Hanningfield, Essex CM3 8AB
 Telephone: 01245 400930 Fax: 01245 400933



Email: info@siteinvestigations.co.uk Website: www.siteinvestigations.co.uk

Client: Pyle Consulting		Scale: N.T.S.	Sheet No: 1 of 1	Weather: Overcast	Date: 07.12.13			
Site: 56 Parkway, London NW1 7AR		Job No: 4137	Borehole No: 1	Boring method: Hand Auger				
Depth Mtrs.	Description of Strata	Thick-ness	Legend	Sample	Test Type Result	Root Information	Depth to Water	Depth Mtrs
0.7	AS TP1	0.7				Roots of live appearance to 1mmØ to 2.2m.		
0.7	MADE GROUND: medium compact, dark brown, sandy, very silty clay with brick fragments.	0.2						
0.9	Stiff, mid brown, silty CLAY with partings of orange and brown silt and fine sand.	2.1		D	V 74 76			1.0
				D	V 108 112			1.5
				D	V 116 118			2.0
				D	V 118 122			2.5
3.0	Borehole ends at 3.0 m			D	V 134 136			3.0

Drawn by: BU Approved by: ME

Remarks: Borehole dry and open on completion.

Key: T.D.T.D. Too Dense to Drive
 D Small Disturbed Sample J Jar Sample
 B Bulk Disturbed Sample V Pilcon Vane (kPa)
 U Undisturbed Sample (U100) M Mackintosh Probe
 W Water Sample N Standard Penetration Test Blow Count

Chelmer Site Investigations


Unit 15 East Hanningfield Industrial Estate
Old Church Road, East Hanningfield, Essex CM3 8AB

Telephone: 01245 400930 Fax: 01245 400933

Email: info@siteinvestigations.co.uk Website: www.siteinvestigations.co.uk



Client: Pyle Consulting	Scale: N.T.S.	Sheet No: 1 of 1	Date: 07.12.13
Location: 56 Parkway, London NW1 7AR	Job No: 4137	Trial Pit No: 2	Weather: Overcast
Excavation Method: Hand tools		Drawn by: BU	Checked by: ME



FOR STRATA BELOW 800mm SEE BH2 Log

Remarks:

Key:

- | | |
|---|----------------------------|
| D Small disturbed sample | J Jar sample |
| B Bulk disturbed sample | V Pilcon Vane (kPa) |
| U Undisturbed sample (U100) | M Mackintosh Probe |
| N Standard Penetration Test Blow Count | W Water Sample |

Chelmer Site Investigations

Unit 15 East Hanningfield Industrial Estate
Old Church Road, East Hanningfield, Essex CM3 8AB
Telephone: 01245 400930 Fax: 01245 400933

Email: info@siteinvestigations.co.uk Website: www.siteinvestigations.co.uk



Client: Pyle Consulting		Scale: N.T.S.		Sheet No: 1 of 1		Weather: Overcast		Date: 0.7.01.14	
Site: 56 Parkway, London NW1 7AR		Job No: 4137		Borehole No: 2		Boring method: Hand Auger			
Depth Mtrs.	Description of Strata	Thick-ness	Legend	Sample	Test Type Result	Root Information	Depth to Water	Depth Mtrs	
0.8	AS TP2	0.8				Roots of live appearance to 1mmØ to 1.6m.			
	Firm, brown, silty CLAY with partings of orange and brown silt and fine sand. Becoming stiff from 1.0m.			D	V 78 82			1.0	
				D	V 118 122			1.5	
			2.2		D	V 134 136			2.0
3.0	Borehole ends at 3.0 m			D	V 124 126			2.5	
				D	V 118 120			3.0	
Drawn by: BU		Approved by: ME		Key: T.D.T.D. Too Dense to Drive D Small Disturbed Sample J Jar Sample B Bulk Disturbed Sample V Pilcon Vane (kPa) U Undisturbed Sample (U100) M Mackintosh Probe W Water Sample N Standard Penetration Test Blow Count					
Remarks: Borehole dry and open on completion.									


Chelmer Site Investigations

Unit 15 East Hanningfield Industrial Estate
 Old Church Road, East Hanningfield, Essex CM3 8AB
 Telephone: 01245 400930 Fax: 01245 400933

Email: info@siteinvestigations.co.uk Website: www.siteinvestigations.co.uk



Client: Pyle Consulting	Scale: N.T.S.	Sheet No: 1 of 1	Date: 07.01.14
Location: 56 Parkway, London NW1 7AR	Job No: 4137	Trial Pit No: 3	Weather: Overcast
Excavation Method: Hand tools		Drawn by: BU	Checked by: ME



FOR STRATA BELOW 900mm SEE BH3 Log

Remarks:	Key:	
	D Small disturbed sample B Bulk disturbed sample U Undisturbed sample (U100) N Standard Penetration Test Blow Count	J Jar sample V Pilcon Vane (kPa) M Mackintosh Probe W Water Sample

Chelmer Site Investigations

Unit 15 East Hanningfield Industrial Estate
 Old Church Road, East Hanningfield, Essex CM3 8AB
 Telephone: 01245 400930 Fax: 01245 400933



Email: info@siteinvestigations.co.uk Website: www.siteinvestigations.co.uk

Client: Pyle Consulting		Scale: N.T.S.		Sheet No: 1 of 1		Weather: Overcast		Date: 0.7.01.14	
Site: 56 Parkway, London NW1 7AR		Job No: 4137		Borehole No: 3		Boring method: Hand Auger			
Depth Mtrs.	Description of Strata	Thick-ness	Legend	Sample	Test Type Result	Root Information	Depth to Water	Depth Mtrs	
0.9	AS TP3	0.9				Roots of live appearance to 1mmØ to 1.4m.			
0.9	Stiff, brown, silty CLAY with partings of brown and orange silt and fine sand.	2.1		D	V 98 102			1.0	
				D	V 118 122			1.5	
				D	V 140+ 140+			2.0	
3.0	Borehole ends at 3.0 m			D	V 140+ 140+			2.5	
				D	V 140+ 140+			3.0	
Drawn by: BU Approved by: ME		Key: T.D.T.D. Too Dense to Drive D Small Disturbed Sample J Jar Sample B Bulk Disturbed Sample V Pilcon Vane (kPa) U Undisturbed Sample (U100) M Mackintosh Probe W Water Sample N Standard Penetration Test Blow Count							
Remarks: Borehole dry and open on completion.									



Root identification
Vegetation surveys
Tree/Building investigations
Plant taxonomy

Richardson's Botanical Identifications

Dr Ian B K Richardson
BSc, PhD, CBiol, MiBiol, MiHort, FLS
James Richardson
BSc (Hons. Biology)

Chelmer Site Investigations
Unit 15
East Hanningfield Ind. Est.
Old Church Rd, E. Hanningfield
Essex CM3 8AB

Enterprise House
49-51 Whiteknights Road
Reading
RG6 7BB

Tel: (0118) 986 9552 (*Direct line*)
E-mail: richardsons@botanical.net
Web: www.botanical.net

Your ref: 4137

Our ref: 73/4501

22/05/2014

Dear Sirs

56 Parkway

The samples you sent in relation to the above on 19/05/2014 (received by us on 21/05/2014 (yesterday)) have been examined. The structure was referable as follows:

TP, u/s, 600mm

1 root: PLATANUS (Plane). This sample was in POOR condition. Dead*.

10 pieces of BARK only - insufficient material for identification.

BH1, 700-2200mm

1 root: PLATANUS (Plane). A further sample, not examined in detail appeared similar under low magnification. Dead*.

TP2, u/s, 600mm

1 root: PLATANUS (Plane). Alive, recently*.

BH2, 800-1600mm

1 root: PLATANUS (Plane). A further sample, not examined in detail appeared similar under low magnification. Alive, recently*.

TP3, u/s, 700mm

1 root: PLATANUS (Plane). Alive, recently*.

BH3, 900-1400mm

1 root: PLATANUS (Plane). Alive, recently*.

I trust this is of help. Please call us if you have any queries; our Invoice is enclosed.

Yours faithfully

Dr Ian B K Richardson

* Based mainly on the Iodine test for starch. Starch is present in some cells of a living woody root, but is more or less rapidly broken down by soil micro-organisms on death of the root, sometimes before decay is evident. This result need not reflect the state of the parent tree.

Identified with no information on vegetation, on or off site.

Report commissioned by



Laboratory Testing Results

BS 1377 : 1990



Job Number : CGL03797
 Client : Pyle Consulting
 Client Reference : CSI4137
 Site Name : 56 Parkway, London NW1

Date Received : 20/01/2014
 Date Testing Started : 20/01/2014
 Date Testing Completed : 21/01/2014
 Laboratory Used : Chelmer Geotechnical, CM3 8AB

Sample Ref	Depth	UID	Sample Type	Moisture Content (%) [1]	Soil Fraction > 0.425mm (%) [2]	Liquid Limit (%) [3]	Plastic Limit (%) [4]	Plasticity Index (%) [5]	Liquidity Index (%) [5]	Modified Plasticity Index (%) [6]	Soil Class [7]	Filter Paper Contact Time (h) [8]	Soil Sample Suction (kPa)	In situ Shear Vane Strength (kPa) [9]	Organic Content (%) [10]	pH Value [11]	Sulphate Content		
																	SO ₃ [12]	SO ₄ [13]	Class [14]
TP/BH1	0.7	47449	D	35	<5						CV			70					
TP/BH1	1.0	47450	D	34	<5	81	23	58	0.20	58	CV			75					
TP/BH1	1.5	47451	D	34	<5	86	21	65	0.19	65	CV			110					
TP/BH1	2.0	47452	D	28	<5	77	22	55	0.11	55	CV			120					
TP/BH1	2.5	47453	D	30	<5									120					
TP/BH1	3.0	47454	D	31	<5	79	21	58	0.17	58	CV			135					

Notes :-

[1] BS 1377 : Part 2 : 1990, Test No 3.2

[2] Estimated if <5%, otherwise measured

[3] BS 1377 : Part 2 : 1990, Test No 4.4

[4] BS 1377 : Part 2 : 1990, Test No 5.3

[5] BS 1377 : Part 2 : 1990, Test No 5.4

[6] BRE Digest 240 : 1993

[7] BS 5930 : 1981 : Figure 31 - Plasticity Chart for the classification of fine soils

[8] In-house method S9a adapted from BRE IP 4/93

[9] Values of shear strength were determined in situ by Chelmer Site Investigations using a Picon hand vane or Geonor vane (GV).

[10] BS 1377 : Part 3 : 1990, Test No 4

[11] BS 1377 : Part 2 : 1990, Test No 9

[12] BS 1377 : Part 3 : 1990, Test No 5.6

[13] SO₃ = 1.2 x SO₄

[14] BRE Special Digest One (Concrete in Aggressive Ground) 2005

Note that if the SO₄ content falls into the DS-4 or DS-5 class, it would be prudent to consider the sample as falling into the DS-4m or DS-5m class respectively unless water soluble magnesium testing is undertaken to prove otherwise

Comments :-

Produced :- MT

Checked By :- AK

Date Checked :- 23-Jan-14

Laboratory Testing Results

BS 1377 : 1990



Job Number : CGL03797
 Client : Pyle Consulting
 Client Reference : CSI4137
 Site Name : 56 Parkway, London NW1

Date Received : 20/01/2014
 Date Testing Started : 20/01/2014
 Date Testing Completed : 21/01/2014
 Laboratory Used : Chelmer Geotechnical, CM3 8AB

Sample Ref	Depth	UID	Sample Type	Moisture Content (%) [1]	Soil Fraction > 0.425mm (%) [2]	Liquid Limit (%) [3]	Plastic Limit (%) [4]	Plasticity Index (%) [5]	Liquidity Index (%) [5]	Modified Plasticity Index (%) [6]	Soil Class [7]	Filter Paper Contact Time (h) [8]	Soil Sample Suction (kPa)	Insitu Shear Vane Strength (kPa) [9]	Organic Content (%) [10]	pH Value [11]	Sulphate Content		
																	SO ₃ [12]	SO ₄ [13]	Class [14]
TP/BH2	0.7	47455	D	35	<5	89	22	67	0.19	67	CV			70					
TP/BH2	1.0	47456	D	34	<5	84	21	63	0.21	63	CV			80					
TP/BH2	1.5	47457	D	31	<5	75	21	54	0.17	54	CV			120					
TP/BH2	2.0	47458	D	36	<5	73	20	53	0.30	53	CV			135					
TP/BH2	2.5	47459	D	32	<5									125					
TP/BH2	3.0	47460	D	31	<5									120					

Notes :-

- [1] BS 1377 : Part 2 : 1990, Test No 3.2
- [2] Estimated if <5%, otherwise measured
- [3] BS 1377 : Part 2 : 1990, Test No 4.4
- [4] BS 1377 : Part 2 : 1990, Test No 5.3
- [5] BS 1377 : Part 2 : 1990, Test No 5.4
- [6] BRE Digest 240 : 1993
- [7] BS 5930 : 1981 : Figure 31 - Plasticity Chart for the classification of fine soils
- [8] In-house method S9a adapted from BRE IP 4/93
- [9] Values of shear strength were determined in situ by Chelmer Site Investigations using a Plicon hand vane or Geonov vane (GV).
- [10] BS 1377 : Part 3 : 1990, Test No 4
- [11] BS 1377 : Part 2 : 1990, Test No 9
- [12] BS 1377 : Part 3 : 1990, Test No 5.6
- [13] SO₃ = 1.2 x SO₄
- [14] BRE Special Digest One (Concrete in Aggressive Ground) 2005

Comments :-

Note that if the SO₃ content falls into the DS-4 or DS-5 class, it would be prudent to consider the sample as falling into the DS-4m or DS-5m class respectively unless water soluble magnesium testing is undertaken to prove otherwise

Laboratory Testing Results

BS 1377 : 1990



Job Number : CGL03797
 Client : Pyle Consulting
 Client Reference : CSI4137
 Site Name : 56 Parkway, London NW1

Date Received : 20/01/2014
 Date Testing Started : 20/01/2014
 Date Testing Completed : 21/01/2014
 Laboratory Used : Chelmer Geotechnical, CM3 8AB

Sample Ref	Depth	UID	Sample Type	Moisture Content (%) [1]	Soil Fraction > 0.425mm (%) [2]	Liquid Limit (%) [3]	Plastic Limit (%) [4]	Plasticity Index (%) [5]	Liquidity Index (%) [5]	Modified Plasticity Index (%) [6]	Soil Class [7]	Filter Paper Contact Time (h) [8]	Soil Sample Suction (kPa)	Insitu Shear Vane Strength (kPa) [9]	Organic Content (%) [10]	pH Value [11]	Sulphate Content		
																	SO ₃ [12]	SO ₄ [13]	Class [14]
TP/BH3	0.7	47461	D	34	<5	84	22	62	0.20	62	CV			70					
TP/BH3	1.0	47462	D	35	<5	88	21	67	0.20	67	CV			100					
TP/BH3	1.5	47463	D	32	<5									120					
TP/BH3	2.0	47464	D	29	<5	73	17	56	0.21	56	CV			>140					
TP/BH3	2.5	47465	D	32	<5	74	22	52	0.18	52	CV			>140					
TP/BH3	3.0	47466	D	32	<5									120					

Notes :-

- [1] BS 1377 : Part 2 : 1990, Test No 3.2
- [2] Estimated if <5%, otherwise measured
- [3] BS 1377 : Part 2 : 1990, Test No 4.4
- [4] BS 1377 : Part 2 : 1990, Test No 5.3
- [5] BS 1377 : Part 2 : 1990, Test No 5.4
- [6] BRE Digest 240 : 1993
- [7] BS 5930 : 1981 : Figure 31 - Plasticity Chart for the classification of fine soils
- [8] In-house method S9a adapted from BRE IP 4/93
- [9] Values of shear strength were determined in situ by Chelmer Site Investigations using a Plicon hand vane or Geonov vane (GV).
- [10] BS 1377 : Part 3 : 1990, Test No 4
- [11] BS 1377 : Part 2 : 1990, Test No 9
- [12] BS 1377 : Part 3 : 1990, Test No 5.6
- [13] SO₄ = 1.2 x SO₃
- [14] BRE Special Digest One (Concrete in Aggressive Ground) 2005

Comments :-

Key

D Disturbed sample
 B Bulk sample
 U U100 (undisturbed sample)
 W Water sample
 ENP Essentially Non-Plastic
 U/S Underside Foundation



Laboratory Testing Results

Moisture Content/Shear Strength Profile



Job Number : CGL03797
 Client : Pyle Consulting
 Client Reference : CS14137
 Site Name : 56 Parkway, London NW1

Date Received : 20/01/2014
 Date Testing Started : 20/01/2014
 Date Testing Completed : 21/01/2014
 Laboratory : Chelmer Geotechnical Laboratories, CM3 8AB



Notes :-

1. If the Soil Fraction > 0.425mm exceeds 5% the Equivalent Moisture Content of the remainder (calculated in accordance with BS 1377: Part 2 : 1990 cl.3.2.4 note 1) is also plotted and the alternative profile additionally shown as an appropriately coloured broken line.
2. If plotted, 0.4 LL and PL+2 (after Discoll, 1983) should only be applied to London Clay (and similarly over consolidated clays) at shallow depths.

Comments :-

Checked By :- AK

Date Checked :- 23-Jan-14

Unless otherwise stated, values of Shear Strength were determined in situ by Chelmer Site Investigations using a Picon Hand Vane the calibration of which is limited to a maximum reading of 140 kPa.


Laboratory Testing Results

Plasticity Chart for the classification of fine soils and the finer part of coarse soils
In Compliance with BS5930 : 1999



Job Number : GGL03797
Client : Pyle Consulting
Client Reference : CS14137
Site Name : 56 Parkway, London NW1

Date Received : 20/01/2014
Date Testing Started : 20/01/2014
Date Testing Completed : 21/01/2014
Laboratory : Chelmer Geotechnical Laboratories, CM3 8AB



Notes :-

SILT (M-SOIL), M, plots below A-Line
CLAY, C, plots above A-Line JM and C may be combined as FINE SOIL, F.

Key :- TP/BH1


TP/BH2

TP/BH3

Comments :-

Checked By :- AK

Date Checked :- 23-Jan-14



DRAINAGE REPORT

Client:

Pyle Consulting

Site Address:


**56 Parkway
London
NW1 7AH**

Date of Drainage Survey:

7th January 2014


Chelmer Reference:

1019



REPORT CONTENTS

- 1.0 Drainage investigation summary
- 2.0 Drainage layout plan
- 3.0 CCTV survey report and recommendations
- 4.0 Manhole detail and condition summary
- 5.0 Summary of recommendations with repair costs




1.0 DRAINAGE INVESTIGATION SUMMARY

This property has a combined drainage system with services collected from the rear of the property into an interceptor manhole, MH1, before flowing out and connecting to a common sewer. This common sewer appears to flow across the rear of the properties, passing under the back addition.


There were no operational issues noted at the time of the survey, however some defects were noted and are outlined in this report.

A CCTV survey was carried out to establish the condition of the drainage system. The fine detail of this CCTV survey is given on Pages 5–7, together with a summary of the findings and relevant recommendations where appropriate (recommendations based solely on *visual* condition of pipework).

A summary of all the recommendations are given on Page 9, together with costing for the proposed works.



2.0 DRAINAGE LAYOUT PLAN (NTS)



KEY:	BD = Backdrop	R/E = Rodding Eye	SWG = Surface water gully
	CG = Combined grey waste and storm gully	RWG = Rainwater gully	SVP = Soil and vent pipe
	G = Grey water waste gully	RWP = Rainwater pipe	VP = Vent pipe
	MH = Manhole	RWS = Rainwater pipe onto surface	WP = Waste pipe



3.0 CCTV SURVEY INSECTION REPORT AND RECOMMENDATIONS

SURVEY 1:		MH1 UPSTREAM TO SVP: 100mm CLAY: FOUL DUTY	
Meterage	Observations and comments		
00.0	Start survey		
00.8	Slight offset joint (stepped with flow)		
00.9 – 01.4	Bend right		
01.2	Slight offset joint (pulled right) and jointing intrusions		
01.3	Radial crack		
02.0 – 02.5	Bend left		
02.6	At rest bend to SVP		
Invert level at MH1:	650mm	Operational condition:	No operational issues noted at time of survey
Recommendations:			
<p>There were no operational issues in this line at the time of the survey, however the survey did identify a crack in the pipework just after the first bend upstream from MH1 and given this defect there is likely to be leakage from the drain.</p> <p>Accordingly, consideration should be given to lining from MH1 upstream to approximately 1.5m in order to seal this defect. Please note that due to the bend in the pipework this will need to be a 'flexible' liner (CIPP).</p> <p>(See Repair Item A, Section 5.0)</p>			

SURVEY 2:		MH1 UPSTREAM 'B': 100mm CLAY: REDUNDANT	
Meterage	Observations and comments		
00.0	Start survey		
00.0 – 00.4	Debris, up to 30%		
00.4	End of pipework – brick visible ahead. Line appears redundant		
Invert level at MH1:	650mm	Operational condition:	N/A
Recommendations:			
<p>The CCTV survey indicated this to be a redundant connection into MH1. The end of the pipe does not appear to be properly capped-off therefore if the system blocks there could be leakage into the ground from this inlet.</p> <p>All services should be carefully checked again and once this inlet is confirmed to be redundant it should be properly capped-off from within MH1.</p> <p>(See Repair Item B, Section 5.0)</p>			

cont./



3.1 CCTV SURVEY INSECTION REPORT AND RECOMMENDATIONS


SURVEY 3:	MH1 UPSTREAM TO CG1: 100mm CLAY: COMBINED DUTY	
Meterage	Observations and comments	
00.0	Start survey	
00.3	Slight offset joint (stepped with flow). At back-inlet gully CG1	
Invert level at MH1:	650mm	Operational condition: No operational issues noted at time of survey
Recommendations:		
<p>This run is very short and no operational issues noted, however there is an open pipe from the RWP/waste pipes that connects into the gully as a back-inlet. This is in very poor condition and leakage could be seen during our site attendance. Accordingly this back-inlet and the gully CG1 should be broken out and renewed and the layout rationalised into MH1.</p> <p>(See Repair Item C, Section 5.0)</p>		

SURVEY 4:	RODDING EYE UPSTREAM TO WC: 100mm PLASTIC: FOUL DUTY	
Meterage	Observations and comments	
00.0	Start survey	
00.7 – 01.0	Bend up to WC	
Invert level:	GL	Operational condition: No operational issues noted at time of survey
Recommendations:		
<p>This section of pipework is unusually installed in that the pipework is at ground level. There were no visual defects or operational issues in the section surveyed therefore further works are not considered essential, however the arrangement is not ideal.</p>		



Pipework to WC is visible at ground level

cont./




3.2 CCTV SURVEY INSECTION REPORT AND RECOMMENDATIONS


SURVEY 5:	R/ EYE DOWNSTREAM TO MH1: 100mm PLASTIC/CAST IRON/CLAY: FOUL DUTY	
Meterage	Observations and comments	
00.0	Start survey	
00.3	Change of material to cast iron	
04.0	Change of material to clay	
04.1 – 04.3	Bend down to MH1 (enters MH1 at high level – see MH1 overview photograph, Page 8)	
Invert level:	GL	Operational condition: No operational issues noted at time of survey
Recommendations: See general notes for Survey 4 regarding pipework being at ground level.		

SURVEY 6:	MH1 DOWNSTREAM TO MAIN SEWER: 100mm CLAY: COMBINED DUTY	
Meterage	Observations and comments	
00.0	Start survey	
00.1	Interceptor trap outlet at 6 o'clock. Radial crack/fracture	
00.3	Radial crack	
00.4 – 00.5	Bend left	
00.6	At junction to common sewer	
Invert level at MH1:	650mm	Operational condition: No operational issues noted at time of survey
Recommendations: The survey identified some serious visual defects in this short section of pipework through to the common sewer. There is a fracture around the back of the interceptor trap and a further radial crack in the pipework indicating this run will leak. Consideration should therefore be given to excavating and renewing the pipework through to the common sewer, including the interceptor trap. Please note that the common sewer passes under the back addition. If the integrity of this sewer needs to be established it should be CCTV surveyed, however this will need to be instructed through Thames Water Utilities Limited as they are responsible for this sewer. (See Repair Item D, Section 5.0)		

END OF CCTV SURVEY



4.0 MANHOLE SUMMARY



MH1

Invert level (relative to cover level): 650mm


Cover dimension: 500 x 500mm

Chamber dimension: 500 x 500mm


Construction: Brick and render

Condition: No defects noted

Recommendation: None




MH1 overview



4.0 SUMMARY OF RECOMMENDATIONS AND REPAIR COSTS

Item	Section of drainage	Chelmer CCTV survey number	Recommendation	Priority	Cost (£) excluding VAT
A	MH1 – SVP	1	Part line (CIPP) using flexible liner	Medium	£325.00
B	MH1 – ‘B’	2	Check all services to confirm line is redundant, then cap-off properly from within MH1	Medium	£75.00
C	MH1 – CG1	3	Excavate and renew CG1 and back-inlet from RWP/waste pipes	High	£601.28
D	MH1 – Downstream	6	Excavate and renew (Please note that it <i>may</i> be necessary to break out part of the front manhole wall to allow sufficient working space to renew the interceptor trap in MH1)	High	£810.85
	<i>High Priority</i>			Sub-total	£1,812.13
	<i>Medium Priority</i>			VAT	£362.43
	<i>Low Priority</i>			TOTAL	£2,174.56



TERMS AND CONDITIONS

Please note the Quotation is based on the following:-

Within this quotation we have not included for any works other than for those stated above.

All works are subject to Chelmer Site Investigations Ltd Terms and Conditions of contract, schedule of variations and day working charges.

Access to the area of work is agreed prior to date of work, as a relevant fee will apply for an aborted site visit.

Areas of work are easily accessible and clear of obstructions.

When undertaking any internal works we will require the use of electricity. However, if none is available at time of works then an additional charge will be made.

Timber decking is to be lifted by householder/owner prior to date of works or a further fee will apply.

No allowances have been made to use crawler camera drain unit to survey pipelines greater than 225mm diameter, price on application.

Subject to availability, we would be able to undertake these works within **7 days** upon receipt of written instruction.

Payment Terms

Please be advised that when undertaking works for private/domestic clients full payment is required either before, or on the day of works.

For all new commercial clients/companies a 50% payment will be required before works commence.

If you would like to accept this quotation we would be grateful if the details attached could be completed by the person/s settling our invoice and returned to ourselves.


Please note this quotation is valid for 90 days from the date of this letter.

Chelmer Drainfix Logistics

Unit 15, East Hanningfield Industrial Estate, Old Church Road
East Hanningfield, Essex CM3 8AB

Telephone: 01245 400 930 **Fax:** 01245 400 933

Email: info@siteinvestigations.co.uk **Website:** www.siteinvestigations.co.uk



We/I accept the quotation and terms as set out in Chelmer Project No. **1019** and agree your payment terms.

The invoice should be addressed as follows:-

Company Name: _____
(Invoice payee)

Invoice Address: _____

Tele No: _____

Fax No: _____

Email: _____

Purchase Order No: _____

Signed _____

Print Name: _____


Date: _____

Chelmer Site Investigations

Unit 15, East Hanningfield Industrial Estate, Old Church Road
East Hanningfield, Essex CM3 8AB

Telephone: 01245 400 930 Fax: 01245 400 933

Email: info@siteinvestigations.co.uk Website: www.siteinvestigations.co.uk



REPORT NOTES

Equipment Used

Hand tools, Mechanical Concrete Breaker and Spade, Hand Augers, 100mm/150mm diameter Mechanical Flight Auger Rig, GEO205 Flight Auger Rig, Window Sampling Rig, and Large or Limited Access Shell & Auger Rig upon request and/or access permitting.

On Site Tests

By Pilcon Shear-Vane Tester (Kn/m^2) in clay soils, and/or Mackintosh Probe in granular soils or made ground and/or upon request Continuous Dynamic Probe Testing and Standard Penetration Testing.

Note:

Details reported in trial-pits and boreholes relate to positions investigated only as instructed by the client or engineer on the date shown.

We are therefore unable to accept any responsibility for changes in soil conditions not investigated i.e. variations due to climate, season, vegetation and varying ground water levels.

Full terms and conditions are available upon request.