

P3075 BULL & LAST PUBLIC HOUSE, NW5 1QS

REVIEW OF INFORMATION IN RESPECT OF FORMER CELLAR HATCH

1. Introduction

As part of a planning application for alterations to the Bull & Last Public House, it is proposed to re-create a cellar hatch adjacent to the pavement to Woodsome Road. Refer architectural drawings by WMG Studio. The cellar hatch is currently internal within the pub, however it is thought that originally this was external and has subsequently been infilled. We have reviewed the information available in respect of this, which we have summarised in this statement.

2. Site Visit

We have visited the public house and we have attached a sample of our photos in Appendix A.

In summary of our observations: -

- The public house has wide pavements to both Highgate Road and Woodsome Road, suggesting some of these pavement areas lie within the demise of the pub (refer photo 1)
- Adjacent to the Woodsome Road elevation, there is an area where there has been previous re-surfacing (refer photo 2)
- Inside of the pub and behind the re-surfaced area there is an internal cellar hatch (refer photo 3)
- At basement level there is an area of wall which is damp, giving very high readings with a dampmeter (refer photo 4). This is beneath the internal cellar hatch and behind the assumed former cellar hatch.
- The internal cellar hatch has been framed out in timber. The original steel beam does not line through with the edge of the hatch.

3. Sub-surface scanning

A sub-surface scan was commissioned to check for any services which would be affected by the reinstatement of the cellar hatch, and to check for any further signs of the original cellar hatch. The scan was carried out by Subscan Technology Ltd on 23 September 2015, and their findings are given in Appendix B.

In summary: -

- Generally the services were found to be clustered together and close to the kerbline to Woodsome Road
- One service ran closer to the building elevation; this was a telecoms cable 300 deep.



The Institution of Structural Engineers







 The scan also picked up a subsurface anomaly, assumed to be a possible slab 500mm below pavement level. The Subscan Technology report suggests this may be a capping slab over a former void.

4. Conclusions

- Our observations from the site visit suggest the presence of an external cellar hatch
 which has previously been infilled. There has been re-surfacing in the assumed location
 and the basement wall behind is damp, whereas the adjacent sections are not. The
 internal hatch looks not be original as it has been framed out in timber, with the original
 steel beam not running parallel to its inside edge.
- The findings of the subsurface scan support the above conclusion. The existing services were generally found to be close together and route around rather than over the assumed former hatch. The report from the sub-surface scanning specialist also suggested the presence of a slab over a void, suggesting an infilled area.
- The one service that does run over the proposed reinstated cellar hatch is a telecoms cable and this will need to be diverted prior to the excavation works.

Isaac Hudson MEng MA(Cantab.) CEng MIStructE











APPENDIX A - PHOTOS











Photographs from site visits



Photograph 1 - External View



Photograph 2 – View of pavement adjacent in front of Woodsome Road elevation



Photograph 3 – Internal view showing bricking up to line of internal cellar hatch



Photograph 4 - High damp readings taken to wall on line of hatch





Photograph 5 - Detail of Internal Cellar Hatch



Photograph 6 – Framing around internal cellar hatch



APPENDIX B - SUB-SURFACE SCAN RESULTS









UTILITY SURVEY REPORT

SITE ID:
Bull and last Public house,
High gate road,
Issue A

Prepared by:

Contractor name Subscan Technology Ltd

9 Somers Road

Rugby

Warwickshire

CV22 7DB

Tel: 01788 550017

SUBSCAN TECHNOLOGY

On behalf of:

Michael Alexander Consulting Engineers.

REGISTRATION OF AMENDMENTS

Issue	Date	Comments	Page(s)	By	Reviewe
Α		Original Issue			

Fig.		
File:	Page 1 Of 6	Date:
	0	

Table of Contents

	1.1.	Survey History	. 3
	1.2.	Dates of Current Survey	. 3
	1.3.	Personnel	. 3
2.		sting Service Records	
		UU Site As-built Records	
		Other Information	
3.		ld Equipment used	
4.	Acc	curacy Compliance	. 4
		General	
	4.2.	Calibration Procedures and Records	. 5
5.	Sur	rvey Results	. 6
	5.1.	Gas	. 6
		Electricity	
		Water	
	5.4.	Surface Water	. 6
	5.5.	Foul Water	. 6
	5.6.	Telecom	. 6
		Pipework	
	5.8.	GPR Results	. 6
6.	Cor	nclusions and Recommendations	. 6

SUMMARY

1.1. Survey History

Date	Contractor	Details	Drawings and documents issued
28/9/15	Subscan Technology Ltd	Autocad. Drawing	26234.

1.2. Dates of Current Survey

Fieldwork: 23-9-15.

Data-processing: 25-9-15.

Completion 28-9-15.

1.3. Personnel

Initials	Position	Fieldwork	Data- Processing	Report Compilation	QC
JE.	sweyer.	SP	DN.	JE	

2. Existing Service Records

Service	Provider	Filename(s)	Remarks
Cable TV			
Drainage			
Electric			
Gas			
Telecom			
Water			
Other			

File:	Page 3 Of 6	Date:

2.1. UU Site As-built Records

2.2. Other Information

3. Field Equipment used

Туре	Make	Model	S/N	Operator(s) Initials
RD4000	Radio Detection	RD4000	11 TIO-A-11	62077 5
GPR	ERA		1	-/-
RD4000	Radio Detection	RD4000	11/4Kex-15	022207 5
GPR	ERA			

4. Accuracy Compliance

4.1. General

We undertake to survey only for declared services (i.e., services that appear on statutory record drawings) to be provided by you unless otherwise agreed at the point of order. We will however, endeavour to locate and track any services not featured on record drawings but for technical reasons cannot guarantee to do so. Failure to detect or fully track any declared services will be recorded in detail. Any service that may be undetectable would be plotted on our drawing and annotated as taken from record plans.

SERVICES, WHICH WE HAVE INCLUDED

Sewers and drains of 100mm and above where access to the pipe work is possible

Water pipes of 38mm and above

Gas pipes of 38mm and above

Telecom and data services in ducts

Electric supply cables of 440v to 66kv, AC, which are live

Electric cables to street lighting

SERVICES, WHICH WE HAVE EXCLUDED FROM OUR SURVEY

Pipes, which have no access points for our transmitting probe

Pot ended cables

Disused services

Manhole covers that we cannot lift after 15 minutes levering with hand tools

Service connections to individual properties

File:	Dogg 4 Of 6	D-4-
rile:	Page 4 Of 6	Date:

Working in areas that are either unsafe or not practical for us to work in Internal Services (unless specified at point of order)

All Radiodetection and SPRScan survey equipment has a self checking and calibrating system built in upon the turning on and 'booting up' of the software. The instrument goes through a series of checks to ensure that all systems are correctly functioning. Should any of these systems fail then the instrument has an error message appear and can not be used until returned back to the dealer/supplier.

4.2. Calibration Procedures and Records

Calibration is scheduled on a yearly basis with Radiodetection.

A Calibration procedure is also undertaken on site prior to survey works commencing. Where a depth to a service can be physically measured i.e. from an inspection cover this depth can then be checked using both the RD 4000 and GPR for comparison. If the depths do not correlate then these instruments will be deemed as unserviceable and sent to the manufacturers for calibration/ repair. Replacement equipment will be then be used.

a) Horizontal Accuracy

Accuracy of underground utilities can vary depending on the type / size of service, its depth (vertical) and also local soil conditions. However, in general we would estimate that horizontal accuracy should be + or - 10cm of the services true width.

b) Vertical Accuracy of results

Accuracy of underground utilities can vary depending on the type / size of service, its depth (vertical) and also local soil conditions. However, in general we would estimate that depth (vertical) accuracy should be + or - 10% of the services true depth.

Note

- (i) Measurements on drains and sewers are to the invert.
- (ii) Measurements on non metallic pipes are to the crown of the pipe.

Measurements on cables and metallic pipes are to the centre of the magnetic field.

File:	Page 5 Of 6	Date:

5.	Survey Results
5.	1. Gas
	NA.
5.2.	Electricity
	Located Low Voltage Cable with Radiodetection 0.3 deep.
5.3.	Water
	Located using radiodetection
	O.7deep.
5.4.	Surface Water
	$\sim \mid A$.
5.5.	Foul Water
5.6.	Telecom Located by clamping Cable within BT manhote + tracing electromagnetically
5.7.	depth at 0.3 deep above slab. Pipework
	NA.
5.8.	GPR Results void located at 0.5 deep we
6.	clieve this to be the old hatchmay to conclusions and Recommendations Sellar beneath, here is a Solid obstruction at a Solid abstruction
+	here is a Solid obstruction at 0.5dep
1.	adingus to believe there is a void
E	Beneath.
File:	Page 6 Of 6 Date:



