

TECHNICAL REPORT ON A SUBSIDENCE CLAIM

Crawford Reference: SU1504550

37 Greville Road
London
NW6 5JB



This document and information provided relate to personal claim information and therefore should not be circulated or placed anywhere to make this freely available. By doing so, you will be in breach of Data Protection Act requirements

SUBSIDENCE CLAIM

DATE 10th November 2015




Specialist Property Services – Subsidence Division
Cartwright House,
Tottle Road,
Riverside Business Park, Nottingham, NG2 1RT
Tel: 0115 943 8230
Fax: 0121 200 0309

Site Plan
























This plan is Not to Scale

This plan is diagrammatic only and has been prepared to illustrate the general position of the property and its relationship to nearby trees etc. The boundaries are not accurate, and do not infer or confer any rights of ownership or right of way. Position of utilities is only indicative and contractors must satisfy themselves regarding actual location before commencing works.



© Bluesky International & © Infoterra 2006.
 Map Reproduced with the Permission of Ordnance Survey License Number #####

Key:

	Tree: Deciduous		Tree: Conifer		Shrub
	Hedge		Area of Damage		Bore Hole
	Trial Hole		Trial & Bore Hole		Level Monitoring
	Rain Water Manhole		Rain Water Gully		Rain Water Pipe
	Waste Water Manhole		Waste Water Gully		Toilet Pipe
	Rain Water Drain		Waste Water Drain		Electricity Cable
	Water Supply Pipe		Gas Supply Pipe		Incoming Gas Pipe
	Incoming Water		Incoming Electrics		

Chartered Loss Adjusters

INTRODUCTION

We have been asked by RSA to comment on movement that has taken place to the above property. We are required to briefly describe the damage, establish a likely cause and list any remedial measures that may be needed.

Our report should not be used in the same way as a pre-purchase survey. It has been prepared specifically in connection with the present insurance claim and should not be relied on as a statement of structural adequacy. It does not deal with the general condition of the building, decorations, timber rot or infestation etc.

The report is made on behalf of Crawford & Company and by receiving the report and acting on it, the client - or any third party relying on it - accepts that no individual is personally liable in contract, tort or breach of Statutory duty. Where works address repairs **that are not covered** by the insurance policy we recommend that you seek professional advice on the repair methodology and whether the works will involve the Construction (Design & Management) Regulations 2007. Compliance with these Regulations is compulsory; failure to do so may result in prosecution. We have not taken account of the regulations and you must take appropriate advice.

Investigations have been carried out in accordance with the requirements of The Institution of Structural Engineers¹.

We have not commented on any part of the building that is covered or inaccessible.

TECHNICAL CIRCUMSTANCES

The Insured noticed the damage in August and upon worsening of the damage notified Insurers. The property is grade 2 listed and had the basement excavated in 2013 to an approximate depth of 4m and approximate area of 100m². The planners would not allow any alteration of the footings to the front bay which is now the area of concern.

PROPERTY

The property comprises a two storey large detached house with basement of traditional construction with rendered walls surmounted by a pitched slate roof.

HISTORY & TIMESCALE

Site investigations are being organised and level monitoring established.

Date of Construction	Circa 1850
Purchased	2006
Policy Inception Date	13/12/2006
Damage First Noticed	August 2015
Claim Notified to Insurer.....	29/10/2015
Date of our Inspection.....	03/11/2015
Issue of Report	10/11/2015
Anticipated Completion of Claim	12/11/2015

TOPOGRAPHY

The property occupies a reasonably level site with no unusual or adverse topographic features.

¹ Institution of Structural Engineers (1994) "Subsidence of Low Rise Buildings"

GEOLOGY

Reference to the 1:625,000 scale British Geological Survey Map (solid edition) OS Tile number TQNW suggests the underlying geology to be London Clay.


London Clays are marine deposits characterised by their silty, sandy composition. They are typically stiff, dark or bluish grey, weathered dark to mid-brown superficially with fine particle size (less than 0.002mm). Tomlinson² describes it as a ‘fat’ clay with high loadbearing characteristics due to pre-consolidation pressures in its geological history.

The upper horizon is often encountered at shallow depth, sometimes just below ground level. They have high shrink/swell potentials^{3,4} and can be troublesome in the presence of vegetation.

The superficial deposits are thought to be Clay Soils.

Clay soil superficial deposits are a cohesive soil characterised by their fine particle size and are usually derived from weathering of an underlying “solid geology” clay soil such as London Clay or Oxford Clay.

Like the solid geology sub-soil from which they are derived they shrink when dry, and swell when wet and can be troublesome when there is vegetation⁵ nearby and Gypsum and selenite crystals can be encountered (particularly in the south east). Protection using Class II Sulphate Resisting cement is therefore recommended for buried concrete.



Geology. Reproduced with consent of The British Geological Survey at Keyworth.
Licence IPR/34-7C CSL British Geological Survey. ©NERC. All rights Reserved.

² Tomlinson M.J. (1991) *Foundations Design & Construction* Longman Scientific Publishing.

³ B.S. 5930 (1981) *Site Investigations*

⁴ Driscoll R. (1983) *Influence of Vegetation on Clays* Geotechnique. Vol 33.

⁵ Table 1, Chapter 4.2, Para. 2.3 of N.H.B.C. Standards, 1986.

⁶ Driscoll R. (1983) *Influence of Vegetation on Clays* Geotechnique. Vol 33.

VEGETATION


There are several trees and shrubs nearby, some with roots that may extend beneath the house foundations. The following are of particular interest:-

Type	Height	Distance	Ownership
Climbers	5 m	0 m	Owners
Deciduous	12 m	2 m	Owners
Shrubs	1 m	1 m	Owners
Deciduous	4 m	5 m	Owners
Deciduous	12 m	15 m	Owners

See sketch. Tree roots can be troublesome in cohesive (clay) soils because they can induce volumetric change. They are rarely troublesome in non-cohesive soils (sands and gravels etc.) other than when they enter drains, in which case blockages can ensue.

Climbers: Can be significant in subsidence cases as they are frequently planted close to the property, trained up house walls. As their roots do not need to spread to provide support they are frequently compact, and can have an intense but localised desiccation effect. Most tolerate pruning well, but respond by sprouting vigorously and need regular maintenance. Pyracantha or firethorn is common and has roots which cannot be distinguished anatomically from apple, pear and other members of the Pomoideae group of the rose family. Wistyeria roots are similar to those of other members of the pea family, including laburnum and false acacia.

Broadleaf trees typically have wider spreading roots and higher water demands than coniferous species and many are better adapted to growing on heavy clay soils. Some are capable of sprouting from cut stumps or bare wood and most will tolerate pruning better than conifers.



Typical proportions of a broadleaf tree. Note the potential root zone. It must be noted that every tree is different, and the root zone will vary with soil type, health of the tree and climatic conditions.

However heavy pruning of any tree should be avoided if possible, as it stimulates the formation of dense masses of weakly attached new branches which can become dangerous if not re-cut periodically to keep their weight down.

Shrubs. Sometimes even small shrubs can cause localised subsidence damage. In the Kew Garden Survey data was collected between 1979 - 86 to record the number of roots of each species received for identification. Of the 1009 roots identified, 367 (36%) belonged to the family *Rosoideae* or Rose. Next came the family *Oleaceae* (Forsythia, Jasmin, Privet and Lilac) with 354 (35%) enquiries.

Berberis, *Viburnum*, *Hedera* (ivy), *Hydrangea* and *Pyracanthus* are also regularly associated with foundation movement, the latter having surprisingly large roots on occasions.

Chartered Loss Adjusters

OBSERVATIONS

The front bay is the focal point of the Insured's concerns / movement

The following is an abbreviated description. Photographs accompanying this report illustrate the nature and extent of the problem.

INTERNAL

No damage internally.

EXTERNAL



Front Bay

Vertical tapering crack at either side of abutment up to 15mm wide.
 Separation between right hand bay pier and window frames up to 2mm wide.
 Various 1mm diagonal cracks above left hand window head.

CATEGORY

In structural terms the damage falls into Category 3 of Table 1, Building Research Establishment⁶ Digest 251, which describes it as **“moderate”**.

Category 0	"negligible"	< 0.1mm
Category 1	"very slight"	0.1 - 1mm
Category 2	"slight"	>1 but < 5mm
Category 3	"moderate"	>5 but < 15mm
Category 4	"severe"	>15 but < 25mm
Category 5	"very severe"	>25 mm

Extract from Table 1, B.R.E. Digest 251
 Classification of damage based on crack widths.

⁶ Building Research Establishment, Garston, Watford. Tel: 01923.674040

DISCUSSION

The pattern and nature of the cracks is indicative of an episode of subsidence. The cause of movement appears to be clay shrinkage.

The timing of the event, the presence of shrinkable clay beneath the foundations and the proximity of vegetation where there is damage indicates the shrinkage to be root induced. This is a commonly encountered problem and probably accounts for around 70% of subsidence claims notified to insurers.

Fortunately, the cause of the problem (dehydration) is reversible. Clay soils will re-hydrate in the winter months, causing the clays to swell and the cracks to close. Provided the cause of movement is dealt with (in this case, vegetation) there should not be a recurrence of movement.

RECOMMENDATIONS

Although the cause of the movement needs to be dealt with, we note the vegetation is subject to a Preservation Order. Unfortunately, current legislation requires certain investigations to be carried out to support an application for the tree works.

Typically, these investigations would involve trial pit(s) to determine the depth and type of footings, boreholes to determine the nature of the subsoil/influence of any roots and monitoring to establish the rate and pattern of movement. The monitoring data provided must be sufficient to show a pattern of movement consistent with the influence of the vegetation and therefore it may be necessary to carry out the monitoring for up to a 12 month period.

It will also be necessary to obtain a specialist Arboricultural Report.

We will report further once these investigations have been completed.

Gordon McEwan BSc (Hons) Building Surveying Cert CILA

Specialist Property Services - Subsidence Division

Direct Dial : 07500 891857

subsidence@crowco.co.uk

10th November 2015

PHOTOGRAPHS



Chartered Loss Adjusters



Chartered Loss Adjusters