



Airsafe Surveys Ltd

# Demolition / Refurbishment Asbestos Survey Report

Comissioned By

Merchant Land Investments Ltd

Site Address

61 – 65 Charlotte Street

London

W1T 4PF

Survey Conducted

31<sup>st</sup> March 2016



**Survey Conducted By**

Surveyors: A Porter & S Bewick

**Report Production**

Report Prepared by: A Porter

Date: 5<sup>th</sup> April 2016

Signature:



Report Proof-Read by: R Wren CCP (Asbestos)

Date: 5<sup>th</sup> April 2016

Signature:



**Contact Points**

Airsafe Surveys Ltd  
14 Normandy Street  
Alton  
Hampshire  
GU34 1BX

Tel: 01420 89990

Mr Andrew Porter  
(*Survey Manager*)

## **CONTENTS**

1.0 Executive Summary

1.1 – 1.3 Background

1.4 – 1.5 Scope & Purpose

1.6 – 1.9 Sources of Information

1.10 – 1.11 Presentation of Findings

1.12 Material Assessment Algorithm

1.13 CAR 2012 (exert regarding ACM removal)

2.0 References

Appendix A – Results of Laboratory Testing

Appendix B – Data Sheets

Appendix C – Summary of Findings

Appendix D – Plans

## 1.0 Executive Summary

Within the scope of this survey Asbestos Containing Materials (ACM's) have been identified. The incidence of asbestos and the actions recommended are summarised below.

Total number of suspect materials sampled **15**

Number of samples containing Asbestos **6**

Total Recommendations for:

- Remove **6**
- Encapsulate, label & manage in-situ **0**
- Label & manage in-situ **0**
- Manage in-situ **0**

Throughout the report the following colour coding is used.

<b>Red</b>	Laboratory analysis shows that <b>asbestos is present</b> in the recovered sample.
<b>Orange</b>	No laboratory analysis has been carried out because it was not possible to recover a sample at this location and it is <b>considered likely that asbestos is present</b> .
<b>Green</b>	Laboratory analysis shows that <b>asbestos is not present</b> in the recovered sample (NADIS)

### **Asbestos Insulation (lagging / sprayed insulation)**

- N/A

### **Asbestos Insulation Board**

- B09: No 65 – Basement, Stairwell – Board lining to under side of stairs

### **Asbestos Cement Products**

- B01: No 65 – 3<sup>rd</sup> Floor, External – Flue pipe on roof (runs into ceiling void above flat)
- B07: No 65 – GF, Shop – Cement panels to former fire place (located behind wooden panels)

### **Asbestos Textile Materials**

- B12: No 63 – GF, Hallway – Textile flash guards within switch gear

### **Asbestos Composite Materials**

- B05: No 65 – 1<sup>st</sup> Floor, Flat Kitchen – Sink pad
- B08: No 65 – GF, Shop, Rear External WC – Toilet cistern

### **Materials found to be NADIS (no asbestos detected in sample)**

- B02: No 65 – 3<sup>rd</sup> Floor, Stairwell – Board lining to riser
- B03: No 65 – 3<sup>rd</sup> Floor, Flat Kitchen – Panel under boiler
- B04: No 65 – 2<sup>nd</sup> & 1<sup>st</sup> Floors, Stairwell – Board lining to riser
- B06: No 65 – GF, Hallway – Floor lino

- B10: No 63 – GF, Shop – Bitumen lining to sink
- B11: No 63 – 1<sup>st</sup> Floor, Stairwell – Door panel on loose door
- B13: No 61 – 1<sup>st</sup> Floor, Throughout – Textile covers to ceiling down lights
- B14: No 61 – GF, Rear Gallery – Bitumen roof liner
- B15: No 61 – GF, Rear Gallery – Roof tiles

<b>Demolition / Refurbishment Asbestos Survey – General Building Description</b>	
<b>Area</b>	<b>Comments</b>
Roof	Mixture of natural slate & man-made slate
Loft Spaces	MMMF insulation, metal water tanks, hessian wrapped pipe work
Soffits	Wooden where present
Fascias	Wooden where present
Rain Water Goods	Plastic & Cast
Flues / Cows	Metal & Asbestos Cement
Cavity Walls	Brick / Block
Partition Walls	Plasterboard / Lath & Plaster / Wooden
Ceilings	Plasterboard / Lath & Plaster / Wooden
Window / Door Frames	No Suspect Materials
Floor Voids	Bare pipe work
Concealed Risers / Voids	Bare pipe work
Electrical Switchgear	Asbestos Textile flash guards in No 61
Plant / Equipment	Modern wall mounted boilers
Locked Areas	None

**Areas excluded from the scope of this survey**

- Voids beyond known or suspected asbestos containing materials were not accessed.
- Soil and land testing is not covered in the remit of this survey.
- Intrusive inspection was limited in the occupied flats in building 65.



## **Background**

- 1.1 Asbestos has been used extensively in the building industry for over one hundred years and has proved to be an excellent product for a variety of uses, having many qualities such as insulation, fire and chemical resistance. Its suitability across a wide range of uses and its relatively cheap cost made it very popular, with over 3,000 different asbestos products having been recorded.
- 1.2 The use of asbestos containing materials (ACM's) was most prevalent between the 1950's and 1970's when it provided an economic, easy to use and versatile material. Unfortunately, given the constitution and make up of asbestos it can give rise to microscopic airborne fibres being released into the working environment. The fibres have carcinogenic properties, which, when inhaled can lodge in the lining of the lungs causing disease and death.
- 1.3 For this reason the use of asbestos has receded and its use in buildings was eventually banned in 1999. Despite its ban, millions of tonnes of ACM's are still present in properties and buildings throughout the UK.

## **Scope and Purpose**

- 1.4 Merchant Land Investments Ltd has commissioned Airsafe Surveys Ltd to undertake a Demolition / Refurbishment Asbestos Survey of 61-65 Charlotte Street, London, W1T 4PF. The aim of the survey was to locate and identify the presence of ACM's or suspected ACM's, as far as is reasonably practicable. This report provides a record and assessment of the extent and characteristics of ACM's. It is assumed that all ACMs identified will be removed to enable demolition / refurbishment, therefore priority assessment scores are not given.
- 1.5 This type of survey employs the use of destructive sampling techniques of an unfamiliar site. Although every effort is made to locate all asbestos containing materials, it cannot be ruled out that undiscovered ACMs may be present in inaccessible areas due to the way that ACMs were used during construction. Therefore we cannot give assurances that all asbestos containing materials have been located and as such we recommend that further sampling be undertaken, should any suspect material become accessible during the course of any demolition / refurbishment works.

## **Site Description & Survey Purpose**

The site surveyed consists of 3 adjacent buildings which contain shops / gallery on the lower levels with three floors of residential above. The flats in No 65 are still occupied. This building is to be refurbished.

## **Sources of Data**

### **Background Information**

- 1.6 No background information was available concerning the location of asbestos-containing materials within the buildings on the site.

### **Inspection, sampling and testing**

- 1.7 Airsafe Surveys Ltd carried out a visual inspection of the buildings. The purpose of the inspection was to identify locations where the presence of asbestos is suspected, and to make arrangements for the recovery and testing of representative samples, where practicable. The inspection also enabled informed judgements to be made about the likelihood of asbestos being present in situations where samples could not be recovered.
- 1.8 Based on the findings of the visual inspection, representative bulk samples of materials suspected of containing asbestos were recovered. During the sampling process, care was taken to verify that the recovered samples were representative of the situation and the medium in which asbestos contamination was suspected. The sampling protocol that was used is as specified in HSG264 (Asbestos: The Survey Guide), published by the Health & Safety Executive.
- 1.9 The recovered samples were subsequently examined by Airsafe Analytical Ltd (UKAS number: 4376) to establish their asbestos content, in accordance with their in-house procedures and HSG248 (Asbestos: The analysts' guide for sampling, analysis and clearance procedures), published by the Health & Safety Executive. The analysis certificate is presented in Appendix A.

## **Presentation of Findings**

### **Data Sheets**

- 1.10 A series of data sheets provide assessments and recommendations for each of the locations where samples were taken. These data sheets are presented in Appendix B. The information in the data sheets is summarised in Appendix C.

### **Plans**

- 1.11 Asbestos location plans presented in Appendix D if supplied by client at the time of the survey, shows the locations of all materials found to contain Asbestos (ACM's). Additionally areas of no access, if applicable, will be highlighted on the plans.

## **Material Assessment Algorithm**

1.12 A material assessment algorithm for potential of fibre release has been carried out for all asbestos materials found, based on their product type, condition (extent of damage/deterioration), surface treatment and asbestos type. The method adopted is as described below;

<b>Sample Variable</b>	<b>Score</b>	<b>Examples of scores</b>
Product Type (or debris from product)	1	Asbestos-reinforced composites (plastics, resins, mastics, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc.).
	2	AIB, millboards, other low-density insulation boards, asbestos textiles, gaskets, ropes & woven textiles, asbestos paper & felt.
	3	Thermal insulation (e.g. pipe & boiler lagging), sprayed asbestos, loose asbestos, asbestos mattresses & packing.
Extent of Damage / Deterioration	0	Good Condition
	1	Low Damage
	2	Medium Damage
	3	High Damage
Surface Treatment	0	Composite materials (reinforced plastics, resins, vinyl tiles)
	1	Enclosed sprays & lagging, AIB (with exposed face painted or encapsulated), asbestos cement
	2	Unsealed AIB, or encapsulated lagging & sprays
	3	Unsealed lagging & sprays
Asbestos Type	1	Chrysotile
	2	Amphibole asbestos excluding crocidolite
	3	Crocidolite
<b>Score</b>		<b>Potential to release fibres</b>
10 or more		High
7 – 9		Medium
5 – 6		Low
4 or less		Very Low

## **Control of Asbestos Regulations**


1.13 The Control of Asbestos Regulations 2012 (CAR) applies to most work situations involving risk of exposure to asbestos. CAR requires that employers:

- Take all reasonable steps to identify the locations of materials likely to contain asbestos.
- Assume that the identified materials contain asbestos, unless there is evidence to the contrary.
- Keep an up to date written record (an **Asbestos Register**) of the location of asbestos-containing materials.
- Monitor the condition of asbestos-containing materials.
- If any remedial / removal works are required it should be determined whether the work is licensed, notifiable non-licensed or non-licensed. This has to be determined in each case and will depend on the type of work being carried out, the type of material and its condition (as shown in the decision flow chart below).
  - Some non-licensed work needs to be notified to the relevant enforcing authority.
  - Brief written records should be kept of non-licensed work, which has to be notified e.g. copy of the notification with a list of workers on the job, plus the level of likely exposure of those workers to asbestos. This does not require air monitoring on every job, if an estimate of degree of exposure can be made based on experience of similar past tasks or published guidance.
  - By April 2015, all workers / self-employed carrying out notifiable non-licensed work with asbestos must be under health surveillance by a Doctor. Workers who are already under health surveillance for licensed work need not have another medical examination for non-licensed work. BUT medicals for notifiable non-licensed work are not acceptable for those carrying out licensed work
- Make a written assessment of the risk of exposure from asbestos.
- The Regulations require mandatory training for anyone liable to be exposed to asbestos fibres at work. This includes maintenance workers and others who may come into contact with or who may disturb asbestos as well as those involved in asbestos removal work.
- Prepare and implement a **management plan** to control asbestos-related health risks, including measures to ensure that:
  - Materials known or presumed to create a risk of exposure to asbestos is repaired or, if necessary removed.

- Materials known or presumed to contain asbestos, but which does not pose a risk of exposure, are maintained in a good state of repair.
- Information about the location and condition of materials known or presumed to contain asbestos are given to anyone likely to disturb them.

**Decision flow chart**

Use this simple flow chart to help you decide who needs to do the work:



## **2.0 REFERENCES**

- (1) HSG264 Asbestos: The Survey Guide**  
*HSE Books*
- (2) HSG248 Asbestos: The analysts ' guide for sampling, analysis and clearance procedures.**  
*Methods for the Determination of Hazardous Materials, HSE Books*
- (3) HSG227 A Comprehensive Guide to Managing Asbestos in Premises**  
*HSE Books*
- (4) The Control of Asbestos Regulations 2012**
- (5) Working with materials containing Asbestos**  
*Approved Code of Practice (CAR 2012)*

# Appendix A


Results of Laboratory Testing  
(Bulk Sample Identification Certificates)

**Certificate of Analysis**

<b>Job Number :</b>	<b>AA7280</b>	<b>Date :</b>	<b>05/04/16</b>	<b>Analyst :</b>	<b>AP</b>
<b>Name &amp; Address of Client :</b>			<b>Site Address :</b>		
Merchant Land Investments			61 – 65 Charlotte Street		
66 Leman Street			London		
London					
<b>Postcode :</b>	<b>E1 8EU</b>	<b>Tel :</b>		<b>Postcode :</b>	<b>W1T 4PF</b>
<b>Date Samples Taken :</b>	<b>31/03/16</b>	<b>Certificate Number :</b>	<b>1 of 2</b>		
<b>Date Samples Received :</b>	<b>03/04/16</b>	<b>Total Number of Samples :</b>	<b>15</b>		
<b>Date of Analysis :</b>	<b>05/04/16</b>	<b>Clients Representative :</b>	<b>Seamus Porter</b>		
<p>Samples collected by the client are evaluated using information provided by the client at the time of delivery. Airsafe Analytical Limited are not responsible for the accuracy and / or competence of the sampling by third parties. Under these circumstances Airsafe Analytical Limited cannot be held responsible for the interpretation of the results shown.</p> <p>All samples of material, detailed below, have been examined to determine the presence of Asbestos fibres using Polarised Light Microscopy and the McCrone Dispersion Staining Technique in accordance with Airsafe Analytical Limited's documented "in-house" procedures which are based on the HSE's guidance note HSG248 - Asbestos: The Analysts' guide for sampling analysis and clearance procedures.</p>					
<b>AA Sample Reference</b>	<b>Client Sample Number</b>	<b>Sample Description / Material Type</b>		<b>Fibre Type Detected</b>	
B01		Flue pipe		CHRYBOTILE	
B02		Riser panel		NADIS	
B03		Boiler panel		NADIS	
B04		Riser panel		NADIS	
B05		Sink pad		CHRYBOTILE	
B06		Lino		NADIS	
B07		Fire place panel		CHRYBOTILE	
B08		Toilet cistern		AMOSITE	
<p>NADIS = No Asbestos Detected In Sample</p> <p>All samples will be retained by the laboratory for a minimum of 6 months from the date the samples were received.</p>					
<b>Authorised By :</b>	<b>R. Wren</b>	<b>Date :</b>	<b>05/04/16</b>	<b>Time :</b>	<b>1544</b>
<b>Signature :</b>					
<b>ISSUE NUMBER</b>	<b>6</b>	<b>DATE</b>	<b>DEC 2015</b>		



**Certificate of Analysis**

<b>Job Number :</b>	AA7280	<b>Date :</b>	05/04/16	<b>Analyst :</b>	AP
<b>Name &amp; Address of Client :</b>			<b>Site Address :</b>		
Merchant Land Investments			61 – 65 Charlotte Street		
66 Lemn Street			London		
London					
<b>Postcode :</b>	E1 8EU	<b>Tel :</b>		<b>Postcode :</b>	W1T 4PF
<b>Date Samples Taken :</b>	31/03/16	<b>Certificate Number :</b>	2 of 2		
<b>Date Samples Received :</b>	03/04/16	<b>Total Number of Samples :</b>	15		
<b>Date of Analysis :</b>	05/04/16	<b>Clients Representative :</b>	Seamus Porter		
<p>Samples collected by the client are evaluated using information provided by the client at the time of delivery. Airsafe Analytical Limited are not responsible for the accuracy and / or competence of the sampling by third parties. Under these circumstances Airsafe Analytical Limited cannot be held responsible for the interpretation of the results shown.</p> <p>All samples of material, detailed below, have been examined to determine the presence of Asbestos fibres using Polarised Light Microscopy and the McCrone Dispersion Staining Technique in accordance with Airsafe Analytical Limited's documented "in-house" procedures which are based on the HSE's guidance note HSG248 - Asbestos: The Analysts' guide for sampling analysis and clearance procedures.</p>					
<b>AA Sample Reference</b>	<b>Client Sample Number</b>	<b>Sample Description / Material Type</b>		<b>Fibre Type Detected</b>	
B09		Under stairs panel		AMOSITE	
B10		Sink pad		NADIS	
B11		Door panel		NADIS	
B12		Flashguards		CHRYSTILE	
B13		Light covers		NADIS	
B14		Roof liner		NADIS	
B15		Roof tiles		NADIS	
<p>NADIS = No Asbestos Detected In Sample</p> <p>All samples will be retained by the laboratory for a minimum of 6 months from the date the samples were received.</p>					
<b>Authorised By :</b>	R. Wren	<b>Date :</b>	05/04/16	<b>Time :</b>	1546
<b>Signature :</b>					
<b>ISSUE NUMBER</b>	6	<b>DATE</b>	DEC 2015		

# Appendix B

Data Sheets

Sample Ref: B01

Location: No 65 - 3rd Floor, External



Material Sampled: Asbestos Cement flue pipe  
(runs into ceiling void above flat)

Analysis Result: **Chrysotile (white) Asbestos**

Approximate Quantity: 2 LM

Product Type: **Asbestos Re-inforced Composites**

Condition: **Good Condition**

Surface Treatment: **Cement / Sealed AIB / Enclosed Lagging**

Material Assessment Score: **3**

Remarks / Recommendations: Remove.

Sample Ref: B02

Location: No 65 - 3rd Floor, Stairwell



Material Sampled: Board lining to riser

Analysis Result: **No Asbestos Detected**

Approximate Quantity:

Product Type:

Condition:

Surface Treatment:

Material Assessment Score: **0**

Remarks / Recommendations:

Sample Ref: B03

Location: No 65 - 3rd Floor, Flat Kitchen



Material Sampled: Panel below boiler

Analysis Result: **No Asbestos Detected**

Approximate Quantity:

Product Type:

Condition:

Surface Treatment:

Material Assessment Score: **0**

Remarks / Recommendations:

Sample Ref: B04

Location: No 65 - 2nd & 1st Floors, Stairwell



Material Sampled: Board lining to riser

Analysis Result: **No Asbestos Detected**

Approximate Quantity:

Product Type:

Condition:

Surface Treatment:

Material Assessment Score: **0**

Remarks / Recommendations:

Sample Ref: B05

Location: No 65 - 1st Floor, Flat Kitchen



Material Sampled: Asbestos Composite sink pad

Analysis Result: **Chrysotile (white) Asbestos**

Approximate Quantity: <1 Sqm

Product Type: **Asbestos Re-inforced Composites**

Condition: **Good Condition**

Surface Treatment: **Composite Materials**

Material Assessment Score: **2**

Remarks / Recommendations: Remove.

Sample Ref: B06

Location: No 65 - GF, Hallway



Material Sampled: Floor lino

Analysis Result: **No Asbestos Detected**

Approximate Quantity:

Product Type:

Condition:

Surface Treatment:

Material Assessment Score: **0**

Remarks / Recommendations:

Sample Ref: B07

Location: No 65 - GF, Shop



Material Sampled: Asbestos Cement panels to former fire place  
(located behind wooden panels)

Analysis Result: **Chrysotile (white) Asbestos**

Approximate Quantity: 3 Sqm

Product Type: **Asbestos Re-inforced Composites**

Condition: **Good Condition**

Surface Treatment: **Cement / Sealed AIB / Enclosed Lagging**

---

Material Assessment Score: **3**

---

Remarks / Recommendations: Remove.

Sample Ref: B08

Location: No 65 - GF, Shop, Rear External WC



Material Sampled: Asbestos Composite toilet cistern

Analysis Result: **Amosite (brown) Asbestos**

Approximate Quantity: 1 Item

Product Type: **Asbestos Re-inforced Composites**

Condition: **Good Condition**

Surface Treatment: **Composite Materials**

---

Material Assessment Score: **3**

---

Remarks / Recommendations: Remove.

Sample Ref: B09

Location: No 65 - Basement, Stairwell



Material Sampled: Asbestos Insulation Board lining under stairs

Analysis Result: **Amosite (brown) Asbestos**

Approximate Quantity: 3 Sqm

Product Type: **AIB / Millboards / Textiles**

Condition: **Good Condition**

Surface Treatment: **Cement / Sealed AIB / Enclosed Lagging**

---

Material Assessment Score: **5**

---

Remarks / Recommendations: Remove.

This form of Asbestos can only be removed by a licensed contractor.



Sample Ref: B10

Location: No 63 - GF, Shop



Material Sampled: Bitumen lining to sink

Analysis Result: **No Asbestos Detected**

Approximate Quantity:

Product Type:

Condition:

Surface Treatment:

Material Assessment Score: **0**

Remarks / Recommendations:

Sample Ref: B11

Location: No 63 - 1st Floor, Stairwell



Material Sampled: Door panel (to rear of door)

Analysis Result: **No Asbestos Detected**

Approximate Quantity:

Product Type:

Condition:

Surface Treatment:

Material Assessment Score: **0**

Remarks / Recommendations:

Sample Ref: B12

Location: No 63 - GF, Hallway



Material Sampled: Asbestos Textile flash guards within switch gear

Analysis Result: **Chrysotile (white) Asbestos**

Approximate Quantity: <1 Sqm

Product Type: **AIB / Millboards / Textiles**

Condition: **Good Condition**

Surface Treatment: **Composite Materials**

Material Assessment Score: **3**

Remarks / Recommendations: Remove.

Sample Ref: B13

Location: No 61 - 1st Floor, Throughout



Material Sampled: Textile covers to ceiling down lights

Analysis Result: **No Asbestos Detected**  
Approximate Quantity:  
Product Type:  
Condition:  
Surface Treatment:

Material Assessment Score: **0**

Remarks / Recommendations:

Sample Ref: B14

Location: No 61 - GF, Rear Gallery



Material Sampled: Bitumen roof liner

Analysis Result: **No Asbestos Detected**  
Approximate Quantity:  
Product Type:  
Condition:  
Surface Treatment:

Material Assessment Score: **0**

Remarks / Recommendations:

Sample Ref: B15

Location: No 61 - GF, Rear Gallery



Material Sampled: Roof tiles

Analysis Result: **No Asbestos Detected**  
Approximate Quantity:  
Product Type:  
Condition:  
Surface Treatment:

Material Assessment Score: **0**

Remarks / Recommendations:

# Appendix C


## Summary of Findings



No	Location	Material Sampled	Asbestos Content	Quantity
B01	No 65 - 3rd Floor, External	Asbestos Cement flue pipe	Chrysotile (white) Asbestos	2 LM
B02	No 65 - 3rd Floor, Stairwell	Board lining to riser	No Asbestos Detected	N/A
B03	No 65 - 3rd Floor, Flat Kitchen	Panel below boiler	No Asbestos Detected	N/A
B04	No 65 - 2nd & 1st Floors, Stairwell	Board lining to riser	No Asbestos Detected	N/A
B05	No 65 - 1st Floor, Flat Kitchen	Asbestos Composite sink pad	Chrysotile (white) Asbestos	<1 Sqm
B06	No 65 - GF, Hallway	Floor lino	No Asbestos Detected	N/A
B07	No 65 - GF, Shop	Asbestos Cement panels to former fire place	Chrysotile (white) Asbestos	3 Sqm
B08	No 65 - GF, Shop, Rear External WC	Asbestos Composite toilet cistern	Amosite (brown) Asbestos	1 Item
B09	No 65 - Basement, Stairwell	Asbestos Insulation Board lining under stairs	Amosite (brown) Asbestos	3 Sqm
B10	No 63 - GF, Shop	Bitumen lining to sink	No Asbestos Detected	N/A
B11	No 63 - 1st Floor, Stairwell	Door panel (to rear of door)	No Asbestos Detected	N/A
B12	No 63 - GF, Hallway	Asbestos Textile flash guards within switch gear	Chrysotile (white) Asbestos	<1 Sqm
B13	No 61 - 1st Floor, Throughout	Textile covers to ceiling down lights	No Asbestos Detected	N/A
B14	No 61 - GF, Rear Gallery	Bitumen roof liner	No Asbestos Detected	N/A
B15	No 61 - GF, Rear Gallery	Roof tiles	No Asbestos Detected	N/A

# Appendix D

## Asbestos Location Plan




3rd Floor

**Airsafe Surveys Ltd**  
14 Normandy St  
Alton, Hants  
GU34 1BX  
01420 89990  
andy@airsafe.org.uk

**Client**  
Merchant Land  
Investments Ltd

**Site**  
61 - 65 Charlotte Street  
London

**Key**  
  
Asbestos Cement  
flue pipe

**B\*\***  
Denotes NADIS  
sample

Not to Scale

**Airsafe Surveys Ltd**  
14 Normandy St  
Alton, Hants  
GU34 1BX  
01420 89990  
andy@airsafe.org.uk

**Client**  
Merchant Land  
Investments Ltd

**Site**  
61 - 65 Charlotte Street  
London


**Key**




Asbestos Composite  
sink pad

**B\*\***  
Denotes NADIS  
sample

Not to Scale



**01** First Floor Plan  
Scale 1:500(A1), 1:1000(A3)



**02** Second Floor Plan  
Scale 1:500(A1), 1:1000(A3)


**Airsafe Surveys Ltd**  
14 Normandy St  
Alton, Hants  
GU34 1BX  
01420 89990  
andy@airsafe.org.uk

**Client**  
Merchant Land  
Investments Ltd

**Site**


61 - 65 Charlotte Street  
London

**Key**

  
Asbestos Cement fire  
place panels

**B12**  
Asbestos Textile  
flash guards

**B\*\***  
Denotes NADIS  
sample



**00** Ground Floor Plan  
Scale 1:500(A1, 1:1000(A3))

Not to Scale

**Airsafe Surveys Ltd**  
14 Normandy St  
Alton, Hants  
GU34 1BX  
01420 89990  
andy@airsafe.org.uk

**Client**  
Merchant Land  
Investments Ltd

**Site**  
61 - 65 Charlotte Street  
London

**Key**




Asbestos Insulation  
Board to under stairs

**B08**

Asbestos Composite  
toilet cistern

**B\*\***

Denotes NADIS  
sample



**05** Lower Ground Floor Plan  
Scale 1:500 (A1, 1:1000 (A2))

Not to Scale