

**Rose Cottage, Vale of Health, Hampstead , London.**

### **Structural Overview**

On May 8 2017 I visited this cottage and, together with the help of a builder, I was able to determine the sizes of most of the main structural elements, and see some of the defects.

### **Brief Description of Existing Structure**

**Walls.** The walls are mainly brickwork, though they contain horizontal timber “bond beams” built in at 900mm vertical intervals. Some rot in these timbers is inevitable, especially since the external walls are only 112mm thick brick with render outside and plaster inside. Ideally, the rotten timber should be removed, though this would mean taking off the plaster. It seems that the party wall with the next door cottage is also only 112mm thick brick in between the chimney stacks. The outside wall of the rear extension has settled, and there are some fresh cracks suggesting that movement is ongoing.

**Chimneys.** There are 3 chimney stacks, all brick, and of squat proportions. 2 of these 3 chimneys are prominent, and 1 virtually invisible. The 2 chimneys in the main front part of the house are shared with the neighbouring cottage, and these project approx. 18 brick courses above the clay tiled roof. The third chimney in the rear extension sits almost behind the ridge of the double pitched roof, making it difficult to see from street level.

**Roof.** The main roof has adequate timber framing visible within the large loft space. Some timbers have been renewed recently. Rafters are 125 x 50 at 400mm c/s. Both purlins are 75 x 225mm, and these are propped at centre span by a truss which spans from front to central wall to back. Ceiling joists are 100 x 50 (generous for a property this age (approx. 1810)). The pantile roof is adequately supported. The lead lined timber rear gutter needs attention since it is blocked.

The rear extension is slated, and these slates seem to have been recently re-laid. There was no access into the small triangular loft above the bedroom ceiling, though boarding was visible above the ceiling joists, and perhaps this is evidence of a former flat roof.

**First Floor.** For the main part of the house the joists run from front to back, and must be carried by a beam in the centre, visible in the ceiling of the ground floor room. For the extension, joists (125x 50) run from party wall to the external side wall (span 2.4m). Some joists have been weakened by deep notches where pipes have been threaded, and the joist ends bearing on the thin outside wall were hardly adequate, so all these need inspection and may need repair.

**Ground Floor.** Some of the timber joists are rotten, because there has been a long term damp problem, partly because the external paving is too high, and partly because there is inadequate underfloor ventilation. It is hard to see how to reinstate this timber without a lot of excavation to improve air flow. A solid floor may be the answer.

**External Paving.** The stone paving covers the thresholds, and without adequate measures to deal with surface water drainage, there will continue to be a damp problem, especially at door openings.

**Balcony.** This timber structure seems to have settled slightly, since it is pulling away from the front wall. The handrail of the balustrade is rather lower, and the open apertures do not comply with modern building regulations.


**6 principal measures** are suggested, and these are shown on drawings 1 and 2, and the photos of the balcony:

1. The first floor joist ends where they bear on the outside wall of the should all be inspected, and if there is rot or less than 75mm of bearing, then repair work should be done. Likewise, the buried horizontal timber bond beams within the external walls should be located, inspected and probably cut out and replaced with masonry. Since the wall is only 112mm thick, this will affect internal plaster and external render.
2. A new ground floor slab made of reinforced concrete should be introduced to form a raft foundation, with the ends tucked into the masonry walls on all 4 sides. This raft will reduce the risk of further settlement.
3. The chimney stack in the rear extension provides lateral stability, so new slender steel portal frames are needed when the masonry stack is removed. This steel frame could carry the weight of the top part of the chimney as it passes through the roof.
4. Larger deeper foundations are needed under the 2 posts which hold up the balcony. This will reduce the likelihood of further settlement.
5. Because the balcony posts are not strong enough to resist accidental outward load, the balustrade of the balcony needs to be strengthened, and a higher handrail ought to be added. The slender diagonal balusters are also too weak, and small steel flats could be added almost invisibly in order to make them stronger
6. Paving should be lowered, and falls for drainage improved.

Philip Cooper FStructE  
Structural Engineer. CAR Ltd

June 13 2017

First Floor :-  
 ① Inspect & Repair Joist Ends  
 New insulated lining




③ Pair of 2 Storey Steel Portal Frames, rigid joints, made from New french doors to 100x100x 6.3mm thick RHS match style of existing windows

⑤ Balustrade Strengthening New handrail, steel flat or tube. Balustrade to be replaced / m/c (TBC)




② New 150 thick RC slab 2 layers B1131 mesh reinforcement with 225x102 hit & miss reinforced tongues @ 675c/s around perimeter


④ New 400x400 plain Concrete Bases For Balcony columns.



2 No Portal Frames Like This  
 All members 100x100x6.3 RHS



③ Pair of steel Portals




② New 150thick R.C. Slab. 2 layers B1131 mesh

# Rose Cottage

existing handrail 60x45  
wide deep

existing 4 posts 62x45 mm

May 19 2017 p.4




Handrail span 1.83m  
if 0.75 kN/m applied  
 $W = 0.75 \times 1.83 = 1.37 \text{ kN}$   
 $M = 1.37 \times 1.83 / 8 = 0.314 \text{ kNm}$   
 $\frac{M}{Z} = \frac{0.314 \times 10^6 \times 6}{45 \times 60^2} = 11.6 \text{ N/mm}^2$

allowable short term if c24 wood,  
 $= 7.5 \times 1.5 = 11.25 \text{ N/mm}^2$  just under  
11.6, but probably OK since margin  
of safety.

Look at Joints. will handrail to post take  
 $1.37/2 = 0.685 \text{ kN}$ . I think it will since  
I gave it a sharp tug, and no sign of  
weakness.

So, handrail is just strong enough based  
on calcs but should be load tested with  
Horiz load to check. Put horiz load  
of  $1.37/2 = 0.685 \text{ kN} = 68.5 \text{ kg}$  as point  
load centre span to verify

NB. Handrail only 900 high  
Not 1100 high as Building Regs



Posts height 2.2m.

if 0.75 kN/m applied to handrail, and if handrail  
was 1.5m high; then  $W = 1.5 \times 0.75 = 1.125 \text{ kN}$

$$M = 1.125 \times \frac{2.2}{4} = 0.618 \text{ kNm}$$

$$\frac{M}{Z} = \frac{0.618 \times 10^6 \times 6}{45 \times 62^2} = 21.4 \text{ N/mm}^2 \text{ Fails}$$

Small Baluster 22x33mm (wood)

diagonal spans 1.1m what point load would overload?

if max stress = 11.25  $\sigma Z = 11.25 \times \frac{22 \times 33^2}{6} = 44921 \text{ Nmm}$

$$\frac{P \times 1100}{4} = 44921$$

$P = 163 \text{ N} = 16 \text{ kg}$  very low - Not strong enough - Balusters  
should be swapped for steel.

New 25x25 steel  
handrail white  
at 1100 above deck

Extra 45x45 timber  
(taper if desired)  
glued & screwed to  
inside (back face) of  
2 vertical posts at  
both ground to 1st  
and 1st to Roof.






45 x 45 or tapered wood inside


New addition 25 x 25 steel white

1100 mm

Add 45 x 45 wood, glue & screw paint wood



X SECTION THRO POSTS.



Tie Back Through Wall

New 25 x 25 steel

Add 45 x 45 wood (could taper if desirable thinner top & bottom, max 45 mm in middle)

SECTION

New Foundation