






Third Floor Bedroom looking south



Existing Internal View 2  
Third Floor  
Int. 01




Third Floor Bedroom looking east to opening in white box



Existing Internal View 2  
Third Floor  
Int. 01




Third Floor Master ensuite looking east



Existing Internal View 2  
Third Floor  
Int.01




Third Floor Master bedroom looking west



Existing Internal View 2  
Third Floor  
Int.01




View from opening in Third Floor bedroom looking west towards windows in Main Hall




Existing Internal View 2  
Third Floor  
Int.01




View from opening in Third Floor bedroom looking south-west towards balconies on western historic brick wall



Existing Internal View 2  
Third Floor  
Int.01




View from from Third Floor down elevator shaft, towards the East



Existing Internal View 2  
Third Floor  
Int.01




View to south in Third Floor bedroom



Existing Internal View 2  
Third Floor  
Int.01




Fourth Floor Roof Terrace looking North



Existing Internal View 2  
Fourth Floor  
Int. 01




Fourth Floor Roof Terrace looking south



Existing Internal View 2  
Fourth Floor  
Int. 01




View to the North showing the openable roof light



Existing Internal View 2  
Roof  
Int. 01




View to the North at roof level showing wall of 22 Stukeley Street and the openable roof light



Existing Internal View 2  
Roof  
Int.01



View to the East from the southern end of the roof showing access opening




PAXTON LOCHER ARCHITECTS, 8 CLERKENWELL GREEN, LONDON EC1R 0DE TEL: 0171 251 6645 FAX: 0171 251 6646

058/4.1/EJP/LJC  
3rd March 1999

*Submission of planning and  
Listed building Consent Details*

Ms Rebecca Peterson  
Director of Environment  
Development Control  
Planning Services  
London Borough of Camden  
Camden Town Hall  
Argyle Street  
London, WC1H 8NL

*Plan nos. P59904233  
L59904234*



Dear Ms Peterson

**RE: 23 MACKLIN STREET, COVENT GARDEN WC2**

Further to our letter dated 28th January 1999, details for the final contract are now being completed. These include the internal fitout, existing building fabric repairs and works to the external elevations.

We enclose details in relation to the outstanding conditions.

Planning conditions (P)

(2) P1. Front elevation

Revised elevation enclosed reflecting initial comments.

P4. Overlooking to the courtyard

Revised courtyard elevation enclosed. Glass to windows proposed as obscured. Glass to doors to be clear with internal blinds. Trellis detail to be agreed with adjacent neighbour to avoid any overlooking prior to occupation. Details will then be submitted.

Listed Building consent conditions (LBC)

LBC1. Front elevation

Revised elevation enclosed.

LBC2. Visible Services

RWPs reused or replaced to match existing and retained in original locations.  
Flues to rear enclosed in patinated lead or zinc panelling.

LBC4. a) Specification of repairs - see specialist timber and brickwork reports

(3) a, c, e) c) Brickwork repairs - see specialist report enclosed.  
*(P29)*

REGISTERED OFFICE: TORRINGTON HOUSE, 47 HOLYWELL HILL, ST ALBANS, HERTS AL1 1HD REGISTERED IN ENGLAND NO.2775003

PAXTON LOCHER ARCHITECTS, 8 CLERKENWELL GREEN, LONDON EC1R 0DE TEL: 0171 251 6645 FAX: 0171 251 6646

- e) Brickwork cleaning - see specialist report enclosed.
- f) New external joinery - see elevation drawings enclosed.
- g) Render to front elevation - a sample panel has been exposed. See specialist report for details of proposed removal and restoration work.

We trust that the above items and enclosed information replies satisfactorily to the conditions.

Yours sincerely

*Heidi Locher*

Heidi Locher

Please distribute to all relevant parties including:

Delcia Keate - English Heritage  
Mrs Leonard - Conservation Officer

cc: Alain Perrin  
Peter Baillie - Baillie Knowles Partnership  
Andy Downey - Elliott Wood Partnership

REGISTERED OFFICE: TORRINGTON HOUSE, 47 HOLYWELL HILL, ST ALBANS, HERTS AL1 1HD REGISTERED IN ENGLAND NO.2775003

05/03 '99 16:46 FAX 0181 544 0066 ELLIOTT WOOD 01



For the attention of: Liz Pearson Date: 5-3-1999  
Company: Paxton Locher Job No: 98046  
Fax No: 01712516646 From: Andy  
Ref: 23 Macklin Street No of pages: 1

**MESSAGE**

Structural Implications of the Proposed Remedial Works to the Front Elevation.

The existing front elevation comprises four robust brickwork piers with spandrel panels supported on arches/lintels between them. The brickwork piers are very robust, approximately 780mm thick by 1350mm wide. The remedial works consist of removing the hard cement render from this wall and making good the original brickwork currently hidden from view. Trial panels have shown that the render is very hard and well bonded to the brickwork. It is likely that areas of brickwork will be damaged during render removal and as such brick replacement will be necessary.

In the affected areas it is proposed that the outer half brick (approx. 100mm) be removed and replaced with reclaimed bricks. These new bricks will be laid in a lime mortar to match the existing and tied back to the main section of the wall using stainless steel wavy tail ties. All voids will be filled with lime mortar to ensure that the finished wall acts homogeneously. These works will need careful co-ordination to allow the slow setting lime mortars to go off before undertaking successive lifts.

The works will also involve the rebuilding of the existing spandrel panels and arches/lintels over windows and doors. These elements are currently in very poor condition, and require rebuilding using reclaimed bricks and mortars to match the existing.

These brickwork repairs will be undertaken once the new internal floors are complete. These floor levels will restrain the brickwork at approximately 2.7m centres vertically. Given this, the overall size of the existing piers, and the sequencing necessitated by the lime mortar, removal of the outer skin is eminently feasible.

We must also stress the high level of workmanship that is required for this type of work.

Regards  
Andy

Elliott Wood Partnership • Consulting Structural and Civil Engineers • 2nd Floor • Broadway House • 112-134 The Broadway  
London SW10 1RL • Telephone: 0181 544 0033 • Facsimile 0181 544 0066 • Email:elliottwood@compuserve.com  
Partners: P.F.Wood BEng, CEng, MICE, MStructE • G.J.Elliott BEng (Hons), CEng, MStructE • D.N.Morgan MEng, CEng, MStructE

**RIDOUT ASSOCIATES**  
147a Worcester Road,  
Hagley, Stourbridge,  
West Midlands DY9 0NW.  
Telephone: 01562 885135 Facsimile: 01562 885312.

TIMBER DECAY ANALYSTS  
DAMP CONSULTANTS  
ENVIRONMENTAL MONITORING  
RESEARCH



26 June 1998

Andy Downey  
Elliott Wood Partnership  
Nelson House  
271 Kingston Road  
LONDON  
SW19 3NW

Dear Andy

**23 Macklin Street, London WC2: Project number 98046**

We visited 23 Macklin Street on 5 June 1998, and have carried out a timber decay survey of the exposed roof timbers. Where appropriate, the integrity of the timbers was investigated with a non destructive decay detecting drill. This instrument pushes a 1mm diameter steel probe into the timber at constant pressure. Resistance to pressure, correlating with timber density, is recorded on a revolving chart.

Twenty paint samples were removed from the walls (18 from the upper floor area and 2 at ground floor level) and these are undergoing analyses which will detect the presence of lead. Three salt samples were also removed, two from the wall surface, and one from a rafter.

We are required by our insurers to state that we have not inspected woodwork which is covered, unexposed or inaccessible and we are therefore unable to report on the condition of any such woodwork. Nevertheless based on our inspection of the uncovered, exposed and accessible areas, the following is our opinion.

**Roof timbers (figure 1)**

Figure 1 shows a sketch plan of the main roof timbers. Rafters rest on a small section plate (75mm x 125mm) which is notched into the tie beams. The rafter plate spans the tie beams with small brick supporting piers between. The plate is usually separated from the brickwork by slate.

Tie beams rest on a large section wall plate (200mm x 150mm) and most beam ends are not embedded into the brickwork. There is a gap behind the wall plate and the masonry supporting the rafter plate. This gap varies in size, but is filled with debris

Directors: Dr. B.V. Ridout Managing Dr. E.A. Ridout Data Analysis Dr. L.J. Chapman Research  
Ridout Associates is a Division of Scientific and Educational Services Ltd.,  
Reg Office: 147a Worcester Road, Hagley, Stourbridge, West Midlands DY9 0NW. Co Reg No 2090912

Stamp: PAXTON LOCHER ARCHITECTS  
29 JUN 1998  
COPY  
RP ✓  
ML ✓  
EP ✓