

Summary Of Structural Assessment And Strengthening Works Required

The capacity of the existing structural elements have been checked against the required loadings to the Eurocodes. Below is a summary of the assessment identifying any elements which require strengthening as part of the refurbishment works:

Existing Timber Spine Beam Assessment:

The spine wall has been re-supported at 1st floor level on a 203UC steel beam, from analysis this beam is insufficient to support the full height of spine wall and floor beams above so the existing timber floor beams at each level have been assessed.

Bending Stresses @ 230% capacity => strengthening required
 Deflection @ 200% limit => strengthening required

Refer to Z3-S100.1&2-Detail 1&2

Existing Timber Floor Joist Assessment:

The existing floor joists vary in both depth and width, typically they are 160x60 at 380 c/c. They have been assessed for their maximum span.

Bending Stresses @ 98% capacity
 Deflection @ 160% limit => strengthening required

Refer to Z3-S100.1-Detail 1

Existing Stair Beam Assessment:

The stair wall is not supported below first floor level so the existing timber floor beams at each level have been assessed.

Bending Stresses @ 140% capacity => strengthening required
 Deflection @ 200% limit => strengthening required

Refer to Z3-S100.7-Detail 9

Existing Floor Beam Assessment:


The existing timber floor beam at each level have been assessed.

Bending Stresses @ 110% capacity => strengthening required
 Deflection @ 200% limit => strengthening required

Refer to Z3-S100.5-Detail 6

Existing Floor Movements:

From survey spot levels the existing floor structure has settled/deflected by up to 100mm at each floor level. Strengthening Works are required to ensure to further settlement occurs



NOTES

engenuiti

+44 (0)20 7089 5760
www.engenuiti.com

2 Mailings Place
Tower Bridge Road
London SE1 3JB
United Kingdom

project name		9 Denmark Street	
sketch title		Proposed Structural Details	
date		15.09.2017	
project no	sketch no	rev	by
879	Z3-S-100.0	-	RK

Option A:

- This option provides the required strengthening to the existing spine beam while minimising impact on the historic finishes.
- This option does require the existing floor beams to be trimmed and re-supported on the new steelwork
- Option A is considered to have the least impact on the historic building fabric while achieving the required structural strengthening

Existing timber spine wall beams to be strengthened with pairs of PFC steel beams - through bolted to spine beam with pairs of bolts at 600mm c/c

New plywood sheathing fixed down to new timber joists - resilient bars to tops of joists to Architects specification

Existing joists to be strengthened with 200x50 C24 timber joists - bolted together at 400mm staggered c/c

Proposed spine beam strengthening allows for finishes to remain largely undisturbed




Figure 1, Spine Wall Strengthening Location

Detail 1: Spine Beam & Joist Strengthening Requirements, 1:10
Option A

Structural Strengthening Requirements:

- The existing spine wall beam can not be justified to support the required residential loadings to current standards therefore strengthening is required.
- The existing floor joists require strengthening due to comply with current standards and allow for levelling of existing floors
- Generally all structural strengthening proposed will reduce deflections and movements within the building to protect the historic structure and materials from further damage
- Steel beams to bear onto padstones in masonry party walls

NOTES

engenuiti

+44 (0)20 7089 5760
www.engenuiti.com


2 Mailings Place
Tower Bridge Road
London SE1 3JB
United Kingdom

project name		9 Denmark Street	
sketch title		Proposed Structural Details	
project no		879	
sketch no		Z3-S-100.1	
date		25.08.2017	
rev		-	
by		RK	

Strengthening steel beams to existing timber spine wall beams allow for kitchen waste pipe to run through to riser beyond - steel beams to be strengthened locally around penetration

Existing and proposed joists to be strengthened locally with steel plates to allow for kitchen waste pipe to run within floor zone - plates to be screw fixed to joists

Service penetration to mid depth of joists



Detail 3: Spine Beam & Joist Service Penetration, 1:10

Structural Strengthening Requirements:

- The strengthening is required to allow the waste pipe from the proposed kitchen island unit to run through the floor zone. The island unit is required to avoid any damage to historic wall finishes
- The service run for the kitchen waste pipe will effect a maximum of 3 joists and the spine beam at each level



Figure 3, Spine Wall Strengthening Location


NOTES

engenuiti

+44 (0)20 7089 5760
www.engenuiti.com

2 Mailings Place
Tower Bridge Road
London SE1 3JB
United Kingdom

project name		9 Denmark Street	
sketch title		Proposed Structural Details	
project no		879	
sketch no		Z3-S-100.3	
date		25.08.2017	
rev		-	
by		RK	



Detail 4: Floor Beam To Be Re-supported, 1:10

Structural Strengthening Requirements:

- The strengthening is required to the bearing of the floor beams to justify the connection for required residential loadings to current standards



Figure 4, Floor Beam To Be Re-supported

NOTES


engenuiti

+44 (0)20 7089 5760
www.engenuiti.com

2 Mailings Place
Tower Bridge Road
London SE1 3JB
United Kingdom


project name		9 Denmark Street	
sketch title		Proposed Structural Details	
project no		date	
879	Z3-S-100.4	1	25.08.2017
rev		by	
1		RK	

Steel strengthening plate to be resin bonded into slot cut into existing timber floor beam



Detail 5: Section of Front Floor Beam To Be Strengthened, 1:10

Existing joists to be strengthened with 200x50 C24 timber joists - bolted together at 400mm staggered c/c



Incoming floor joists

New timber joists to be fixed to existing floor beam with screw fixed angle brackets

Detail 6: Plan of Front Floor Beam To Be Strengthened, 1:10 Option A

Structural Strengthening Requirements:

- The existing timber floor beam can not be justified for the required residential loadings to current standards and requires strengthening
- This solution offers the least impact to the existing floor joists




Figure 5, Front Floor Beam To Be Strengthened

NOTES

engenuiti


+44 (0)20 7089 5760
www.engenuiti.com

2 Mailings Place
Tower Bridge Road
London SE1 3JB
United Kingdom

project name		9 Denmark Street	
sketch title		Proposed Structural Details	
project no		879	
sketch no		Z3-S-100.5	
date		25.08.2017	
rev		-	
by		RK	

Existing timber spine wall beams to be strengthened with pairs of PFC steel beams - through bolted to spine beam with pairs of bolts at 600mm c/c


Steel plate to be supported on new steel beam - fixed with bolted angle connection




New steel plate bolted to stair side face of existing timber beam - existing finishes to be carefully removed to allow for plate to be installed

Existing timber floor & stair beam

Existing stair trimmer beam to be re-supported in steel plate with joist hanger



New timber joists to be fixed to existing floor beam with screw fixed angle brackets



Detail 9: Plan of Rear Floor/Stair Beam To Be Strengthened, 1:10

Structural Strengthening Requirements:

- The existing timber floor beam can not be justified for the required residential loadings to current standards and requires strengthening
- The staircase shows signs of settlement due to the movement of the stair wall and the supporting beam line needs to be stabilised at each level
- The proposed solution offers the least impact to the existing floor structure as the floor joists will not require cutting back and re-supporting




Figure 6, Rear Floor Beam To Be Strengthened
Note: Strengthening to opposite side of wall shown

NOTES

engenuiti

+44 (0)20 7089 5760
www.engenuiti.com

2 Mailings Place
Tower Bridge Road
London SE1 3JB
United Kingdom

project name		9 Denmark Street	
sketch title		Proposed Structural Details	
project no		879	
sketch no		Z3-S-100.7	
date		25.08.2017	
rev		-	
by		RK	

Typical Structural Repair Details



Figure 7, Typical Cracked Masonry Repair - Third Floor Party Wall Shown

Structural Repair Works:

- Cracked bricks to be replaced with bricks and mortar to match existing construction
- Helibar crack repair bars to be installed to bed joints at every 5th course to avoid future cracking
- Timber within masonry walls to be removed and bricked in to avoid future settlement or decay




Figure 8, Typical Masonry Reveal Repair - First Floor Half Landing Shown

Structural Repair Works:

- Masonry to be made good with bricks and mortar to match existing construction




Figure 9, Typical Decayed Timber Repair - Roof Rafters & Bearing Plate Shown

Structural Repair Works:

- Decayed timber to be cut out and new timber spliced in
- Rafters to be strengthened with timbers of matching size as required

NOTES

engenuiti

+44 (0)20 7089 5760
www.engenuiti.com

2 Mailings Place
Tower Bridge Road
London SE1 3JB
United Kingdom

project name		9 Denmark Street	
sketch title		Proposed Structural Repairs	
project no		date	
879	sketch no	25.08.2017	
rev		by	
-		RK	

Location of opening up required to historic finishes



Figure 10, Location Of Panelling To Be Removed - Second Floor Stair Wall

Structural Investigation Requirements:

- The existing staircase has settled significantly and we need to inspect the connection of the staircase to the stair wall and assess whether additional strengthening is required



Figure 11, Location Of Panelling To Be Removed - Second Floor Spine Wall

Structural Investigation Requirements:

- The base and head of the existing timber stud wall needs to be inspected to confirm whether any remedial works are required

NOTES

engenuiti

+44 (0)20 7089 5760
www.engenuiti.com

2 Mailings Place
Tower Bridge Road
London SE1 3JB
United Kingdom

project name		9 Denmark Street	
sketch title		Proposed Structural Investigations	
project no		879	
sketch no		Z3-S-100.9	
rev		-	
date		25.08.2017	
by		RK	

Existing Non-Structural Additions To Be Removed



Figure 12, Third Floor Non-Structural Additions

Non-Structural Items To Be Removed:

- By inspection it is apparent that almost all of the white painted timber joinery inside the plaster finish line is a decorative add-on and non-structural in nature. As such this can be removed.
- The only exception are the posts supporting each end of the roof beam high lighted above.



Figure 13, Third Floor Non-Structural Additions

Non-Structural Items To Be Removed:

- The white timber work to the ceiling has splice joints which have rotated and are not designed to be load-bearing




Figure 14, Third Floor Non-Structural Additions

Non-Structural Items To Be Removed:

- The apparent main white timber beam to the underside of the ceiling is formed of timber sheets and is hollow, by inspection this element is non-structural

NOTES

engenuiti

+44 (0)20 7089 5760
www.engenuiti.com

2 Mailings Place
Tower Bridge Road
London SE1 3JB
United Kingdom

project name		9 Denmark Street	
sketch title		Proposed Structural Works	
project no		879	
sketch no		Z3-S-100.10	
date		25.08.2017	
rev		-	
by		RK	