

# TECHNICAL REPORT ON A SUBSIDENCE CLAIM

Crawford Reference: SU1701605

**The Society of Analytical Psychology**  
**1 Daleham Gardens,**  
**London**  
**NW3 5BY**



prepared for

**AIG Europe Limited**  
**The AIG Building, 2-8 Altyre Road, Croydon, CR9 2IG**

**Claim Reference 3799024214GB**

**SUBSIDENCE CLAIM**

DATE 19 May 2017




**Crawford**<sup>®</sup>

Specialist Property Services UK  
1<sup>st</sup> Floor, Cassiobury House,  
11-19 Station Road,  
Watford,  
WD17 1AP  
Tel: 01923 471755

**Site Plan**
























**This plan is Not to Scale**

This is an Aerial Photograph of the property and the immediate surrounding area. The positions of utilities etc are only indicative and contractors must satisfy themselves regarding actual location before commencing works.



© Bluesky International & © Infoterra 2006.  
Map Reproduced with the Permission of Ordnance Survey License Number #####

**Key:**

	Tree: Deciduous		Tree: Conifer		Shrub
	Hedge		Area of Damage		Bore Hole
	Trial Hole		Trial & Bore Hole		Level Monitoring
	Rain Water Manhole		Rain Water Gully		Rain Water Pipe
	Waste Water Manhole		Waste Water Gully		Toilet Pipe
	Rain Water Drain		Waste Water Drain		Electricity Cable
	Water Supply Pipe		Gas Supply Pipe		Incoming Gas Pipe
	Incoming Water		Incoming Electrics		

Chartered Loss Adjusters

## INTRODUCTION

We have been asked by AIG Europe Limited to comment on movement that has taken place to the above property. We are required to briefly describe the damage, establish a likely cause and list any remedial measures that may be needed.

Our report should not be used in the same way as a pre-purchase survey. It has been prepared specifically in connection with the present insurance claim and should not be relied on as a statement of structural adequacy. It does not deal with the general condition of the building, decorations, timber rot or infestation etc.

The report is made on behalf of Crawford & Company and by receiving the report and acting on it, the client - or any third party relying on it - accepts that no individual is personally liable in contract, tort or breach of Statutory duty. Where works address repairs **that are not covered** by the insurance policy we recommend that you seek professional advice on the repair methodology and whether the works will involve the Construction (Design & Management) Regulations 2015. Compliance with these Regulations is compulsory; failure to do so may result in prosecution. We have not taken account of the regulations and you must take appropriate advice.

We have not commented on any part of the building that is covered or inaccessible.

## TECHNICAL CIRCUMSTANCES

Operations manager Lykke Leszczynski noticed damage to the right side of building over the last 12 months. The area of concern is to the rear single storey extensions.

Previously on the 8th of May 2015 a structural appraisal of the building was carried out by Martin Redston Associates. The report highlighted movement to various parts of the property. The report was commissioned as there were plans to construct an extension.

## PROPERTY

Three storey large detached house of traditional construction with brick walls surmounted by a pitched tiled roof with flat roof construction to rear single storey extensions.

## HISTORY & TIMESCALE

Date of Construction .....	1900
Policy Inception Date .....	01/06/2013
Damage First Noticed .....	08/05/2015
Claim Notified to Insurer.....	10/05/2017
Date of our Inspection.....	12/05/2017
Issue of Report .....	19/05/2017
Anticipated Completion of Claim .....	19/05/2017

## TOPOGRAPHY

The property occupies a reasonably level site with no unusual or adverse topographic features.


Chartered Loss Adjusters

**GEOLOGY**

Reference to the 1:625,000 scale British Geological Survey Map (solid edition) OS Tile number TQNW suggests the underlying geology to be London Clay.

London Clays are marine deposits characterised by their silty, sandy composition. They are typically stiff, dark or bluish grey, weathered dark to mid-brown superficially with fine particle size (less than 0.002mm). Tomlinson<sup>1</sup> describes it as a ‘fat’ clay with high loadbearing characteristics due to pre-consolidation pressures in its geological history.

The upper horizon is often encountered at shallow depth, sometimes just below ground level. They have high shrink/swell potentials<sup>2,3</sup> and can be troublesome in the presence of vegetation.



Geology. Reproduced with consent of The British Geological Survey at Keyworth. Licence IPR/34-7C CSL British Geological Survey. ©NERC. All rights Reserved.

**VEGETATION**

There are several trees and shrubs nearby, some with roots that may extend beneath the property foundations. The following are of particular interest:-

Type	Height	Distance	Ownership
T1 Deciduous	8 m	3 m	Owners
T2 Deciduous	4 m	3 m	Owners
T3 Deciduous	10 m	4 m	Owners
T4 Deciduous	8 m	4 m	Owners
T5 Deciduous	4 m	4 m	Owners
T6 Deciduous	3 m	3 m	Owners
T7 Deciduous	3 m	12 m	Owners
T8 Deciduous	10 m	4 m	Owners
T9 Deciduous	8 m	5 m	Owners
T10 Deciduous	4 m	5 m	Owners

<sup>1</sup> Tomlinson M.J. (1991) “Foundations Design & Construction” Longman Scientific Publishing.

<sup>1</sup> B.S. 5930 (1981) “Site Investigations”

<sup>2</sup> Driscoll R. (1983) “Influence of Vegetation on Clays” Geotechnique. Vol 33.


<sup>3</sup> Table 1, Chapter 4.2, Para. 2.3 of N.H.B.C. Standards, 1986.

Chartered Loss Adjusters

T11 Deciduous	3 m	5 m	Owners
T12 Deciduous	3 m	5 m	Owners
T13 Deciduous	4 m	1 m	Owners
T14 Deciduous	3 m	2 m	Owners

See sketch. Tree roots can be troublesome in cohesive (clay) soils because they can induce volumetric change. They are rarely troublesome in non-cohesive soils (sands and gravels etc.) other than when they enter drains, in which case blockages can ensue.

Broadleaf trees typically have wider spreading roots and higher water demands than coniferous species and many are better adapted to growing on heavy clay soils. Some are capable of sprouting from cut stumps or bare wood and most will tolerate pruning better than conifers.



Typical proportions of a broadleaf tree. Note the potential root zone. It must be noted that every tree is different, and the root zone will vary with soil type, health of the tree and climatic conditions.

However heavy pruning of any tree should be avoided if possible, as it stimulates the formation of dense masses of weakly attached new branches which can become dangerous if not re-cut periodically to keep their weight down.

**OBSERVATIONS**

The following is an abbreviated description. Photographs accompanying this report illustrate the nature and extent of the problem.

**INTERNAL**

Library ceiling crack to rear of room



Close up of crack to right of window in the library

**Ground floor library**

- Diagonal crack of 1 to 4mm to top left of window
- Straight ceiling crack of 2mm extending down the wall of 5mm
- Separation gap of 2mm to ceiling wall junction

**Corridor to library**

- Cracking to ceiling wall junction with central cracks to ceiling joints
- Vertical tapering crack along door to meeting room on the left

**Meeting room**

- Vertical tapering crack to right of door
- Vertical tapering crack below all windows with small vertical crack top left of right side window
- ceiling crack

**Rear corridor**

- Vertical wall crack to top right of right side WC
- Visible patch repairs to top right of door to main hallway
- Diagonal cracks to top right of cupboard door
- Separation gap to ceiling wall junction

**Rear cupboard no. 23**

- Diagonal crack of 2.5m length to right partition wall
- Diagonal crack to top left of door

Chartered Loss Adjusters

Left side WC

- Separation crack along the right hand side ceiling wall junction

Front small office

- Small crack above left of window
- Localised separation crack to ceiling wall junction

**Unrelated Damage**


Entrance hall

- Ceiling crack across the centre

**EXTERNAL**



~Stepped diagonal crack below window along flank wall to library



Evidence of previous repairs to rear elevation of single storey extension

Rear elevation of single storey projection

- Evidence of previous repairs to the brickwork below all windows

Library right flank

- Stepped diagonal crack of 3mm below right of window

**CATEGORY**

In structural terms the damage falls into Category 2 of Table 1, Building Research Establishment<sup>4</sup> Digest 251, which describes it as "slight".

Category 0	"negligible"	< 0.1mm
Category 1	"very slight"	0.1 - 1mm
Category 2	"slight"	>1 but < 5mm
Category 3	"moderate"	>5 but < 15mm
Category 4	"severe"	>15 but < 25mm
Category 5	"very severe"	>25 mm

<sup>4</sup> Building Research Establishment, Garston, Watford. Tel: 01923.674040

**Extract from Table 1, B.R.E. Digest 251**  
Classification of damage based on crack widths.

## **DISCUSSION**

### **Right hand side of building and rear single storey extension**

The pattern and nature of the cracks is indicative of subsidence. The cause of movement appears to be clay shrinkage.

Clay soils shrink and swell seasonally, and this can cause minor damage following particularly dry spells of weather where footings are relatively shallow.

The timing of the event, the presence of shrinkable clay beneath the foundations and the proximity of vegetation where there is damage indicates the shrinkage to be root induced. This is a commonly encountered problem and probably accounts for around 70% of subsidence claims notified to insurers.

Fortunately, the cause of the problem (dehydration) is reversible. Clay soils will re-hydrate in the winter months, causing the clays to swell and the cracks to close. Provided the cause of movement is dealt with (in this case, vegetation) there should not be a recurrence of movement.

### **Entrance hall**

The cracks in the ceiling appear to be due to normal deterioration.

Ceilings crack for many reasons. For example, older lath and plaster ceilings suffer as a result of the shrinkage of the underlying laths or fail simply due to age.

Unfortunately, this type of damage is not covered by the insurance policy.

## **RECOMMENDATIONS**

### **Right hand side of building and rear single storey extension**

The cause of the movement needs to be dealt with first. We recommend site investigations and will likely recommend tree removal works be undertaken by the owners, subject to statutory checks for Preservation Orders or whether the tree(s) are in a Conservation Area first.

Typically, these investigations would involve trial pit(s) to determine the depth and type of footings, boreholes to determine the nature of the subsoil/influence of any roots and monitoring to establish the rate and pattern of movement.

Provided the tree management works are completed by the owners, consideration may then be given to carrying out the appropriate repairs to the property.

Subject to Insurer's instructions, a schedule of repairs will be obtained and repairs may commence once the scope has been approved.



**Entrance hall**

Further investigation of the damage is beyond our brief.

Consequently, you may wish to consider engaging the services of an appropriate construction professional to ensure the correct remedial action is taken.

**Matin Abdul BSC (Hons)**  
**Specialist Property Services - Subsidence Division**  
**Direct Dial : 0115 943 8260**  
[subsidence@crowco.co.uk](mailto:subsidence@crowco.co.uk)

19 May 2017

Chartered Loss Adjusters

**PHOTOGRAPHS**




Ceiling crack in corridor near library



Fracture to partition wall to cupboard no. 23



Rear meeting room crack above right of window



Ceiling crack in hallway

Chartered Loss Adjusters



Flat roof to rear extension



Ceiling crack to library cupboard

Chartered Loss Adjusters