

# ARBORICULTURAL ASSESSMENT REPORT

<b>For:</b>	<b>Client:</b>	Oriel Services Limited
	<b>Insurer:</b>	Legal and General Insurers Limited
<b>Site:</b>	<b>Policyholder:</b>	██████████
	<b>Risk Address:</b>	25 Frognal, London, NW3 6AR
<b>Refs:</b>	<b>OCA Ref:</b>	70790
	<b>Client Ref:</b>	6724684
	<b>Insurer Ref:</b>	D140903640

<b>Arborist Name:</b>	Thomas Peppiatt	<b>Date:</b>	27/02/2018
-----------------------	-----------------	--------------	------------



## OCA Insurance Services

2 The Courtyards, Phoenix Square, Severalls Park, Wyncolls Road, Colchester, Essex CO4 9PE  
Tel.No: 01206 751626

Email: [colchester@oca-arb.co.uk](mailto:colchester@oca-arb.co.uk) [www.oca-arb.co.uk](http://www.oca-arb.co.uk)



## **CONTENTS**

1.0 INTRODUCTION & BRIEF .....	3
2.0 LIMITATIONS.....	3
3.0 DISCUSSION AND ANALYSIS .....	4
4.0 EVIDENTIAL REVIEW AND MATERIAL CONSIDERATIONS.....	5
5.0 CONCLUSIONS AND RECOMMENDATIONS.....	6
6.0 STATUTORY CONTROLS.....	6
7.0 APPENDIX 1: TREE TABLES .....	7
8.0 APPENDIX 2: SITE PLAN.....	10
9.0 APPENDIX 3: SITE PHOTOGRAPHS.....	12

## **1.0 INTRODUCTION & BRIEF**

- 1.1** OCA Insurance Ltd has been instructed by Oriel Services Limited on behalf of the building insurers of 25 Frognal, London, NW3 6AR. We have been advised that the insured property has suffered differential movement and damage that is considered to have been caused by trees growing adjacent to the property influencing soils beneath its foundations.
- 1.2** We have been instructed to undertake a survey of the vegetation growing adjacent to the insured property in order to provide our opinion as to whether, based on the available information, any of this vegetation is likely to be influencing soil moisture levels beneath the foundations of the property, and if so, to provide recommendations as to what tree management could be implemented to effectively prevent damage continuing.
- 1.3** The vegetation growing adjacent to the risk address has been surveyed from the ground. All distances are measured to the nearest point of the risk address unless otherwise stated.

## **2.0 LIMITATIONS**

- 2.1** Recommendations with respect to tree management are associated with the risk address as stated on the front cover of this report and following consultation with investigating engineers. The survey of trees and any other vegetation is associated with impacts on the risk address subject of this report. Matters of tree health, structural condition, and/or the safety of vegetation under third party control are specifically excluded. Third party land owners are strongly advised to seek their own professional advice as it relates to the health and stability of trees under their control.
- 2.2** Recommendations do not take account of any necessary permission (statutory or otherwise) that must be obtained before proceeding with any tree works.
- 2.3** Recommendations do not take account of any requirements for survey or mitigation relating to European or other protected species, e.g. bird nesting or bats. Land owners must obtain their own professional advice in respect of any protected species.

## **3.0 DISCUSSION AND ANALYSIS**

### **3.1 Soils, soil water and vegetation**

All vegetation requires water to live, and this water is substantially accessed from the soil within which the plants' roots grow.

If the soil is classified as a clay soil, then it will hold very much more water than sands, gravels and loam soils. As plants abstract water from the clay soil, the soil volume will "shrink" and "swell" during the summer as water is first removed and then added by summer rainfall.

In years in which rainfall during the summer is less than the total amount of water taken from the soil by plants, shrinkage will occur. This shrinkage may remove support from building foundations, leading to cracking in the fabric of the building.

### **3.2 Vegetation management**

The control of trees, shrubs, and climbers, by removal or pruning as appropriate, are proven techniques that can control total soil water loss thereby minimising soil shrinkage and allowing repairs to proceed.

If vegetation management works are carried out promptly, then repairs can usually proceed very quickly and the duration and distress associated with the disruption that tree related subsidence brings can be minimised.

### **3.3 Third party liaison and statutory controls**

Tree roots do not respect physical or property boundaries and can travel for many metres beyond the above ground "dripline" of the canopy of the vegetation.

The purpose of this report is to ascertain which vegetation is the most likely substantial and/or effective contributory cause of the damage witnessed to allow for liaison with third parties or with local administrative Councils as necessary.

You can learn more about tree related subsidence of low rise buildings by visiting:

[www.oca-arb.co.uk/whatissubsidence.htm](http://www.oca-arb.co.uk/whatissubsidence.htm)

## 4.0 EVIDENTIAL REVIEW AND MATERIAL CONSIDERATIONS

### 4.1 Engineering Summary

Report dated 14/02/2018:

The engineer has described the damage to the property, its location and the likely mechanism of movement, and has concluded that the building failure is related to differential subsidence damage caused as a result of the action of vegetation.

This is a new subsidence claim and we are unaware of any previous history of subsidence at the property.

We have been informed by the engineer that there is not a heave risk to this property.

### 4.2 Foundations, geotechnical, and root identification

Report dated 18/02/2018:

A factual geotechnical report has described the below ground foundation design, soil and geotechnical conditions, as well as any root identification where available.

Foundations are described as being 1500mm (TP1) & 950mm (TP2) below ground level.

Trial pit/borehole samples have been subject to laboratory analysis and the results of these tests indicate that soils have a plasticity index ranging from 14% in TP1 and 19% to 48% in TP2.

Roots have been recovered from the trial pit(s) and subjected to laboratory analysis and the results confirm:

TH1 1600mm depth	Prunus spp and Tilia spp.
TH1 1800mm depth	Vitaceae spp and Tilia spp.
TH2 1000mm to 1500mmdepth	Leguminoseae spp.

Although no rooting evidence has been found to implicate TG3, S1 and S2, we feel that, due to their size, location and species characteristics, this tree is considered to be rooting below foundation depth and should be removed as a current claim requirement.

The Prunus spp roots found in TH1 were found to be negative in starch. It is likely that these originate from a previously removed species, not related to the current claim damage.

## 5.0 CONCLUSIONS AND RECOMMENDATIONS

### 5.1 Recommendations

On the basis of our findings, we have considered a practical vegetation management specification.

This specification will assist in reducing the impact of the adjacent vegetation on soil moisture levels, thereby potentially stabilising foundations of the affected area of the building.

Where felling has been proposed, this will be on the basis that the vegetation in question would not respond well to a severe reduction in leaf area that would inevitably lead to decay, the development of potential hazards, and an annual or other on-going management commitment and cost.

If pruning is recommended, the specification will be designed to allow continual ease of re-pruning with a reasonable prospect of a reduction in soil water use.

### 5.2 Recommended vegetation management to address the current subsidence:

Tree No:	Species	Works Required
T1	False Acacia	Fell and treat stump
T2	False Acacia	Fell and treat stump
S1	Buddleia	Fell and treat stump
C1	Vine	Fell and treat stump
T4	Lime	Fell and treat stump
S2	Buddleia	Fell and treat stump
TG3	Bay Laurel	Fell and treat stumps

## 6.0 STATUTORY CONTROLS

The London Borough of Camden has confirmed that the implicated Lime tree T4 is subject to a Tree Preservation Order. They have also confirmed that the properties are within a Conservation Area as well.

## 7.0 APPENDIX 1: TREE TABLES




## OCA Insurance Services

Tree No	Common Name	Age Class	Condition	Height (m)	Crown Spread (m)	Stem diam. (mm)	Dist to bldg. (m)	Pruning history	Recommendation	Tree work constraints	Notes	Owner address	Owner
T1	False Acacia	Mature	Fair	14	6	310	2	No significant recent management	Fell and treat stump			25 Frogna, London, NW3 6AR	PH
T2	False Acacia	Mature	Fair	10	4	160	4	No significant recent management	Fell and treat stump			25 Frogna, London, NW3 6AR	PH
TG1	Cabbage tree	Mature	Fair	4.5	1.50	180	1.8	No significant recent management	No work required		x2 Cabbage trees	25 Frogna, London, NW3 6AR	PH
TG2	Mixed species group	Mature	Fair	11.5	7.0	280	7	No significant recent management	No work required		x1 Cabbage tree, x2 Silver birch, x2 Walnut	25 Frogna, London, NW3 6AR	PH
T3	Silver Birch	Mature	Fair	10	4	150	4.6	No significant recent management	No work required			25 Frogna, London, NW3 6AR	PH
TG3	Bay Laurel	Mature	Fair	10	4	80	3.5	No significant recent management	Fell and treat stump		x2 Laurel Bay	25D Frogna, London, NW3 6AR	P3P
S1	Buddleia	Mature	Fair	6.5	6	180	3	No significant recent management	Fell and treat stump			25D Frogna, London, NW3 6AR	P3P
C1	Vine	Mature	Fair	4	4	80	0	No significant recent management	Fell and treat stump			25 Frogna, London, NW3 6AR	PH
T4	Lime	Mature	Fair	17	6	700	9	No significant recent management	Fell and treat stump			25 Frogna, London, NW3 6AR	PH



Tree No	Common Name	Age Class	Condition	Height (m)	Crown Spread (m)	Stem diam. (mm)	Dist to bldg. (m)	Pruning history	Recommendation	Tree work constraints	Notes	Owner address	Owner
S2	Buddleia	Mature	Fair	4	5.0	120	3	No significant recent management	Fell and treat stump			25D Frognal, London, NW3 6AR	P3P
T5	Maple	Mature	Fair	11	10	400	11.5	No significant recent management	No work required			23 Frognal, London, NW3 6AR	P3P

## 8.0 APPENDIX 2: SITE PLAN



Location:	25 Frognaal, London, NW3 6AR	
Job Ref:	70790	
Survey Date:	26/02/2018 - NTS	
By OCA Insurance Limited		
Crown copyright 2016. License number 100043594		

## 9.0 APPENDIX 3: SITE PHOTOGRAPHS



T1 - False Acacia



T2 - False Acacia



TG1 - Cabbage tree




TG2 - Mixed species group



T3 - Silver Birch



TG3 - Bay Laurel



S1 - Buddleia



C1 - Vine



T4 - Lime



S2 - Buddleia



T5 - Maple



# **OCA Insurance Services**

**Landscape Planning Limited  
2 The Courtyards  
Phoenix Square  
Wyncolls Road  
Colchester  
Essex CO4 9PE**

**01206 752539**

**[colchester@oca-arb.co.uk](mailto:colchester@oca-arb.co.uk)**

**[www.oca-arb.co.uk](http://www.oca-arb.co.uk)**