

**TECHNICAL REPORT ON A SUBSIDENCE CLAIM**

**Crawford Reference: SU1604808**

**Gilling Court (Hampstead) Ltd  
Flat 2 Gilling Court  
Belsize Grove  
Hampstead  
London  
NW3 4UY**




prepared for


**Aviva - Commercial  
Commercial Claims Dept., Northfield House, 110-114 Baxter Avenue, Southend On Sea, SS2  
6FF**

**Claim Reference 8945388**

**SUBSIDENCE CLAIM**

  
**Crawford**<sup>®</sup>  
Specialist Property Services UK





**INTRODUCTION**

We have been asked by Aviva - Commercial to comment on movement that has taken place to the above property. We are required to briefly describe the damage, establish a likely cause and list any remedial measures that may be needed.

Our report should not be used in the same way as a pre-purchase survey. It has been prepared specifically in connection with the present insurance claim and should not be relied on as a statement of structural adequacy. It does not deal with the general condition of the building, decorations, timber rot or infestation etc.

The report is made on behalf of Crawford & Company and by receiving the report and acting on it, the client - or any third party relying on it - accepts that no individual is personally liable in contract, tort or breach of Statutory duty. Where works address repairs **that are not covered** by the insurance policy we recommend that you seek professional advice on the repair methodology and whether the works will involve the Construction (Design & Management) Regulations 2015. Compliance with these Regulations is compulsory; failure to do so may result in prosecution. We have not taken account of the regulations and you must take appropriate advice.

We have not commented on any part of the building that is covered or inaccessible.

**TECHNICAL CIRCUMSTANCES**

We understand from the managing agents for Flat 28 that the cracks started about 2-3 months ago, and that there has been a further deterioration over the last month.

The insured commissioned a report from Guardian Surveyors LLP regarding the cracking to Flat 2. Their report is dated 20th October and considers the movement to be due to a leaking water main or other pipe. Their recommendations include testing the stop tap in the road and excavating at the front left corner of the front entrance projection.

They also advise that Cunningham Lindsey dealt with a claim in the same area in 2008, followed by repairs to Flat 2. The leaseholder of Flat 2 advised that cracks reappeared about 8 months later.

**PROPERTY**

The property comprises a 4 storey purpose built block with brick internal and external walls, concrete floors, surmounted by a flat roof. It is most likely that the construction is traditional with loadbearing masonry, but it is also possible that the floors are supported on a steel frame.

## HISTORY & TIMESCALE

Site investigations are being organised and level monitoring established

Date of Construction .....	1933
Purchased .....	Various
Policy Inception Date .....	25/04/2016
Damage First Noticed .....	October 2016
Claim Notified to Insurer.....	21/11/2016
Date of our Inspection.....	03/01/2017
Issue of Report .....	10/01/2017
Anticipated Completion of Claim .....	September 2018

## TOPOGRAPHY

The property occupies a reasonably level site with no unusual or adverse topographic features.

## GEOLOGY

Reference to the 1:625,000 scale British Geological Survey Map (solid edition) OS Tile number TQNW suggests the underlying geology to be London Clay.

London Clays are marine deposits characterised by their silty, sandy composition. They are typically stiff, dark or bluish grey, weathered dark to mid-brown superficially with fine particle size (less than 0.002mm). Tomlinson<sup>1</sup> describes it as a 'fat' clay with high loadbearing characteristics due to pre-consolidation pressures in its geological history.

The upper horizon is often encountered at shallow depth, sometimes just below ground level. They have high shrink/swell potentials<sup>2,3</sup> and can be troublesome in the presence of vegetation.

The superficial deposits are thought to be Clay Soils.

Clay soil superficial deposits are a cohesive soil characterised by their fine particle size and are usually derived from weathering of an underlying "solid geology" clay soil such as London Clay or Oxford Clay.

Like the solid geology sub-soil from which they are derived they shrink when dry, and swell when wet and can be troublesome when there is vegetation<sup>4</sup> nearby and Gypsum and selenite crystals can be encountered (particularly in the south east). Protection using Class II Sulphate Resisting cement is therefore recommended for buried concrete.


<sup>1</sup> Tomlinson M.J. (1991) *"Foundations Design & Construction"* Longman Scientific Publishing.

<sup>2</sup> B.S. 5930 (1981) *"Site Investigations"*

<sup>3</sup> Driscoll R. (1983) *"Influence of Vegetation on Clays"* Geotechnique. Vol 33.

<sup>4</sup> Table 1, Chapter 4.2, Para. 2.3 of N.H.B.C. Standards, 1986.

<sup>4</sup> Driscoll R. (1983) *"Influence of Vegetation on Clays"* Geotechnique. Vol 33.  
Chartered Loss Adjusters




Geology. Reproduced with consent of The British Geological Survey at Keyworth. Licence IPR/34-7C CSL British Geological Survey. ©NERC. All rights Reserved.

**VEGETATION**

There are several trees and shrubs nearby, some with roots that may extend beneath the house foundations. The following are of particular interest:-

Type	Height	Distance	Ownership
Deciduous x5	20 m	12 m	Owners

See sketch. Tree roots can be troublesome in cohesive (clay) soils because they can induce volumetric change. They are rarely troublesome in non-cohesive soils (sands and gravels etc.) other than when they enter drains, in which case blockages can ensue. Broadleaf trees typically have wider spreading roots and higher water demands than coniferous species and many are better adapted to growing on heavy clay soils. Some are capable of sprouting from cut stumps or bare wood and most will tolerate pruning better than conifers.



Typical proportions of a broadleaf tree. Note the potential root zone. It must be noted that every tree is different, and the root zone will vary with soil type, health of the tree and climatic conditions.

However heavy pruning of any tree should be avoided if possible, as it stimulates the formation of dense masses of weakly attached new branches which can become dangerous if not re-cut periodically to keep their weight down.





**OBSERVATIONS**

The damage appears to be limited to the front centre of the building

The following is an abbreviated description. Photographs accompanying this report illustrate the nature and extent of the problem.

**INTERNAL**

Crack in Flat 28 Living Room

Crack in the ground floor entrance lobby

**FLAT 2** (Ground floor, left of entrance)**Right hand end bedroom:**

10mm diagonal crack to the right flank wall

5mm crack over the window

3mm crack over the hall door, extending along the top of the left flank wall

**Hall:**

3mm crack over the door to the right hand end bedroom

**Left hand end bedroom:**

2mm crack over the hall door, extending along the top of the right flank wall

2mm crack in the front left corner

**FLAT 28** (First floor, left of stairs)**Living room:**

Diagonal crack to right flank wall, possibly 15mm width with significant disturbance of plaster

2mm cracks over the door to the hall

3mm crack over the window

**Right hand end bedroom:**

Crack behind wardrobe against left flank wall, possibly 10mm width

**Hall:**

3mm diagonal crack over door to the living room:

**Kitchen:**

3mm diagonal crack to the rear right corner, high level, extending along the top of the right flank wall

**COMMUNAL AREAS:**

**Ground floor entrance lobby:**

8mm diagonal crack to the wall to Flat 2, extends over front window

2 no 2mm diagonal cracks under the left hand window

Staining and water penetration over the entrance door

1mm vertical cracks to both flank walls of the entrance projection

2mm diagonal crack to the wall to Flat 3

1mm diagonal crack under the right hand window

**First floor landing:**

2mm vertical and diagonal cracks to the walls to Flats 28 and 29

**Second floor landing:**

1mm vertical and diagonal cracks to the walls to Flats 54 and 55

**EXTERNAL**



Cracks to front elevation

Cracks to front elevation

**Front elevation:**

Series of short cracks, up to 3mm width to the rendered areas at first floor and below. These cracks are predominately to the left of the main entrance. Cracking and movement of the front steps.

**CATEGORY**

In structural terms the damage falls into Category 4 of Table 1, Building Research Establishment<sup>5</sup> Digest 251, which describes it as "severe".

Category 0	"negligible"	< 0.1mm
Category 1	"very slight"	0.1 - 1mm
Category 2	"slight"	>1 but < 5mm
Category 3	"moderate"	>5 but < 15mm
<b>Category 4</b>	<b>"severe"</b>	<b>&gt;15 but &lt; 25mm</b>
Category 5	"very severe"	>25 mm

**Extract from Table 1, B.R.E. Digest 251**  
Classification of damage based on crack widths.

<sup>5</sup> Building Research Establishment, Garston, Watford. [REDACTED]





**DISCUSSION**

The pattern and nature of the cracks is indicative of an episode of subsidence. The cause of movement appears to be clay shrinkage.

The timing of the event, the presence of shrinkable clay beneath the foundations and the proximity of vegetation where there is damage indicates the shrinkage to be root induced. This is a commonly encountered problem and probably accounts for around 70% of subsidence claims notified to insurers.

Fortunately, the cause of the problem (dehydration) is reversible. Clay soils will re-hydrate in the winter months, causing the clays to swell and the cracks to close. Provided the cause of movement is dealt with (in this case, vegetation) there should not be a recurrence of movement.

**RECOMMENDATIONS**

Although the cause of the movement needs to be dealt with, we note the vegetation is in a Conservation Area and may be subject to Preservation Orders. Unfortunately, current legislation requires certain investigations to be carried out to support an application for the tree works.

Typically, these investigations would involve trial pits to determine the depth and type of footings, boreholes to determine the nature of the subsoil/influence of any roots and monitoring to establish the rate and pattern of movement. The monitoring data provided must be sufficient to show a pattern of movement consistent with the influence of the vegetation and therefore it may be necessary to carry out the monitoring for up to a 12 month period.

It will also be necessary to obtain a specialist Arboricultural Report.

We will report further once these investigations have been completed.


**Philip Gardner BSc, MIStructE, CEng, Cert CILA**  
**Specialist Property Services - Subsidence Division**




**PHOTOGRAPHS**



Crack in Flat 28 living Room



Crack in Flat 2 Right hand end bedroom



Crack in Fla2 Right hand end bedroom



Close up of crack in the entrance lobby showing evidence of past repair





Trees in the front of the building.



Damage to front steps at main entrance



Cracking in Flat 28 Right hand end bedroom



Cracking in Flat 2

