

1&1a Montague Street

Structural Report

Curtins Ref: 063007

Revision: V02

Issue Date: 26 July 2018

Client Name: The British Museum

Client Address: Great Russell Street, WC1B 3DG

Site Address: 1&1a Montague Street, London W1B

Curtins
40 Compton Street
London, EC1V 0BD
Tel: 020 7324 2240
www.curtins.com

Rev	Description	Issued by	Checked	Date
00	First issue	NCD	NCD	23/07/2018
01	Includes amendments suggested by BDP Architects and the British Museum	NCD	NCD	25/07/2018
02	Includes drawings in Appendix 2	NCD	NCD	26/07/2018

This report has been prepared for the sole benefit, use, and information for the client. The liability of Curtins Consulting Limited with respect to the information contained in the report will not extend to any third party.

Author	Signature	Date
Neill C Duke BSc(Hons) CEng MICE Associate	NCD	26/07/2018

Table of contents

1.0	Introduction.....	1
2.0	Rear Elevation and Balcony.....	2
3.0	Prospective Method Statement for the Repair of the Rear Elevation to No.1.....	6
4.0	Internal and External Cracking.....	8
5.0	Internal - Structural Openings.....	9
6.0	Appendix 1.....	11
7.0	Appendix 2.....	12

Figures

Figure 1 - Existing balcony.....	2
Figure 2 - Example of an existing braced support to the balcony.....	2
Figure 3 - Balcony - Proposed Bracing Position and Detail (**Note the brickwork should be removed with care, in order to facilitate the re-use of the bricks when the structural works are complete).....	3
Figure 4 - Repair Works to Rear Elevation.....	4
Figure 5 - Examples of how and where DryFix Ties may be utilised.....	5
Figure 6 - HeliFix crack stitching repair.....	8
Figure 7 - Extract from second floor drawing showing reduction of opening widths minimising structural interventions (refer to Appendix 2, BDP Drawing (20)AP004_WorkInProgress).....	9
Figure 8 - Extract from third floor drawing showing reduction of opening widths minimising structural interventions (refer to Appendix 2, BDP Drawing (20))AP005_WorkInProgress).....	10

1.0 Introduction

Two letters dated 15 May 2018 were issued by Regeneration and Planning Development Management, London Borough of Camden for the properties at 1 and 1A Montague Street, London WC1B 5BP:

- DECISION – Town and Country Planning Act (as amended), Full Planning Permission Granted; and
- DECISION - Planning (Listed Building and Conservation Areas) Act 1990, Listed Building Consent Granted, including -
 - permission for the creation of new openings at first, second and third floors; and
 - Condition No. 6, which requires a structural engineer's report and method statements for No.1 in order to safeguard the architectural and historic interest of the building.

The proposals to upgrade the two Grade II listed town houses for 21st Century office use are supported by Camden, allowing the buildings to be fully repaired and reused to avoid their addition to the Heritage at Risk Register. New work and work of making good (repair) are to be carried out to match the existing adjacent work as closely as possible in material and detailed execution.

Within this report, we propose to address the following aspects:

- repair works to the rear elevation and balcony, including a prospective method statement;
- structural repair of internal and external cracking (where appropriate); and
- forming new internal structural openings.

Extracts or “snips” from drawings and mark-ups have been included up to demonstrate proposals and supplement the report text. Similarly, information has been extracted from the HeliFix website.

2.0 Rear Elevation and Balcony

The proposals for the rear balcony had previously comprised the removal of the balcony structure for refurbishment (possibly off site) and whilst those works were ongoing, the rear elevation was going to be repaired, followed by reinstatement of the balcony.



Figure 1 - Existing balcony


More recently, localised exposure works revealed that the balcony is of a much lesser construction than anticipated. Of the six supports, three are just cantilevering out of the thickness of the rear elevation wall, whilst the other three are supported by diagonal braces.



Figure 2 - Example of an existing braced support to the balcony

We are of the opinion that as a structure, its supports cannot be justified analytically and certainly not to accommodate loadings from present day standards. If the structure is removed for refurbishment and then reinstated, there is a significant possibility lots of additional strengthening works may be required, potentially impacting upon the elevation brickwork. Certainly the existing cantilever bearing detail would not be acceptable. Consequently, it is proposed the balcony be refurbished in situ, without removal, but with some strengthening works basically just to support the balcony structure.

Balcony Elevation showing Bracing and Support points:



Proposed Bracing Position Detail:




Figure 3 - Balcony - Proposed Bracing Position and Detail (**Note the brickwork should be removed with care, in order to facilitate the re-use of the bricks when the structural works are complete)

It is proposed that the existing three braced supports be supplemented with three new braced supports at the locations of the existing cantilever supports, i.e. replicating the existing braced supports. A sketch detail is shown above. Please also refer to BDP drawing (15) AE002, Rev D issued with this report.

The loadings for balconies are much higher than can be accommodated by the present form of construction and indeed higher than would be acceptable for the strengthened form of construction, hence it is NOT to be used as a balcony.

In addition, it is considered wise to secure the returning ends of the handrail to the rear elevation. That would comprise simple cleats bolted to the rear elevation and the handrail. If necessary, a pocket could be formed in the face of the wall, so that the cleat can be secured at a nominal 100mm behind the external face of the elevation, and the pocket be reinstated.

Further, the hand rail is at less than the recognised minimum safe height of 1100mm. Hence, reinforcing the scenario that the balcony be retained as a “feature”, not a structure, and be identified by signage within the building and in the Building Fabric Manual that the balcony is not to be accessed nor used as such.

In addition to the balcony, remedial works are required for the rear elevation. In properties of this age and type, frequently the outer skin / external face of the main external walls used to be built by an experienced bricklayer, whilst the inner thickness was built by an apprentice. Thus the thickness of the walls was not fully bonded. Indeed, through the thickness of such walls, bed joints may be at different levels due to inconsistent coursing. This form of construction is described as “snapped header” construction. It is proposed to install remedial ties to ensure that the wall is bonded through its thickness.

Repair works to the brick work adjacent to the balcony- Montague Street

- Staggered Helifix DryFix Ties, 295mm long at 225mm (vertical) and 450mm (horizontal) staggered centres




Figure 4 - Repair Works to Rear Elevation

The form of remedial works is shown above. DryFix ties, as their name suggests, do not require resin or grout. They comprise a mechanical pinning, but do not involve mechanical expansion. The ties are easy to install and effective, and finished behind the face of the masonry.

Applications

- Versatile replacement wall tie
- For securing multiple layers of masonry
- For pinning delicate masonry features





Figure 5 - Examples of how and where DryFix Ties may be utilised

For Montague Street, this form of repair is suggested for the spandrel panel and pier to No.1 at the end of the balcony near the party wall.

3.0 Prospective Method Statement for the Repair of the Rear Elevation to No.1

Note: this a “prospective” method statement in which we believe the items of works are described in a reasonably logical order. However, the appointed contractor may seek to vary the actual sequencing of some aspects of works, depending upon availability of resources and materials.

1. Retain existing balcony temporary supports in position and erect scaffold to facilitate access to the balcony and rear elevation.
2. As noted above in the report, and witnessed by limited exposure on site, the external half brick thickness of facing brick does not appear to be fully bonded to the main inner thickness of the wall construction. Below each of the three simple cantilever bearings for the balcony, carefully form a nominal 100mm deep pocket in the face of the elevation by localised removal of bricks (at a level that corresponds with the braced supports for the balcony), of approximately 200mm height and width. Note that the removal of the brickwork should be carried out with care in order to facilitate the re-use of the bricks.
3. Take dimensions of existing bracing sections and the formed pocket in order to fabricate new braced supports for the balcony. Fabricate new sections to reflect the shape of the existing ones, including an end plate detail that will bear into the pocket and be anchored to the brickwork with a minimum of 2No. M10 resin anchors and connecting with 2No. M12 bolts to the existing balcony cantilevering supports. The newly fabricated sections are to be galvanised prior to delivery to site.
4. Install the three new braces in position below the balcony.
5. At the returning ends of the existing handrail, carefully form a nominal 100mm deep pocket in the face of the elevation by localised removal of bricks, of approximately 150mm height x 100-200mm width. Note that the removal of the brickwork should be carried out with care in order to facilitate the re-use of the bricks.
6. Fabricate small cleats, 50mm long cut from 200 x 100 angle sections and galvanize.
7. Install the cleats into position, fixing into the brickwork with 2No. M10 resin anchors and to the handrail with 2No. M8 bolts.
8. Make good the five pockets formed in the elevation (three below the balcony for the new braces and two at the ends of the cleats to the handrail) with brickwork and pointing to match existing adjoining areas.
9. The balcony is going to be retained as a feature rather than be functional, hence the temporary works need to remain in place whilst the balcony structure is refurbished and the remedial works are undertaken to the elevation brickwork.
10. Undertake structural repair of the cracking as described elsewhere in this report.
11. Install the mechanical pinning and remedial ties – HeliFix DryFix ties – see sketch below for the area to be addressed.



12. Outline specification for the refurbishment of the balcony:

- abrasive / sand blast clean and wire brush the balcony to remove the existing coating(s);
- examine the exposed structure and allow to be repaired as necessary;
- apply primer, two pack high build epoxy zinc phosphate to 80microns DFT; and
- apply finishing coating of two pack high build epoxy micaceous iron oxide to 170microns DFT.

13. Remove the temporary works and scaffolding with care. In the event that anything untoward is noticed, then Curtins should be contacted for a site visit to be made.

14. Undertake refurbishment of localised areas of the balcony that need addressing following removal of the temporary works and / or scaffolding.


4.0 Internal and External Cracking

Where internal cracking occurs, such as around the spine wall of No.1, crack monitoring and investigations have proven the movement to be historic, not recent, i.e. longstanding and not significantly progressive. Consequently, it is anticipated that repair of the cracks in the superstructure, without the need for underpinning works, will be sufficient to reinstate the structural integrity.

Cracking in the elevation brickwork is to be repaired by installation of 1000mm long HeliFix HeliBars, bedded in position at 225mm vertical centres with HeliBond grout – all materials to be used strictly in accordance with the manufacturer's guidelines and recommendations – pointed to match the adjoining areas of face brickwork.

The full length of the cracking, including that between HeliBars, is to be repaired with a proprietary repair mortar, such as an epoxy based weatherproof filler like Crackbond TE – again, all materials to be used strictly in accordance with the manufacturer's guidelines and recommendations.

A "snip", below, from the HeliFix website shows the crack stitching repair.



Lengths of [HeliBar](#) extending 500mm either side of the crack are bonded into cut slots, normally the mortar beds, with [HeliBond grout or resin](#) for a reliable and permanent solution. Where cracks are less than 500mm from an external corner or an opening, at least 100mm should be bent round the corner and bonded into the return wall or bent and fixed into the reveal, avoiding any DPC membrane.

Figure 6 - HeliFix crack stitching repair

Cracks being repaired in this manner have been identified on site, both internally and externally. Those works will be supplemented by (non-structural) repointing works.

5.0 Internal - Structural Openings

The Decision notices include consent for the creation of new openings at first, second and third floor levels, as shown on the Architect's planning submission drawings.

Localised exposure works in advance of creating the openings have revealed there to be elements of more than simple vertical loadbearing timber studs to these internal walls. There are diagonal timber sections within the walls and differing sizes of timber studs.

In order to reduce the level of structural intervention of the existing building fabric and minimise or obviate the need for structural works, we now propose to retain the larger timber studs and generally only remove the smaller timbers. This has the effect of reducing the widths of the proposed structural openings, but still achieving the opening up of the various spaces.

The proposals are shown on the two drawings, second and third floor levels, in the Appendix.




Figure 7 - Extract from second floor drawing showing reduction of opening widths minimising structural interventions (refer to Appendix 2, BDP Drawing (20)AP004_WorkInProgress)




Figure 8 - Extract from third floor drawing showing reduction of opening widths minimising structural interventions (refer to Appendix 2, BDP Drawing (20))AP005_WorkInProgress)

6.0 Appendix 1

Below, is a copy of a report titled, "Statement Related to Historic Movement", which has been submitted to Camden previously.

063007 1 & 1A Montague Street

Statement Relating to Historic Movement



Curtins Ref: 063007
Project Name: 1 & 1A Montague Street
Issue Date: 25 April 2017
Revision: first issue

Introduction

This statement relates to the historic settlement that is evident in the north west corner of 1 and 1A Montague Street.

Description of the Existing Structure

These are Georgian terraced properties considered to be typical of their age and type, that comprise external loadbearing masonry walls; internal loadbearing masonry walls at the lower levels and loadbearing timber stud walls at the upper levels; and suspended floors of timber construction. The buildings have been modified heavily since originally built. Further information is included within Hockley & Dawson's letter reports issued to The British Museum, dated 27 September 2012 and 23 November 2012.

Visual Observations

Curtins have been provided with photographs dating back to 2012, a study of which reveals that there does not appear to have been any significant deterioration, since then, of the cracking or distortions evident in the rear corner of the property adjacent to the party wall.

Curtins were also appointed to visit the site throughout 2016 and during that period no further movement was observed.

Discussion

Whilst the cause of the cracking observed is not obvious, it is historic, not new. We have been informed that the adjoining owner has also not reported any new cracking or deterioration. Consequently, the cracking and distortions are now considered to be longstanding and non-progressive, or at least not significantly progressive, and as such have reached a stable equilibrium.

Summary

There are distortions that can be addressed. We are of the opinion that substructure works, such as underpinning, is not warranted and believe that such works would be likely to cause further movement as a result of the construction. The proposed works to replace the rear façade at first floor level will improve the structural integrity by tying the locally rebuilt façade through to the floor structure.

Signatory

This report has been prepared on the basis of visual observations and with the benefit of limited site investigations, but no actual crack or level monitoring. Our report is provided for the sole use of the named client and is confidential to the client and his professional advisors. All parts of the property that were covered, unexposed or inaccessible were not inspected and therefore we are unable to report that such parts are free from defects.

Neill C Duke
BSc(Hons) CEng MICE
Curtins Consulting Ltd

7.0 Appendix 2

BDP drawings for 1-1A Montague Street:

- Proposed rear Elevation - (15) AE002, Rev D
- Second Floor Plan - (20)AP004_WorkInProgress
- Third Floor Plan - (20)AP005_WorkInProgress

BUILDING DESIGN PARTNERSHIP LTD SHALL HAVE NO RESPONSIBILITY FOR ANY USE MADE OF THIS DOCUMENT OTHER THAN FOR THAT WHICH IT WAS PREPARED AND ISSUED.
 ALL DIMENSIONS SHOULD BE CHECKED ON SITE.
 DO NOT SCALE FROM THIS DRAWING.
 ANY DRAWING ERRORS OR DIVERGENCES SHOULD BE BROUGHT TO THE ATTENTION OF BUILDING DESIGN PARTNERSHIP LTD AT THE ADDRESS SHOWN BELOW.

NOTES

- (X-X-DXX) EXISTING DOOR
- (X-X-DXX) NEW DOOR
- (X-X-DXX) NEW DOOR TO REPLACE EXISTING ASBESTOS CONTAINING DOOR
- (X-X-WXX) EXISTING WINDOW NUMBERS

All existing chimney pots to receive new terracotta ventilated cap.
 Mortar repairs to chimney stacks if required.

Existing balustrade to be refurbished to ensure stability and redecorated with exterior grade paint finish to match existing colour.
 Upon close inspection after the erection of the scaffold this brickwork was found to be sound - the distorted appearance from the garden is due to attempts to tie the brickwork into the coursing of the adjacent building.
 Organic growth to be removed.

Localised non hydraulic lime mortar repointing where required.
 Existing balcony to be repaired and redecorated. Access to it to be restricted.

Existing tie bars to be redecorated with exterior grade paint finish to match colour of existing.

All existing windows, reveals and cills, joinery and shutters to be repaired and redecorated as necessary.

All existing rainwater goods and exterior pipework to be cleaned / redecorated to match existing finish.

Cracking to brickwork to be repaired. Replacement of bricks where required and new bricks where missing.

Existing railing to be tied back into facade and redecorated with exterior grade paint finish.
 Existing balcony to be repaired in line with structural engineers report and redecorated. Brickwork to be carefully removed where necessary for new supports to be retained and replaced with mortar to match existing after the works are complete. Access to be restricted.
 Area of existing brickwork to be restrained in place using remedial DryFix ties in line with structural engineer's details, ties will not be visible.
 New external replacement light fittings. Refer to M&E specifications.
 New timber lintel behind window. Refer to structural engineer detail 10, drawing 063007-07.

Railing in for ground to be modified and redecorated. Refer to detail (41)AD002.



Existing slate roof flashings, ridge tiles, ridge painting, valley gutters, copings, render to parapet walls and localised mortar repairs to be repaired and reintegrated as necessary in matching materials and techniques.

Redundant vent pipes to be removed and holes to be blocked up with finishes to match existing adjacent.

Existing roof including parapet walls and copings to be cleaned and repaired if necessary.

All existing windows, reveals and cills, joinery and shutters to be repaired and redecorated as necessary.

All metal windows to be redecorated.

Existing light fittings and cabling to be removed.

Existing critical type window to be replaced with new sash window to match heights and materials of existing sash windows in the adjacent Montague Street facing rooms. Existing security bars to be removed.

Existing window cill height.

Existing roof including parapet walls and copings to be repaired if necessary.

New extract duct from kitchenette and WC at ground floor level.

Existing window to be replaced for a sash window to match existing windows. Existing security bars to be removed.

External timber panelling to be stripped back repaired and redecorated in exterior grade paint finish to match colour of existing.
 Stucco render to be repaired and redecorated with breathable mineral paint finish in colour to match existing.
 Existing doors to be redecorated with exterior grade paint finish.

Existing door containing asbestos to be replaced with new to match existing. Refer to detail drawing (32)AD001.
 New railing added to existing parapet in design and finish to replicate existing adjacent. Height to comply with building regulations.

Decorative Iron Railings around Balconies at First and Third Floors
 Balconies unsafe - No Access

REVISION / DESCRIPTION	DRAWN	CHECKED	DATE
D - For Listed Building Consent Discharge Condition 6	LBE	AC	25/07/18
C - For Planning and Listed Building Consent Application	LBE	MB	23/06/17
B - For Planning and Listed Building Consent Application	LBE	MB	01/06/17
A - For comments	LBE	MB	12/05/17
FIRST ISSUE	LB	MB	28/04/17



BDP.

18 Brewhouse Yard
 Clerkenwell
 London, EC1V 4LJ
 United Kingdom
 T +44 (0)20 7812 8000
 F +44 (0)20 7812 8399
 www.bdp.com

British Museum Perimeter Properties Refurbishment	
P2007246	
DRAWING TITLE 1-1A Montague Street Proposed Rear Elevation	SCALE 1:50@A1
DATE Planning and LBC Application	DATE April '17
REVISION (15)AE002	REVISION D



BUILDING DESIGN PARTNERSHIP LTD SHALL HAVE NO RESPONSIBILITY FOR ANY USE MADE OF THIS DOCUMENT OTHER THAN FOR THAT WHICH IT WAS PREPARED AND ISSUED.
 ALL DIMENSIONS SHOULD BE CHECKED ON SITE.
 DO NOT SCALE FROM THIS DRAWING.
 ANY DRAWING ERRORS OR DIVERGENCES SHOULD BE BROUGHT TO THE ATTENTION OF BUILDING DESIGN PARTNERSHIP LTD AT THE ADDRESS SHOWN BELOW.

NOTES

- EXISTING STRUCTURE
- NEW CONSTRUCTION
- OFFICE SPACE
- KITCHEN / STORE / CLEANER'S CUPBOARDS
- TOILETS
- X-X-DXX EXISTING DOOR
- *X-X-DXX NEW DOOR
- *A-X-X-DXX NEW DOOR TO REPLACE EXISTING ASBESTOS CONTAINING DOOR
- X-X-WXX EXISTING WINDOW NUMBERS
- *X-X-WXX NEW WINDOW NUMBERS
- DOOR HOLD OPEN DEVICE

REVISION / DESCRIPTION	DRAWN	CHECKED	DATE
J - Structural openings	MF	AC	TBI
I - Structural openings setting out	MF	AC	18/05/18
H - Stage 4	MF	AC	04/05/18
G - For information	LB	MB	26/06/17
F - For information	LB	MB	08/06/17
E - For information	LB	MB	28/04/17
D - For information	LB	MB	06/04/17
C - For information	LB	MB	17/03/17
B - For information	LB	MB	03/03/17
A - For information	LB	-	21/02/17
FIRST ISSUE	LB	-	13/02/16

REV	DATE	DESCRIPTION



BDP.


18 Brewhouse Yard
 Clerkenwell
 London, EC1V 4LJ
 United Kingdom

T +44 (0)20 7812 8000
 F +44 (0)20 7812 8399
 www.bdp.com

British Museum Perimeter Properties Refurbishment	
P2007246	
DRAWING TITLE 1-1A Montague Street Second Floor Plan	SCALE 1:50@A1
DATE February '17	REVISION I
DRAWING NO. (20)AP004	















WIP



BUILDING DESIGN PARTNERSHIP LTD SHALL HAVE NO RESPONSIBILITY FOR ANY USE MADE OF THIS DOCUMENT OTHER THAN FOR THAT WHICH IT WAS PREPARED AND ISSUED.
 ALL DIMENSIONS SHOULD BE CHECKED ON SITE.
 DO NOT SCALE FROM THIS DRAWING.
 ANY DRAWING ERRORS OR DIVERGENCES SHOULD BE BROUGHT TO THE ATTENTION OF BUILDING DESIGN PARTNERSHIP LTD AT THE ADDRESS SHOWN BELOW.

NOTES

-  EXISTING STRUCTURE
-  NEW CONSTRUCTION
-  OFFICE SPACE
-  KITCHEN / STORE / CLEANER'S CUPBOARDS
-  TOILETS
-  EXISTING DOOR
-  NEW DOOR
-  NEW DOOR TO REPLACE EXISTING ASBESTOS CONTAINING DOOR
-  EXISTING WINDOW NUMBERS
-  NEW WINDOW NUMBERS
-  INTERNAL OPENING DETAIL
-  DOOR HOLD OPEN DEVICE

REVISION / DESCRIPTION DRAWN CHECKED DATE

J - Structural openings	MF	AC	TBI
I - Structural openings setting out	MF	AC	18/05/18
H - Stage 4	MF	AC	04/05/18
G - For information	LB	MB	26/06/17
F - For information	LB	MB	08/06/17
E - For information	LB	MB	28/04/17
D - For information	LB	MB	07/04/17
C - For information	LB	MB	17/03/17
B - For information	LB	-	03/03/17
A - For information	LB	-	21/02/17
FIRST ISSUE	LB	-	13/02/17

REVISED



BDP.

16 Brewhouse Yard
 Clerkenwell
 London, EC1V 4LJ
 United Kingdom

T +44 (0)20 7812 8000
 F +44 (0)20 7812 8399
 www.bdp.com


British Museum
 Perimeter Properties Refurbishment

P2007246

DRAWING TITLE: 1-1A Montague Street Third Floor Plan SCALE: 1:50@A1

DATE: February '17

REVISION: (20)AP005 REVISION: J



WIP

Our Locations

Birmingham

2 The Wharf
Bridge Street
Birmingham
B1 2JS
T. 0121 643 4694
birmingham@curtins.com

Bristol

Quayside
40-58 Hotwell Road
Bristol
BS8 4UQ
T. 0117 302 7560
bristol@curtins.com

Cambridge

50 Cambridge Place
Cambridge
CB2 1NS
T. 01223 631 799
cambridge@curtins.com

Cardiff

3 Cwrt-y-Parc
Earlwood Road
Cardiff
CF14 5GH
T. 029 2068 0900
cardiff@curtins.com

Douglas

Varley House
29-31 Duke Street
Douglas
Isle of Man
IM1 2AZ
T. 01624 624 585
douglas@curtins.com

Dublin

39 Fitzwilliam Square
Dublin 2
Ireland
T. 00353 1 507 9447
dublin@curtins.com

Edinburgh

1a Belford Road
Edinburgh
EH4 3BL
T. 0131 225 2175
edinburgh@curtins.com

Glasgow

Queens House
29 St Vincent Place
Glasgow
G1 2DT
T. 0141 319 8777
glasgow@curtins.com

Kendal

28 Lowther Street
Kendal
Cumbria
LA9 4DH
T. 01539 724 823
kendal@curtins.com

Leeds

Rose Wharf
Ground Floor
Leeds
L29 8EE
T. 0113 274 8509
leeds@curtins.com

Liverpool

51-55 Tithebarn Street
Liverpool
L2 2SB
T. 0151 726 2000
liverpool@curtins.com

London

40 Compton Street
London
EC1V 0BD
T. 020 7324 2240
london@curtins.com

Manchester

Merchant Exchange
17-19 Whitworth Street West
Manchester
M1 5WG
T. 0161 236 2394
manchester@curtins.com

Nottingham

56 The Ropewalk
Nottingham
NG1 5DW
T. 0115 941 5551
nottingham@curtins.com