Lighting Strategy Victoria House Heritage Areas



Table of Contents

1. Ground Floor Lift Lobby Approach


Issue Status: Heritage Planning Permission


Project Number: 0987
Date: 21/08/20
Client: LABS




3

1. Ground Floor Lift Lobby Approach






The pendant will be placed at its historic location improving the visual aesthetic of the corridor and creating a symmetry on both side of the circulation space. The Heritage luminaire will also help to improve the overall lighting level by providing soft ambient light to the corridor.



power could be taken to supply the heritage luminaire.

Additional work to the ceiling must be done in order to anchor the pendant at the middle of the soffit and at the same time to re-locate the smoke detector to centre of the hallway for safety

Proposed luminaires for lift lobby



Legend

Description: Pair of ceiling spotlight in front each lift door.
- Location: North & South Ground Floor lift lobby
- Colour temperature: 2700K

- Wattage: 3.5W (310 lm) Beam Angle: 8 deg

Suggested Product: Manufacturer: Reggiani

Product name: Yori surface Ø35mm - 0.FH51B.HWL0



New design to be approved


Description: Wall Mounted luminaire between lift door. - Location: North & South Ground Floor lift lobby

- Colour temperature: 2000K-2800K - Wattage: 11W (1000 lm) E14 Base - Beam Angle: Diffuse

Suggested Product:


Manufacturer: Tala Product name: Light Engine 1

Lighting Calculations





1. Ground Floor Lift Lobby Approach





To be restored to its historic nature



Rectangular Pendants North and South Ground Floor lift lobby

The existing heritage luminaires were initially refurbished were possible utilising modern LED light source in 2017. The new lighting scheme aim to improve/refurbish the historic luminaires in a general and minimal way focusing in the internal LED to provide a much better light quality to the space.

A simple and automated control system is proposed to ensure the lighting is set to the most efficient and effective levels throughout the day, giving the Central Hall further flexibility to create appropriate lighting scenes for the various functions that are held.

The front cast face of the metal frame has been cut away and a diffuser inserted, the removal of this section is crude and it has undermined the structural integrity of the fitting which accounts for the frame work appearing to be bent. This has been fitted with poor quality frosted acrylic. It is noted there are no safety cables fitted.

Improvements:

- A new cast section should be made to replace the section removed to restore the luminaire to its historic nature.
- The interior fixtures should be replaced with new 2700K LED striplights.
- The diffusers should be removed and fitted with a quality opal acrylic.



LIGHT BUREAU

Light Bureau Limited
7F Hewlett House
Havelock Terrace
London SW8 4AS
United Kingdom
Phone +44 (0)20 7498 6111
mail@lightbureau.com

Light Bureau C/o AFRY Lilleakerveien 8 0283 Oslo Norway Phone +47 454 78 101 mail@lightbureau.com

