

## METHOD STATEMENT

St George's Cathedral / Christ Church

Netting Removal and Tower and Cornice Repairs

Rev 00 · March 2021



## Revision History

Rev	Description	Author	Reviewer	Date
00	Issued for Listed Building Consent	JRM	SK	09.03.2021

## ROGER MEARS ARCHITECTS

Union Chapel  
Compton Avenue  
London N1 2VD

[www.rmears.co.uk](http://www.rmears.co.uk)

## Contents

- 1.0 Introduction
- 2.0 Current Condition
- 3.0 Preparatory Works
- 4.0 Conclusion

## 1.0 Introduction

- 1.1 This method statement has been prepared to support the Listed Building Consent application for the installation of the fall arrest netting to St George's Cathedral / Christ Church at the request of the conservation officer at the London Borough of Camden.
- 1.2 This statement has been prepared as a forward-looking document anticipating the removal of the fall arrest netting followed by the immediate repairs to the cornice and tower.
- 1.3 A 'letter of comfort' was received from the London Borough of Camden which permitted the building owner to execute urgent works under Section 9 Part 3 of the Planning (Listed Buildings and Conservation Areas) Act 1990.
- 1.4 The fall arrest netting was installed in late February 2021.
- 1.5 The installed netting is considered temporary work to mitigate the the risk of loose and friable material falling from high level to ground level which represents a severe health and safety risk.
- 1.6 The rendered cornice and render to tower require permanent repair and those works are expected to be captured in a future application which will also include the removal of the fall arrest netting.

## 2.0 Current Condition

### 2.1 St George's Cathedral (formerly Christ Church)



*Img. 1; Netting installed to the cornice*



*Img. 2; Close-up view of black netting installed to sky-facing edge of cornice*



*Img. 3; Black netting installed to tower*

## 3.0 Preparatory Works

### 3.1 Existing Materials Analysis:

There are a number of existing materials and elements that form the historic fabric of the failing external features. These must be carefully reviewed, recorded and analysed to ensure compatible sympathetic products and materials are sourced for final repair works.

#### 3.1.1 Render, Mortar and Pointing

- 3.1.1.1 It is believed that the failing rendered elements are original fabric which has deteriorated substantially and has reached the end of its life.
- 3.1.1.2 There is evidence of previous ad-hoc cement repairs to the tower which accelerated the decay of adjacent historic fabric.
- 3.1.1.3 A chemical analysis should be undertaken by a specialist to analyse the composition of the original historic render mix.
- 3.1.1.4 A judgment will need to be taken whether like for like repairs include for the re-use of identical historic render mix or if technological improvements are available and suitable or if environmental factors necessitate that an altered / improved product be used.
- 3.1.1.5 Once a suitable product mix including coloured admixtures is identified this can be recorded in the product specification.
- 3.1.1.6 Following LBC for these repairs, comparative sample panels should be prepared to assess the visual impact of new render and for approval by the Local Authority.

#### 3.1.2 Brickwork

- 3.1.2.1 There is evidence of brick failure on the tower particularly where singular bricks have been partially embedded to create a dentilled cornice effect. In many cases, the exposed portion of the brick has cracked away. This failure likely exposed a long-term latent defect in the brick manufacturing process.
- 3.1.2.2 The remaining brick dentils should be assessed based on their likelihood to fail in the future.
- 3.1.2.3 Where bricks have already failed their joints will need to be raked out and the broken brick eased out of place.
- 3.1.2.4 New bricks will need to match on a like for like basis but should be assessed also for suitability as decorative dentils.
- 3.1.2.5 Following LBC for these repairs, samples should be sourced for comparison and approval with the Local Authority.

#### 3.1.3 Pointing

- 3.1.3.1 Existing cement pointing should be fully raked out. A suitable like for like mortar (taking into account results of mortar analysis) should be applied to replicate the existing effect.





## 4.0 Conclusion

- 4.1 The outline method statement has been prepared at this moment in time with all the knowledge available to us at this point. The condition of the tower and or cornices will not improve over time. We can expect that a conservation-led design team in the future will carry out detailed investigations and propose a suitable approach to safeguard the building for generations to come.

# ROGER MEARS ARCHITECTS

Union Chapel  
Compton Avenue  
London N1 2VD

[www.rmears.co.uk](http://www.rmears.co.uk)

T: 020 7359 8222

E: [rma@rmears.co.uk](mailto:rma@rmears.co.uk)