

Landmark Trees

---

**FURTHER INVESTIGATION REPORT:**

5 Oval Road  
London  
NW1 7EA

**REPORT PREPARED FOR:**

Richard Tomlinson  
5 Oval Road  
London  
NW1 7EA

**REPORT PREPARED BY**

Adam Hollis  
MSc ARB MICFor FArbor A MRICS C Env

**Ref:** LRE/5OLR/PCS/01

**Date:** 4<sup>th</sup> September 2020

The content and format of this Report are for the exclusive use of the Client. It may not be sold, lent, hired out or divulged to any third party, not directly involved in the subject matter without Landmark Trees written consent.

---

**Web:** [www.landmarktrees.co.uk](http://www.landmarktrees.co.uk)  
**e-mail:** [info@landmarktrees.co.uk](mailto:info@landmarktrees.co.uk)  
**Tel:** 0207 851 4544



**London Office:** Holden House, 4th Floor, 57 Rathbone Place London W1T 1JU

**Registered Office:** 15 Abbey Road, Oxford OX2 0AD

Landmark Trees is the trading name of Landmark trees Ltd. Registered in Wales. Reg No. 3882076



 Institute of  
Chartered Foresters  
Registered Consultant

**The statements in this Report do not take account of the effects of extremes of climate, vandalism or accident, whether physical, chemical or fire cannot therefore accept any liability in connection with these factors, nor where prescribed work is not carried out in a correct and professional manner in accordance with current good practice. The authority of this Report ceases at any stated time limit within it, or if none stated after two years from the date of the survey or when any site conditions change, or pruning or other works unspecified in the Report are carried out to, or affecting, the subject tree(s), whichever is the sooner.**

**Limitations of Use and Copyright:**

**The content and format of this Report are for the exclusive use of the client. It may not be sold, lent, hired out or divulged to any third party not directly involved in the subject matter without our written consent.**

## **Site Details**

**Site Address:** 5 Oval Road, London NW1 7EA

**Client / Agent:** Richard Tomlinson

**Surveyor:** Kim Dear

**Date of Inspection:** 20<sup>th</sup> August 2020

## **Instruction**

Carry out Picus Tomograph Decay detection on the main stem of T6, a sycamore within the rear garden of 5 Oval Road. Client would like a second opinion on the condition of the tree. As part of our report, the Client would specifically like our *opinion on the disease, the life expectancy, stability (tree is leaning) and the effects on the adjacent properties (No5 & No7 Oval Road) by removing the tree.*

## **Picus Sonic Tomography**

The Picus Sonic Tomograph is made by a German company called Argus-Electronic-GmbH. It is a specialised electronic instrument which can 'look' internally into a branch or tree trunk and display a computer generated image of its condition. It achieves this by measuring the speed that sound travels through the wood in a number of different positions and directions. Sound travels fastest through solid wood. Decayed wood will slow its path. By measuring the speed that sound takes to pass through a tree, an idea of its condition can be obtained.

The PICUS Sonic Tomograph consists of 8 to 14 sonic sensors. These sensors are spaced out evenly around the circumference of the trunk. They detect stress waves induced by manual impact propagated through the wood. Time-of-sound-transmissions are used to generate two-dimensional pictures that document decay and cavities.

The sounds are generated manually by tapping on a number of metal nails with a hammer. Special sensors fixed around the stem read the interval the sound takes to travel through the wood. Once all nails have been tapped, and recordings taken, the computer software works out a visual image that requires professional assessment to assess decay.

## T6 Details

**Species:** Sycamore (*Acer pseudoplatanus*)

**Diameter:** 700mm

**Height:** 19m



Photograph 1: Location of T6

## Observations

The tree is situated on the northern boundary of the property, with a panel fence loosely attached to the east and west of the stem. The stem leans to the north over the adjoining council-owned property (No7 Oval Road) and is bifurcated at 6m with a narrow fork. The property is being developed and site usage appears relatively intensive. According to the British Geological Survey, the site overlies London Clay (please see <http://mapapps.bgs.ac.uk/geologyofbritain/home.html>).

There is a small cavity measuring 10cm by 5cm at ground level to the south of the stem (see Photograph 2). No immediate fungal fruit bodies or pathogens are evident at the seat of decay, nor is inspection of the internal wood readily possible. There are metal brackets included in the stem at 0.4 and 1.5m to the West and 2m to the east. The canopy appears full and well balanced with no obvious dieback, but has been crown raised in the past, leaving a long unmodified 'lever-arm' to the main stem and relatively low crown ratio. There is moderate swelling in the base of the tree around the cavity with the diameter increasing markedly to >1000mm, compared to 700mm at 1.5m height.



Photograph 2: Small cavity at base of tree

## Results

One tomograph was taken, at a level 10cm above ground. The tomograph shows an area of decay to the south of the stem with a cavity shown in blue, advanced decay coloured pink/purple and the incipient or early decay coloured green.




Figure 1: Tomograph of T6 taken at 10cm above ground level

## Discussion

No single pathogen / disease can be confirmed at this time, though annual fungal fruit bodies may reveal themselves presently in Autumn. Equally, bodies of perennial fruiting fungi are not always evident on impacted trees. However, it is most likely the decay is caused by one or more of the common decay fungi colonising hardwood / broadleaved trees (e.g. *Ganoderma* spp). These degrade the internal timber with often less obvious symptoms in the tree's external physiognomy, though sometimes a marked basal swelling and / or general thinning / dying back of the canopy. Basal swelling has been observed here as is common in *Ganoderma* decay.

Whilst the percentage cross-sectional area of decay (55%) to sound wood (45%) indicated on the tomograph does not necessarily occupy a high proportion of the overall cross-section of the stem, its eccentric position means it does occupy a large part of the southern half of that stem with the result that the residual walls at points 6 and 8 are particularly narrow (c. 3cm). A higher percentage of 70% decay to 30% sound wood is generally considered a statistical safety threshold. However, Fraedrich and Smiley (1999) recommend increasing the sound wood requirement for trees with asymmetric decay columns, trees that are leaning, trees with low crown ratios, trees with other defects and trees on high use sites. Given the other observed defects in the tree, ongoing adjacent construction works and difficulty in carrying out a crown reduction due to the past pruning history, its retention is deemed, on balance, imprudent. Given the size and position of the cavity, in conjunction with the leaning stem and other defects / site conditions, I would be reticent to award this tree much more than 10 years Safe Useful Life Expectancy.

The removal of a mature tree from a property overlying highly shrinkable London clay could lead to a change in soil volume as the tree's water extraction ceases. This change could impact adversely upon surrounding structures (e.g. wall or building foundations) in the immediate and adjacent properties. A risk assessment is recommended (see below).

## **Recommendations**

Fell tree within 3 months of the date of this report.

Consult with a structural engineer on providing a heave risk assessment with regards to potential ground movement following the removal of a mature tree. NB replacement planting may also be a condition of planning consent to remove the existing tree: the design of foundations and other structures should also take this condition (and future tree growth) into consideration.