
ATWORTH ARBORICULTURE LTD



DECAY DETECTION ON A WEEPING WILLOW TREE AT UNIVERSITY COLLEGE SCHOOL, LONDON.



Prepared for: Marcus Foster. The statements in this Report do not take account of the effects of extremes of climate, vandalism or accident, whether physical, chemical or fire (Atworth Arboriculture Ltd) cannot therefore accept any liability in connection with these factors, nor where prescribed work is not carried out in a correct and professional manner in accordance with current good practice. The authority of this Report ceases at any stated time limit within it, or if none stated after two years from the date of the survey or when any site conditions change, or pruning or other works unspecified in the Report are carried out to, or affecting, the subject tree(s), whichever is the sooner.

Limitations of Use and Copyright:

The content and format of this Report are for the exclusive use of the client. It may not be sold, lent, hired out or divulged to any third party not directly involved in the subject matter without our written consent.

Site Address: University College School, London, NW3 6XH.

Client: Marcus Foster

Instruction: Carry out Decay detection tests on the main stem of 1 tree at the address above.

Inspection: The inspection was carried out by Vince Cainey BSc on 4th August 2021. The weather was dry and sunny.

<u>Tree:</u> Weeping Willow Salix babylonica Diameter 1160mm Height 9m

General Observation:

This tree is adjacent to the main entrance gate to the school, 4m south of the tree. 4m west of the tree is Frognal, a busy road and 2m west the pavement. 2m to the east is a school road. No faults were observed at the base of the tree. The stem leans to the south towards the entrance gate. At 2m above ground level (agl), to the west is a large lateral limb. The main stem bifurcates at 4m agl with limbs southwest and northeast. A large limb has been removed from the southwest leader leaving a stub of around 1m in length. On the underside of the stub are small brackets of the fungi, *Phellinus igniarius*, and associated decay. The crown has been historically pollarded with lots of old pruning wounds throughout.

Resistograph Tests:

The Resistograph is a Drilling instrument that probes the tree with a micro drill with a 3mm tip and a 1.5mm x 400mm shaft; this can penetrate to a depth of 40cm. As the probe advances it measures the resistance encountered and feed rate of the needle. Good healthy wood gives a high reading and poor dysfunctional wood, or cavity gives a lower reading. The readings are presented below.


The instrument used was the IML Resistograph PD400 which has far more capability than earlier models. There are 5 different speed settings, and the data is recorded electronically. The readings show the measured resistance as a black line and the feed rate of the needle as a blue colour. It is useful to have the 2 settings as with the F400 friction on the needle would give you a false high graph. Although there is still friction on the needle with the PD400 the feed rate will change as decay is encountered.

9 Resistograph test were carried out.

Direction	Height	Results	
East	0cm	All Good.	
East	2.5m	Good-25cm, remainder decay.	
East	4m	All decay.	
North	2.5m	All good.	
South	2.5m	Good-23cm, remainder cavity.	
South	3.5m	Decay-30cm remainder good.	
Southeast	3.5m	Good-30cm, remainder decay.	
West	2.5m	Good-14cm, decay -20cm, good-36cm, remainder decay	
West	4m	Decay-28cm, remainder cavity	

Measuring / object data

Measurement n	o.: 1	Speed : 2500 r/mir	Diameter: 116,00 cm
ID number	: UCL E0	Needle state:	Level : 0
Drilling depth	: 40,08 cm	Tilt :	Direction: East
Date	: 04.08.2021	Offset : 82 / 353	Species: Weeping Williow
Time	: 10:49:53	Avg. curve : off / off	Location: UCL
Feed	: 100 cm/min		Name : Vince Cainey




Assessment

From 3,42 cm to 39,87 cm : Good Wood

	Comment
- [
- 1	
- 1	
- 1	
- 1	
- 1	
- 1	





Assessment




Comment



Measuring / object data

Measurement no.:	: 5	Speed	: 2500 r/min	Diameter: 116,00 cm
ID number	: UCL E4m	Needle stat	e:	Level : 4
Drilling depth	40,07 cm	Tilt	:	Direction: East
Date	04.08.2021	Offset	: 88 / 263	Species: Weeping Williow
Time	10:56:32	Avg. curve	: off / off	Location: UCL
Feed :	: 150 cm/min	_		Name : Vince Cainey




Assessment

From 2,75 cm to	39,94 cm : Decay

Comment






Assessment

From 1,49 cm to 39,90 cm : Good Wood

Comment

Measuring / object data




Assessment

From 1,74 cm to 22,88 cm : Good Wood From 22,88 cm to 39,87 cm : Cavity

Comment	
1	

Measurement no.: 6 ID number : UCL S3.5 Drilling depth Direction: South
Species: Weeping Williow
Location: UCL
Name: Vince Cainey Date Time : 150 cm/min




Assessment

From 2,13 cm to 30,11 cm : Decay
From 30,11 cm to 39,94 cm : Good Wood

Comment

Measuring / object data

o.: 7 Speed : 2500 r/min
: UCL SE3.5 Needle state: -: 40,05 cm Tilt : -: 04.08.2021 Offset : 86 / 264
: 10.59:05 Avg. curve : off / off
: 150 cm/min Measurement no.: 7 ID number Drilling depth Date Time Feed




Assessment

From 0,65 cm to 25,40 cm : Good Wood From 25,40 cm to 39,90 cm : Decay

	Comment
ı	
ı	
ı	
ı	
ı	
ı	

Measurement no.: 10	Speed	: 2500 r/min	Diameter: 116,00 cm	
ID number	: UCL W2.5	Needle state: ---	Level	: 2.5
Drillling depth	: 40,05 cm	Tilt	: --	Direction: West
Date	: 04,08.2021	Offset	: 78 / 264	Speeds : Weeping Williow
Time	: 11:04:24	Avg. curve	: off / off	Location: UCL
Name	: Vince Cainey			




Assessment



Comment

Measuring / object data



Assessment



Comment

Conclusion.

Resistograph readings were taken in 2 main areas, around the decaying stub at 4m and above the large lateral limb at 2.5m. Most of the tests show cavity and decay. This level of decay is sufficient to affect the structural integrity of the tree. As the tree has already been pollarded little work can be done to reduce the stress and weight of the decayed and hollow areas. Willow although classed as hard wood is relatively weak and are prone to catastrophic failure. The target should the tree fail is very high.


Recommendations:

The tree should be felled as soon as practically possible. This work to be carried out by a fully qualified and insured tree surgeon working to BS3998(2010), Tree work..

Vince Cainey BSc

23rd August 2021.






Assessment



Comment

1		


Measuring / object data



Assessment

From 2,00 cm to 39,90 cm : Decay

Comment




Assessment

From 1,97 cm to 39,94 cm : Good Wood

Comment

Measuring / object data



Assessment

From 1,74 cm to 39,84 cm : Decay

Comment		