





Photo Ref.1 Photo Ref. 2






- Do not scale from this drawing.
- The defects on this drawing are based on an inspection for an assessment undertaken in 2016 by AECOM and verified on site in 2020
- Following NR response to Technical Query 129021-TQ001-DCL/140A -Steelwork Repair Requirements, steelwork repairs to DCL/140A have been de-scoped from this scheme, on the basis that "the structure currently meets the route availability in terms of assessed category" based upon the 2016 Assessment which accounts for the current condition of the structure. Key defects are depicted on this drawing for completeness, but aside from pumping railbearers which are to be packed, no further steelwork repairs have been included.

Key to symbols	
----------------	--

- Existing elements

Reference drawings



## NOT FOR CONSTRUCTION

MACDONALD

Spring Bank House 33 Stamford Street Altrincham WA14 1ES United Kingdom T +44 (0)161 926 4000 F +44 (0)161 926 4100

W www.mottmac.com



LEC1/9E Canal Bridge Existing Steelwork Defect Plan

164941-MMD-00-XX-DR-C-1002

esigned	B. Standring	RES	Eng check	I. Crook	IJC
rawn	O. Palmer	OP	Coordination	B. Standring	RES
wg check	I. Crook	IJC	Approved	B. Standring	RES
IMD Project Number 110044			Scale at A0 AS SHOWN		
uitability De <b>Vork I</b>	Suit. Code				

Revision

A01

© Mott MacDonald Limited

This document is issued for the party which commissioned it and for specific purposes connected with the captioned project only. It should not be relied upon by any other party or used for any other purposes. We accept no responsibility for the consequences of this document being relied upon by any other party, or being used for any other purpose, or containing any error or omission which is due to an error or omission in data supplied to us by other parties.