


## ARBORICULTURAL ASSESSMENT REPORT

<b>For:</b>	<b>Client:</b>	Sedgwick International UK
	<b>Insurer:</b>	Covea
<b>Site:</b>	<b>Policyholder:</b>	Aberdare Gardens Ltd
	<b>Risk Address:</b>	57 Aberdare Gardens, London, NW6 3AL
<b>Refs:</b>	<b>PRI Ref:</b>	
	<b>Client Ref:</b>	
	<b>Insurer Ref:</b>	

<b>Arborist Name:</b>	Will Hinde	<b>Date:</b>	11/01/2021
<b>QC:</b>	Margaret MacQueen	<b>Date:</b>	11/01/2021



Property Services



Insurance Services



Consumer Services



Data Services

## **CONTENTS**

1.0 INTRODUCTION & BRIEF .....	3
2.0 LIMITATIONS.....	3
3.0 DISCUSSION AND ANALYSIS .....	4
4.0 CONCLUSIONS AND RECOMMENDATIONS.....	5
5.0 STATUTORY CONTROLS.....	5
6.0 APPENDIX 1: TREE TABLES .....	6
7.0 APPENDIX 2: SITE PLAN .....	10
8.0 APPENDIX 3: SITE PHOTOGRAPHS.....	12



## **1.0 INTRODUCTION & BRIEF**

- 1.1** Property Risk Inspection has been instructed on behalf of the building insurers of the insured property. We have been advised that the insured property has suffered differential movement and damage that is considered to have been caused by trees growing adjacent to the property influencing soils beneath its foundations.
- 1.2** We have been instructed to undertake a survey of the vegetation growing adjacent to the insured property in order to provide our opinion as to whether, based on the available information, any of this vegetation is likely to be influencing soil moisture levels beneath the foundations of the property, and if so, to provide recommendations as to what tree management could be implemented to effectively prevent damage continuing.
- 1.3** The vegetation growing adjacent to the risk address has been surveyed from the ground. All distances are measured to the nearest point of the risk address unless otherwise stated.

## **2.0 LIMITATIONS**

- 2.1** Recommendations with respect to tree management are associated with the risk address as stated on the front cover of this report and following consultation with investigating engineers. The survey of trees and any other vegetation is associated with impacts on the risk address subject of this report. Matters of tree health, structural condition, and/or the safety of vegetation under third party control are specifically excluded. Third party land owners are strongly advised to seek their own professional advice as it relates to the health and stability of trees under their control.
- 2.2** Recommendations do not take account of any necessary permission (statutory or otherwise) that must be obtained before proceeding with any tree works.
- 2.3** Recommendations do not take account of any requirements for survey or mitigation relating to European or other protected species, e.g. bird nesting or bats. Land owners must obtain their own professional advice in respect of any protected species.



## **3.0 DISCUSSION AND ANALYSIS**

### **3.1 Soils, soil water and vegetation**

All vegetation requires water to live, and this water is substantially accessed from the soil within which the plants' roots grow.

If the soil is classified as a clay soil, then it will hold very much more water than sands, gravels and loam soils. As plants abstract water from the clay soil, the soil volume will 'shrink' and 'swell' during the summer as water is first removed and then added by summer rainfall. In years in which rainfall during the summer is less than the total amount of water taken from the soil by plants, shrinkage will occur. This shrinkage may remove support from building foundations, leading to cracking in the fabric of the building.

### **3.2 Vegetation management**

The control of trees, shrubs, and climbers, by removal or pruning as appropriate, are proven techniques that can control total soil water loss thereby minimising soil shrinkage and allowing repairs to proceed.

If vegetation management works are carried out promptly, then repairs can usually proceed very quickly and the duration and distress associated with the disruption that tree related subsidence brings can be minimised.

### **3.3 Third party liaison and statutory controls**

Tree roots do not respect physical or property boundaries and can travel for many metres beyond the above ground 'dripline' of the canopy of the vegetation.

The purpose of this report is to ascertain which vegetation is the most likely substantial and/or effective contributory cause of the damage witnessed to allow for liaison with third parties or with local administrative Councils as necessary.

### **3.4 Evidential framework**

The engineer has determined on a preliminary basis the damage to the property, its location and the likely mechanism of movement, and has concluded that the building failure is related to differential subsidence damage caused as a result of the action of vegetation.

Where a factual geotechnical report has been completed, this will describe the below ground foundation design, soil and geotechnical conditions, as well as any root identification where available.



## 4.0 CONCLUSIONS AND RECOMMENDATIONS

### 4.1 Recommendations

On the basis of our findings, we have considered a practical vegetation management specification.

This specification will assist in reducing the impact of the adjacent vegetation on soil moisture levels, thereby potentially stabilising foundations of the affected area of the building.

Where felling has been proposed, this will be on the basis that the vegetation in question would not respond well to a severe reduction in leaf area that would inevitably lead to decay, the development of potential hazards, and an annual or other on-going management commitment and cost.

If pruning is recommended, the specification will be designed to allow continual ease of re-pruning with a reasonable prospect of a reduction in soil water use.

### 4.2 Recommended vegetation management to address the current subsidence:

Tree No:	Species	Works Required
T1	Plane	
T2	Plane	
T7	Plane	
T8	Plane	

## 5.0 STATUTORY CONTROLS

Camden Council has confirmed that the implicated London Plane trees T2 & T7/T8 are subject to a Tree Preservation Order. The properties are also within the South Hampstead Conservation Area.



Tree No	Common Name	Age Class	Condition	Height (m)	Crown Spread (m)	Stem diam. (mm)	Dist to bldg. (m)	Roots implicated	Pruning history	Recommendation	Tree work constraints	Notes	Owner address	Owner
T1	Plane (London)	Mature	Fair	16*	10	700*	24.0	N	Subject to past management.		Access through side/rear gate.		67 Greencroft Gardens London NW6 3LJ	P3P
T2	Plane (London)	Mature	Fair	17.5	10	600*	23.0*	N	Subject to past management.		Access through side/rear gate.		67 Greencroft Gardens London NW6 3LJ	P3P
T3	Palm	Semi-Mature	Fair	4	1.0	120	7.5	N	No significant past tree works.	No work required.	Access through side/rear gate.		57 Aberdare Gardens London NW6 3AL	PH
S1	Hydrangea	Semi-Mature	Fair	2.2*	2	20*	0.1	N	No significant past tree works.	No work required	Access through side/rear gate.		55 Aberdare Gardens NW6 3AL	P3P
S2	Bay	Mature	Good	2.2*	2	300*	1.4	N	Subject to past management.	No work required		large nature base, approx 250mm diameter.	55 Aberdare Gardens London, NW6 3AL	P3P

Tree No	Common Name	Age Class	Condition	Height (m)	Crown Spread (m)	Stem diam. (mm)	Dist to bldg. (m)	Roots Implicated	Pruning history	Recommendation	Tree work constraints	Notes	Owner address	Owner
T4	Bay	Mature	Good	8	4	120*	10*	N	No significant past tree works.	No work required.	Access through building.		55 Aberdare Gardens London NW6 3AL	P3P
T5	Fig	Mature	Fair	3.5	3.0	80*	4.9*	N	Subject to recent reduction within 12 months.	No work required.			55 Aberdare Gardens London NW6 3AL	P3P
S3	REED	Mature	Good	2	3.0	10*	3	N	No significant past tree works.	No work required.			57 Aberdare Gardens London NW6 3AL	PH
HG1	Laurel (Portuguese), rose	Semi-Mature	Good	1.5*	1.2	40*	0.1	N	Subject to past management.	No work required.		front of property is shared between the flats	57 Aberdare Gardens London NW6 3AL	PH
H1	Privet	Semi-Mature	Fair	3	1.0	30*	0.5	N	Subject to past management.	No work required.		front of property is shared between flats	57 Aberdare Gardens London NW6 3AL	PH
H2	Laurel (Portuguese)	Semi-Mature	Fair	1	0.50	35*	0.1	N	Subject to past management.	No work required.		front garden shared between flats	57 Aberdare Gardens London NW6 3AL	PH
T6	Rose	Mature	Fair	2*	2	20*	3	N	Subject to past management.	No work required.		front of property	57 Aberdare Gardens	PH



Tree No	Common Name	Age Class	Condition	Height (m)	Crown Spread (m)	Stem diam. (mm)	Dist to bldg. (m)	Roots Implicated	Pruning history	Recommendation	Tree work constraints	Notes	Owner address	Owner
												shared between flats	London NWS 3AL	
T7	Plane (London)	Mature	Good	17	8	700	23	N	Subject to past management.				67 Greencroft Gardens London NW6 3LJ	P3P
T8	Plane (London)	Mature	Good	17	10	800	24	N	Subject to past management.				67 Greencroft Gardens London NW6 3LJ	P3P

\* Value is estimated







Location:	57 Aberdare Gardens, London, NW6 3AL
Job Ref:	[REDACTED]
Survey Date:	- NTS
By Property Risk Inspection - Insurance Services	



	
T1 - Plane (London)	T3 - Palm
	
S1 - Hydrangea	S2 - BaY
	
T4 - BaY	T5 - Fig
	
S3 - REED	HG1 - Laurel (Portuguese), rose
	
H1 - Privet	H2 - Laurel (Portuguese)



	
<p>T6 - Rose</p>	<p>T2 - Plane (London) (1)</p>
	
<p>T1 - Plane (London) (1)</p>	<p>T7 - Plane (London)</p>
	
<p>T8 - Plane (London)</p>	<p>T5 - Fig (1)</p>
	
<p>S2 - Bay (1)</p>	<p>S2 - Bay (2)</p>
	
<p>S1 - Hydrangea (1)</p>	
	