


Front Elevation of Lower Ground Floor, 42 Parkhill Road (see diagram 100 - 101 A)



- In the lower ground bay, you can see the white painted plaster that will be restored to glazed timber windows more in keeping with the overall front facade design.
- Central bay window in poor repair, all to be made good.
- Lower portion of this window not visible from street level due to its placement in the front lightwell