



A handwritten signature in black ink, appearing to read 'Daniel O'Neill', is positioned above the printed name.

Daniel O'Neill
Director

39 MUSEUM STREET

fire door details

Monday, 12 December 2022

19 Issues Identified



ISSUE 1

Assigned To FD Doors

Doors 1-3 are 27mm thickness

Door 4 is 37 mm thickness

Door widths are 638mm

Door frames widths 650mm

21mm + gaps at bottom of door



ISSUE 2

Assigned To FD Doors

Different thickness doors also old hinge cavity's chizzled in to door edges



ISSUE 3

Assigned To FD Doors

Door leaf thickness



ISSUE 4

Assigned To FD Doors

Door leaf thickness



ISSUE 5

Assigned To FD Doors

Behind riser doors big gaps around ironmongery also fitted with dry wall screws



ISSUE 6

Assigned To FD Doors

Damages to doors



ISSUE 7

Assigned To FD Doors

Excessive gaps



ISSUE 8

Assigned To FD Doors

Joins are opening up



ISSUE 9

Assigned To FD Doors
Damage to leafs



ISSUE 10

Assigned To FD Doors
Gaps opening up



ISSUE 11

Assigned To FD Doors
Top level cupboard doors seem to have been changed seem to be blank FD30 doors with a beading attached for feature had no access for measurements



ISSUE 12

Assigned To FD Doors
FED doors to flats could not get access but should be same detail as riser doors



ISSUE 13

Assigned To FD Doors

FED doors to flats could not get access but should be same detail as riser doors



ISSUE 14

Assigned To FD Doors

FED doors to flats could not get access but should be same detail as riser doors



ISSUE 15

Assigned To FD Doors

FED doors to flats could not get access but should be same detail as riser doors



ISSUE 16

Assigned To FD Doors



ISSUE 17

Assigned To FD Doors

FED doors to flats could not get access but should be same detail as riser doors



ISSUE 18

Assigned To FD Doors

FED doors to flats could not get access but should be same detail as riser doors



ISSUE 19

Assigned To FD Doors

FED doors to flats could not get access but should be same detail as riser doors