






Photographic survey of the pitched roof

REFERENCE	PHOTO
<div>1. East Elevation</div> <div><p>BUILDING OUTLINE</p><p>CROFTOWN ROAD</p></div>	

2. East Elevation



CROFTTOWN ROAD



Photographic survey of the pitched roof

3. East Elevation

BUILDING OUTLINE



Photographic survey of the pitched roof

4. East and West Elevation






Slipped slates. Typical in numerous locaitons throughout the roof. Indicitatve of nail rot.

Photographic survey of the pitched roof

5. East Elevation

BUILDING OUTLINE







Photographic survey of the pitched roof


6. East Elevation

BUILDING OUTLINE



CROFTOWN ROAD







Photographic survey of the pitched roof


7. East Elevation

BUILDING OUTLINE



CROFTOWN ROAD







Photographic survey of the pitched roof


8. East Elevation

BUILDING OUTLINE




CROFTTOWN ROAD







Photographic survey of the pitched roof

9. Internal loft space (East elevation)





Daylight through the sarking boards and staining to the same is indicative of penetrating damp.

10. West Elevation



Photographic survey of the pitched roof

11. West Elevation



Slipped and broken slate.

Photographic survey of the pitched roof

12. West Elevation

BUILDING OUTLINE

WEST ELEVATION









Photographic survey of the pitched roof

13. West Elevation

BUILDING OUTLINE

WEST ELEVATION





Photographic survey of the pitched roof

14. West Elevation

BUILDING OUTLINE

WEST ELEVATION

