



View of the existing Second Floor timber floor viewed from the Rear Elevation Bedroom.



View of the existing Second Floor timber floor viewed from the Front Elevation Study Room.



View of the existing condition to the second floor threshold area to balcony - water damage



View of the existing Second Floor timber floor viewed the bedroom - visible hole through




View of the existing condition to the second floor hallway



View of the existing Second Floor timber floor hallway adjacent to landing



View of the existing condition to the second floor hallway




View of the existing Second Floor timber floor hallway adjacent to landing



Area of previously replaced flooring to the bedroom (lower half of image)



View of the existing First Floor ceiling - water damaged areas from the bathroom above



Reference Plan for Floor Condition Photos on previous pages: Please note **FLR.7** indicates an area of flooring with significant movement. A video record of this flooring defect is available.