

01

1:50

Block A - Existing and Temporary - Distribution Route from Housing Office Balcony to Roof - Elevation

02

For ro	bof plan information. Refer to dwg 3467_L	B_120008 Repaint existing metal balustrade	03 140006	Existing water tank. Existing damage t enclosure to be made good. New Fl locks to be fitted as require	o M
Block A5		01 331002	Lift Core		
Block A5		01			
ehind					
nesh enclosure to protect d water supply. Pattern to h existing ballustrade infill	Exposed mains cold water supply from ground				
	01 130014		03 140006	For pipew	зr

