



18-20 Gower Street – Front Elevation (Gower Street Fronting)



 Windows to be repaired/redecorated.

 Location of bowed brickwork and deformed window.