

**PHOTO SHEET**

**In respect of**

**2 PRIMROSE GARDENS**

**LONDON NW3 4TJ**

**Proposal - replacement of 2.no roof level uPVC doors with uPVC windows**



Photo 1 – roof level box gutter, showing existing upvc door, to be stripped out and replaced with a upvc window to match the existing window units on the elevation.



Photo 2 – existing box gutter uPVC window, new units to match. Newly formed opening to be finished at low level with a weather proofed external insulated wall finished externally in slates to match.





Photo 3 – existing box gutter uPVC window, new units to match. Newly formed opening to be finished at low level with a weather proofed external insulated wall finished externally in slates to match.



Photo 4 – interior of box gutter level uPVC window. New units to match.





Photo 5 – threshold of existing door openings too low, causing damp ingress problems.



Photo 6 – interior of box gutter level uPVC window. New units to match.





Photo 7 – view of box gutter windows from ground level.