





GROUND FLOOR, FINISHES 23. ENTRANCE & STAIRS





Entrance:

Floor: New Stone, Limestone, with contrast diamond laid marble inlay Treads & Risers : Retain, paint to be carefully stripped back to expose stone

Skirting: Painted. Retain original skirting, replace small area of modern Handrail : Retain, gently sand back and refinish mahogany, carefully repair

skirting to match original Dado : Painted. Replace

Cornice : Painted. Retain original Ceilings : Painted. Retain Original

HD01: Paint, Retain original door HD02: Paint, New Panelled Door HD03: Paint, New Panelled Door HD04: Paint, New Panelled Door

Main Staircase

Balustrade: Retain, carefully strip back and repaint ironwork Runner to be laid with stair rods

Basement Staircase

Interior Design Pack Handrail : Replace with new mahogany handrail

Walls: Painted

Dado : Painted. carefully repair where required Cornice : Painted. Retain original Ceilings : Painted. Retain Original


GLOUCESTER GATE GODDARD & STUDIO

Treads & Risers : Retain, paint to be stripped back to expose stone Balustrade: Retain, strip back and repaint ironwork. Add new Balustrade to under stair - See


- Skirting: Painted. Retain original skirting, carefully repair where required



GROUND FLOOR, FINISHES 24. DINING ROOM



HDot



ELEVATION

Formal Dining

Floor: New wide planks of engineered oak, running across the room Walls: Painted Skirtings: Painted. New Skirting AD.SB02 Dado : Painted. New Dado ***

Cornice : Painted. Retain original

Ceilings : Painted. New plasterboard

Doors :


HD02: Paint, new panel door. DD01: Painted, New Panelled Double Doors, new opening & Door Header - Painted.

Fireplace: New marble surround Hearth: New marble hearth laid flush with timber floor

Windows - Paint, retain, repair where required Window Shutters - Paint, retain, repair where required Window Radiator Covers - Paint & metal mesh. New



GROUND FLOOR, FINISHES 22. BAR / LIBRARY



Bar Library

Floor: New wide planks of engineered oak, running across the room

(note flush floor box located in room)

Walls: Painted or wallpaper

Skirting: Painted. New Skirting AD.SB02

Dado : Painted. Replace


Cornice : Painted. Retain original

Ceilings : Painted. New plasterboard

Doors :

HD03: Paint, New panelled door. Repair existing architrave DD01: Painted, New Panelled Double Doors New opening & Door Header - Painted, see Interior Design Detail Pack

Fireplace: New marble surround Hearth: New marble hearth laid flush with timber floor




ELEVATION

Windows - Paint, retain, repair where required Window Shutters - Paint, retain, repair where required Window Radiator Covers - Paint & metal mesh. New, See joinery drawing



GROUND FLOOR, FINISHES 21. KITCHEN



Kitchen

Floor: large format tile Walls: Painted Skirting: Timber Cornice : N/A Ceilings : Painted


Doors

HD04: Paint, New panelled door. Repair existing architrave & lining DD03: Timber flat panel arched double doors


Joinery

Cabinets: combination of timber and metal fronts Counter tops: Marble or Quarzite

Windows - See architects drawings Window Reveals : timber lined openings




ELEVATION 03



ELEVATION o



GROUND FLOOR, FINISHES 15. ACTIVITY ROOM




HD05: paint & plaster jib door with concealed architrave DD04: plaster & plaster double jib doors

Joinery Cabinet & shelves : timber or laquered Counter tops: Marble or man made stone

Arch Windows - See architects drawings Arch Window Reveals : timber lined openings Sash windows: - Painted, see architect's drawings

Counter tops: Marble or man made stone



FIRST FLOOR, FINISHES 30. FORMAL RECEPTION




Slots in floor below windows, to allow heating air flow



2 x flush floor boxes, Cable Duct UK or similar





ELEVATION 03

Formal Reception


Floor: New wide planks of engineered oak, running front to back Walls: Painted Skirting: Painted. New Skirting AD.SB02 Dado : Painted. Replace Cornice : Painted. Retain original Ceilings : Painted. New plasterboard


HDo6: Paint, new panelled door, New architraves, See AD.A.01 DD03: Painted, New Panelled Double Doors New opening & Door Header - Painted, see J.1F.01.02

Fireplace: New marble surround Hearth: New marble hearth laid flush with timber floor Joinery: 2 new joinery pieces, to house the FCU. See joinery drawings

Windows - Paint, retain, repair where required Window Shutters - Paint, retain, repair where required

FIRST FLOOR, FINISHES 28. SITTING ROOM





Sitting Room

Floor: New wide planks of engineered oak, running front to back Walls: Painted or Wallpaper Skirting: Painted. New Skirting AD.SB02 Dado : Painted. Replace Cornice : Painted. Retain original Ceilings : Painted. New plasterboard

HD07: Paint, new panelled door DD03: Painted, New Panelled Double Doors New opening & Door Header - Painted, see J.1F.01.02

Fireplace: New marble surround Hearth: New marble hearth laid flush with timber floor

Windows - Paint, retain, repair where required Window Shutters - Paint, retain, repair where required




FIRST FLOOR, FINISHES 29. STAIRS & LANDING STEPS



Main Stairs

Treads & Risers: Restore & repair existing stone Carpet Runner to stair flights, with stair rods Walls: Painted Skirting/Stronger: Painted. Retain existing Dado : Painted. Retain existing Cornice : Painted. Retain original Ceilings : Painted. Retain Original Balustrade: Retain, strip back and repaint ironwork Handrail : Retain, gently sand back and refinish mahogany, carefully repair

Doors : HDo6: Paint, new panelled door HDo7: Paint, new panelled door



Landing steps to study,

Steps: new marble steps Walls: Painted & Timber panels Skirting/Stringer: Painted. Retain existing Opening reveal : New lining, painted Ceilings : Painted

Doors :

HDo8: New timber flat panel door SDo1: New timber curved door

FIRST FLOOR, FINISHES 27. STUDY



Study

Floor: Wide planks of engineered oak, running across the room (note flush floor box located in room) Walls: Painted or wallpaper, Timber panels to back wall Skirting: Timber Ceilings : Painted. New plasterboard

Doors : HDo8: Timber flat panel door, timber architrave

Windows: See architects drawings Window reveals (internally) - timber lined

WC

Floor: Tile or marble floor


Walls: tile or marble, with mirror set into wall above vanity, and mirrored doors above $\ensuremath{\mathsf{WC}}$

Ceilings : Painted. New plasterboard, with access panel


Study Corridor

SDoi: Timber curved sliding door, timber architrave Floor: Wide planks of engineered oak, set across the room (note flush floor box located in room) Steps : Marble Walls: Painted or wallpaper Skirting: Timber Ceilings : Painted. New plasterboard

Windows: See architects drawings Window reveals (internal) - timber lined



ELEVATION 02



ELEVATION 04




2 x flush floor boxes, Cable Duct UK or similar

1 O

SECOND FLOOR, FINISHES 34. MASTER BEDROOM





ELEVATION 03

Master Bedroom

Floor: New wide planks of engineered oak, running across room Walls: Paint or wallpaper Skirting: Painted. New Skirting Dado : N/A Cornice : New, painted Ceilings : Painted. New plasterboard

Doors : HD09: Paint, new panelled door HD10: Paint, new panelled door

Fireplace: New marble surround Hearth: New marble hearth laid flush with timber floor

Windows - Paint, retain, repair where required Window Shutters - Paint, retain, repair where required Window radiator covers : paint & metal mesh

1 1

SECOND FLOOR, FINISHES 33. MASTER DRESSING



Master Dressing

Floor: New wide planks of engineered oak, running across the

room


- Walls: Paint or wallpaper
- Skirting: Painted. New Skirting
- Dado : N/A

Cornice : N/A

Ceilings : Painted. New plasterboard

Doors :

HD10: Paint, new panelled door HD11: Paint, new panelled door



Joinery : Finishes TBC, but likely a combination of mirror, timber & Lacquer

SECOND FLOOR, FINISHES 32. MASTER BATHROOM




Master Bathroom Floor: Marble or Stone Walls: Marble or Stone Skirting: N/A Cornice : New, Painted Ceilings : Painted. New plasterboard

Doors : HD11: Paint, new panelled door

Joinery : Vanity : timber with stone top Medicine Cabinet : Mirror & Metal

Windows - Paint, retain, repair where required Window Shutters - Paint, retain, repair where required Window radiator covers : paint & metal mesh, marble top



ELEVATION 03

SECOND FLOOR, FINISHES 35. STAIRS & HALLWAY




Hallway

Floor: Stone final tread to main stair, then engineered timber planks Walls: Painted Skirting: New, Painted Cornice : Retain, Painted Ceilings : Retain, painted Dado: Retain, Painted

Doors : HD09: Paint, new panelled door

Secondary Stairs: Treads & Risers: New timber stair, painted Carpet Runner to stair Balustrade: New ironwork, painted Handrail : New mahogany handrail Skirting/Stringer: Painted. Retain existing



Main Stairs

Treads & Risers: Restore & repair existing stone Carpet Runner to stair flights, with stair rods, no runner to landing Balustrade: Retain, strip back and repaint ironwork Handrail : Retain, gently sand back and refinish mahogany, carefully repair Walls: Painted Skirting/Stringer: Painted. Retain existing Dado : Painted. Retain existing Cornice : Painted. Retain original Ceilings : Painted. Retain Original

Doors : HD09: Paint, new panelled door

Window: New Window, see architects drawings - painted Window reveal : painted

THIRD FLOOR, FINISHES 39&46 BED & BATH 04




Bed o4

Floor: New wide planks of engineered oak, running across room Walls: Paint or wallpaper Skirting: Painted. New Skirting Dado : N/A Cornice : N/A Ceilings : Painted. New plasterboard

Doors : HD12: Paint, new panelled door HD13: Paint, new panelled door

Fireplace: New marble surround Hearth: New marble hearth laid flush with timber floor

Windows - Paint, retain, repair where required Window Joinery : Paint



Bath 04

Floor: Tile or Stone Walls: Tile or Stone Cornice : N/A Ceilings : Painted. N

ELEVATION 06

Ceilings : Painted. New plasterboard, with skylight

THIRD FLOOR, FINISHES 36&38 BED & BATH 02




Bed o2

Floor: New wide planks of engineered oak, running across room Walls: Paint or wallpaper Skirting: Painted. New Skirting Dado : N/A Cornice : N/A Ceilings : Painted. New plasterboard

HD14: Paint, new panelled door HD15: Paint, new panelled door

Fireplace: Existing surround Hearth: New marble hearth laid flush with timber floor

Windows - Paint, retain, repair where required



Bath 02

Floor: Tile or marble Walls: Tile or marble Cornice : N/A

Ceilings : Painted. New plasterboard, with skylight

THIRD FLOOR, FINISHES 37 BED 03




Bed og

Floor: New wide planks of engineered oak, running across room Walls: Paint or wallpaper Skirting: Painted. New Skirting Dado : N/A Cornice : N/A Ceilings : Painted. New plasterboard

Doors : HD16: Paint, new panelled door

Windows - Paint, retain, repair where required



ELEVATION o

THIRD FLOOR, FINISHES 40 HALLWAY



Secondary Stairs: Treads & Risers: New timber stair, painted Balustrade: New ironwork, painted Handrail : New mahogany handrail Skirting/Stringer: Painted. Retain existing




Hallway:

Floor: New wide planks of engineered oak, set across landing Walls: Paint or wallpaper Skirting: Painted. New Skirting Dado : N/A Cornice : N/A Ceilings : Painted. New plasterboard

HD12: Paint, new panelled door HD14: Paint, new panelled door HD16: Paint, new panelled door HD17: Paint, new panelled door

THIRD FLOOR, FINISHES 41. SHARED BATHROOM





Shared Dathioon


Floor: Tile or marble Walls: Tile or marble Cornice : N/A Ceilings : Painted. New plasterboard

Windows - Paint, retain, repair where required Window Joinery : Paint & marble sill

LL VATION 03



LOWER GROUND FLOOR, FINISHES 43, 07 & 08 BOOT ROOM & HALLWAY



Boot Room

Floor: Large format tile Walls: Paint with tongue and groove panelling Skirting: Painted. New Skirting Dado : N/A Cornice : N/A Ceilings : Painted

Doors :

HD18: Existing Door, Painted HD19: Paint, new panelled door HD19: Paint, new panelled door

Hallway

Floor: Large format tile (note flush access panel) Walls: Paint Skirting: Painted. New Skirting Dado : N/A Cornice : N/A Ceilings : Painted

Doors :

HD19: Paint, new panelled door HD21: Paint, new panelled door HD22: Paint, new panelled door HD23: Paint, new panelled door HD24: Paint, new panelled door HD25: Paint, new panelled door


Closet

Floor: Large format tile Walls: Paint & Joinery Skirting: Painted. New Skirting Dado : N/A Cornice : N/A Ceilings : Painted

Doors : HD23: Paint, new panelled door



LOWER GROUND FLOOR, FINISHES 12,02 & 10 : BED & BATH 05 & WC



Bed 05

Floor: New wide planks of engineered oak, set across room Walls: Paint or wallpaper Skirting: Painted. New Skirting Dado : N/A Cornice : New, painted Ceilings : Painted. New plasterboard

Doors : HD19: Paint, new panelled door HD20: Paint, new panelled door

Windows - Paint, retain, repair where required Window Shutters: Paint Window Radiator Cover : Paint & Metal Mesh

Bathroom 05


Floor: Tile or marble Walls: Tile or marble Cornice : N/A Ceilings : Painted. New plasterboard

WC

Floor: Tile or marble Walls: Tile or marble to half height, painted plaster above Cornice : N/A Ceilings : Painted. New plasterboard



LOWER GROUND FLOOR, FINISHES 11. UTILITY



Utility


Floor: Large format tile Walls: tile to half height, painted plaster above Skirting: Painted. New Skirting Dado : N/A Cornice : N/A Ceilings : Painted. New plasterboard

Doors : HD22: Paint, new panelled door

Joinery: TBC



LOWER GROUND FLOOR, FINISHES 06: TV ROOM



TV Room:

Floor: Wide engineers timber border, with inset carpet Walls: Painted panels to half height, painted plaster above. Mirror to back wall, with mirrored door accessing TV equipment Skirting: Painted half height panels Cornice : N/A Ceilings : Painted. New plasterboard, with recessed projector & projector screen


Doors : HD25: Paint, new panelled door

Joinery: Mirrored back wall

Windows - Paint, retain, repair where required Window Shutters: Paint Window Radiator Cover : Paint & Metal Mesh



LOWER GROUND FLOOR, FINISHES 05. GYM & SPA



Gym:

Sauna:

Floor: Wide engineered timber floor (note access panel) Walls: Painted or specialist plaster. Mirror to back wall, set into timber joinery with ballet bar Skirting: Timber Cornice : N/A Ceilings : Painted. New plasterboard

Doors :

HD24: Paint, new panelled door HD26: Timber flat panel door

Joinery: Mirrored back wall

Windows - New, see architects drawings Window reveals: Timber internal reveals and frames


Steps: Timber treads & risers

Floor: timber slats Walls: Timber slats and interior window Ceilings : Timber slats


Doors : Glass doo

Joinery: timber seating & sauna oven

Windows - New internal window Window reveals: Timber internal reveals and frames



ELEVATION 03




ELEVATION 02

- Shower
- Floor: tile
- Walls: tile and painted plaster at high level
- Ceilings : Painted plaster
- Hot tub
- Floor: tile & recessed hot tub
- Walls: tile and painted plaster at high level
- Ceilings : Painted plaster with access panel



LOWER GROUND FLOOR, FINISHES 01. GARAGE



Garage:

mews entry Walls: Painted, with timer lining to stair wall Skirting: tile to garage, timber to mews entry Cornice : N/A Ceilings : Painted. New plasterboard, with access panels

HD26: Timber flat panel door HD27: Timber flat panel door HD28: Existing front door, painted

Stairs: Timber treads & risers Timber balustrade and wall lining

Floor: Large scale tile or Epoxy paint to screed to garage, engineered timber to

THANK YOU

GLOUCESTER GATE GODDARD & STUDIO