Appendix A – Front elevation of the site



No.18 [left] and 20 [right] – SIXTEEN unauthorised laminated timber/composite sash windows (**W1 - W16**) - ground to third floor levels.

Appendix B - Rear Elevation of the site




No.18 [left] & 20 [right]: EIGHT unauthorised laminated timber/composite sash windows (**W17 - W24**), TWO unauthorised laminated timber/composite casement windows (**CA1 & CA2**), ONE unauthorised laminated timber/composite top-hung casement window (**CA3**), ONE unauthorised laminated timber/composite door (**DR1**) - basement to third floor levels.

Appendix C – Flank elevation sash windows of the rear extensions



No.18 [left] & 20 [right]: ONE unauthorised laminated timber/composite sash windows (No.18 only) (**W25**) – ground floor.



No.18 [left] & 20 [right]: TWO unauthorised laminated timber/composite sash windows (**W26 & W27**) - first floor.

Appendix D – Rear terrace doors at the second floor rear extension



No.18 [left] & 20 [right]: TWO unauthorised laminated timber/composite doors (DR2 & DR3).