






NOTES

 Indicative Site Boundary

 Low pressure steam cleaning to remove black staining from brickwork. Carry out test patches on lower ground floor to determine appropriate temperature and pressure to avoid causing damage to tuck pointing during cleaning.



Rear Lightwell



Rear Lightwell

