

- 1. Later addition WC closet wing extension in poor condition removed to create new link to
- 2. Poor condition WC closet wing extension roof replaced with new higher thermally performing flat roof to new link.
- Later addition non sympathic corrugated metal cladding to WC extension replaced with weathered London stock brickwork to match existing adjacent.
- 4. Existing non-original window replaced with new thermally broken double glazed window style to match new skylights.
- 5. New basin installed into existing internal window opening.
- 6. Existing non original storage cupboard partition and door rebuilt in design in keeping with the period and character of the studio.
- 7. Existing black metal handrail retained and repaired.
- 8. New low profile solar panels, positioned back from eaves to not be visible from ground, to reduce environmental impact of dwelling.




Alterations Front Elevation



Alterations Rear Elevation



- 3. All levels shown relative to Charlotte Street only.
- --- Leasehold retail unit boundary (outside of application)



28 Charlotte Street

Drawing

Alterations. Front and Rear Elevations

Drawing No.

28CS(10)A04

1st Floor, 59 Charlotte Street London W1T 4PE, UK T +44 (0)20 7637 8839 M +44 (0)77 9669 4196 E info@studiostassano.com www.studiostassano.com



Job No. 13.03.20 1:100@A3 28CS 1:50@A1

