





Loose feather edge boards



Video can be provided to demonstrate instability of the fence



Rotten gravel board and lower part of the fence, indicating evidence of rising damp



Fence is not aligned with the gravel board



Rotten gravel board



Rotten gravel board and lower part of the fence, indicating evidence of rising damp

Figured dimensions only are to be taken from this drawing - for construction purpose. All dimensions are to be checked on site before any work is put in hand. **DO NOT SCALE FROM THIS DRAWING - for construction purpose.** If in doubt, ask.

Copyright © 4H Architecture Limited 2025  
Registered in England & Wales.  
Registered No. 12112149  
4H is the trading name of 4H Architecture Limited

Note

Revision		
PL01	Planning	21.03.2025.

project	131_9 Wedderburn Road
client	Private Client

site address	9 Wedderburn Road, London, NW3 5QS
--------------	------------------------------------------

date	21.03.2025.
scale	

designed / drawn by	4H Architecture 07515 772458 C/O DS Burge and Co., The Courtyard, 7 Francis Grove, London, SW19 4DW
---------------------	--------------------------------------------------------------------------------------------------------------

drawing title	<b>Fence Condition</b>
project number_drawing number_revision	<b>131_425_PL01</b>