

---

## PHOTOGRAPHIC PLATES

---

PHOTOGRAPHIC PLATES



Plate 1. General view to front of property.



Plate 2. Large Plane tree to rear of property.

Cont'd overleaf.../





Plate 3. Displaced step now filled with grout.




Plate 4. Vertical crack to garage wall.

Cont'd overleaf.../



Plate 5. High level cracking to wall in living room.



Plate 6. Cracking to ceiling in living room.

Cont'd overleaf.../



Plate 7. Cracking to wall in hallway.



Plate 8. Skirting to GF WC.

Cont'd overleaf.../






Plate 9. Misaligned door to understairs cupboard.




Plate 10. Displaced newel post.

Cont'd overleaf.../



Plate 11. Cracking to landing at FF level.



Plate 12. Further view of cracking.

Cont'd overleaf.../



Plate 13. Cracking in hall above door to front bedroom.




Plate 14. Cracking above door in master bedroom.

Cont'd overleaf.../





Plate 15. Corner cracking to ensuite.



Plate 16. Corner cracking to main bathroom.

Cont'd overleaf.../



Plate 17. Vertical crack in garage.




Plate 18. Cracking in pantry – change in medium.

Cont'd overleaf.../



Plate 19. Evidence of existing cracking.



Plate 20. Hairline cracking to coving in office.

Cont'd overleaf.../





Plate 21. General condition of cracking at second floor level.