## Appendix A: Site Walkover Records



**Image 1**: Eastern portion of the Site which is used vehicle parking and used for the storage of timber. Note that there is a skip which contains domestic waste.




Image 2: Contents of the skip.



Image 3: Storefront of the current builders' merchants.




Image 4: Interior of the warehouse.




Figure 5: Electrical Switchroom.



Image 6: Electrical Substation at the northeastern corner of the Site.

Appendix B: Proposed Development Documentation





