

- KEY
- (\overline{A}) existing painted roughcast dash render
- B existing painted timber mock-tudor details
- $\overline{(C)}$ existing painted brick
- (D) existing plain red roof tiles
- (E) existing bitumen asphalt roof
- (F) existing double glazed, painted timber window
- \bigcirc existing double glazed, painted metal rooflight / skylight
- (\overline{H}) existing double glazed, painted timber door
- $\bar{(\mathbf{I})}$ existing plain red tiled dormer with double glazed, painted timber window
- () existing painted metal balustrade

- (01) proposed painted roughcast insulated render to match existing
- (02) proposed reinstated painted timber mock-tudor details
- (03) proposed painted insulated brick to match existing
- (04) proposed plain red roof tiles to match existing
- (05) proposed insulated GRP roof
- (06) proposed triple glazed, painted timber window to match existing style & proportions
- (07) proposed triple glazed, painted composite metal & timber rooflight / skylight * = denotes rooflight with integrated external shading blinds
- 08 proposed triple glazed, painted timber door to match existing
- style & proportions
- (09) proposed triple glazed, painted composite metal & timber door / window
- 10 proposed plain red tiles to existing dormer with triple glazed, painted timber
- window to match existing proportions
- (1) proposed external metal-framed glass balustrade
- (12) proposed external solar shading blinds
- (13) proposed solar PV panels
- (14) proposed maintenance access hatch



application ref: 2024/1788/P



LEGEND



2309

DATE

12.09.2024

75H

PA-1-3102

02