

Lintel over door opening.

Clean back steels for further inspection.

If more than 20% section is corroded, replace with concrete lintels (2no) and make good.

Do not scale from this print or use as a template.
 All dimensions must be verified on site before any work is put in hand and any discrepancies must be reported to the Architect. Where any variations occur between small scale and detailed drawings, detail drawings should be worked from.
 Copyright of this drawing is reserved by Osbornes and is issued on condition that it is not copied or disclosed to any third party either wholly or in part without the consent of Osbornes in writing.
 This drawing is to be read in conjunction with all relevant specifications and drawings issued by the Architect, Engineer and other specialists.

KEY



Red outlines indicate location of proposed works at each level.

REV B: 07/05/2025 Key added.
REV A: 30/04/2025 Notes updated.

OSBORNES CHARTERED ARCHITECTS

PO Box 395 • Malvern • Worcestershire • WR14 911

