


VICTORIA HOUSE - Second Floor Louvre Replacement / Reglazing




Louvre removal and re-glazing principles



PROPOSED






Existing metal louvres sat internal to the original existing window frames.

Historically glazing had been removed from corresponding window panes to allow air passage through.




Non - glazed areas that require re-glazing.

Historic louvre elements carefully removed to reveal existing window behind.



Reinstated glazing in existing window frames (External Southampton Row)



Reinstated glazing in existing window frames (upper 2 panes). Limited amounts of existing glazing were located on site and where possible these were used in the re-glazing exercise. Frames redecorated

- Bottom 4 panes are existing and remain as is.



Reinstated glazing in existing window frames (External Bloomsbury Square)



Reinstated glazing in existing window frames (upper 2 panes). Limited amounts of existing glazing were located on site and where possible these were used in the re-glazing exercise. Frames redecorated

- Bottom 4 panes are existing and remain as is.