



Timber infill removed to expose arched opening, now filled in with brickwork to enclose dressing room

Splayed casement window shown in photograph no longer on site. Replaced EW/G.22 on site.



South entrance joinery framing to be carefully restored

Check new FFL against FFL in listed part of the building

