



























**PHOTOGRAPH 21:
NO WATERPROOF JOINT BETWEEN THE STEP AND THE WALL.**





























































**PHOTOGRAPH 25:
ROT TO THE WINDOWS**