

60 Doughty Street - Listed Building Application
Photographic report



1.
Curved wall to be demolished and rebuilt slightly further into the front room with a shallower curvature. The existing door will not be effected by the works.



2.
The chimney breast in the front room is not centered on the wall.

60 Doughty Street - Listed Building Application
Photographic report



The dimensions of the ground floor rear room are inadequate to provide a functional kitchen for modern family living ^{3.}



The chimney breast in the ground floor rear room is partially engulfed in the partition subject of this application ^{4.}

60 Doughty Street - Listed Building Application
Photographic report



The partition between the front room and the rear room on the ground floor seen from the rear room

5.