


AS APPROVED



b.

C. d.


1st floor internal linking passage between buildings, salvaged red stock brick structure supported by reclaimed cast iron pillars Salvaged 19th Century timber and lead cupola, echoing those already in existence in the studios complex of similar age, style and construction. Partial demolition to roof of existing ground floor linking passage, rest retained Purpose made new sash window, profiles and molding to match existing Half hipped pitched roof, angle and clay tiles to match existing adjacent.

Re-build existing poor quality modern extension in salvaged red stock brick, plan area to extend to the full size of the building footprint below, incorporating the previous lean-too roof and 1st floor conservatory.

existing chimney raised, as previously granted.
doublepitched roof of 1st floor corridor, exposed timber roof structure with insulation above, clad inclay tiles to match existing adjacent



AS PROPOSED



d. e.

1st floor internal linking passage between buildings, salvaged red stock brick structure supported by reclaimed cast iron pillars Salvaged 19th Century timber and lead cupola, echoing those already in existence in the studios complex of similar age, style and construction.

Partial demolition to roof of existing ground floor linking passage, rest retained Purpose made new sash window, profiles and molding to match existing Half hipped pitched roof, angle and clay tiles to match existing adjacent.

Re-build existing poor quality modern extension in salvaged red stock brick, plan area to extend to the full size of the building footprint below, incorporating the previous lean-too roof and 1st floor conservatory. existing chimney raised, as previously granted.

doublepitched roof of 1st floor corridor, exposed timber roof structure with insulation above, clad inclay tiles to match existing adjacent

conservation rooflight set flush with tile [structural size 615 875h]