

PHOTO SHEETS



Photo 1: Existing front elevation.



Photo 2: Panorama of street scene with subject property to lhs of main tree.



Photo 3: Existing rear elevation illustrating rear dormer to be replaced with 2 new dormer windows.





Photos 4 & 5: Spiral staircase from ground floor rear addition leading to dead space on lower ground floor.



Photo 6: Existing window to be replaced with door leading to new wrought iron deck and stairs.



Photos 7 & 8: Elevation of existing deck and stairs with rear doors and transoms at ground floor level to be replaced.





Photo 9: Existing concrete deck.



Photo 10: View from deck to rear garden.



Photo 11: View from front garden to existing window to be replaced in proposed staff bedroom.



Photos 12 & 13: View from front entrance to lightwell and vaults.