

Note:

Details of proposed works are approximate and illustrative. Precise extent of necessary re-building to be determined during progress on site once stability of brickwork at anticipated re-build boundary is established.

Existing, relatively recent, cement pointing to be raked out together with rest of brickwork retained/rebuilt, and wall repointed with lime mortar.

-	1	-			1
-		_			-
_		_			
					-
		_			+
REV.	REVISION NOTE			REV.DATE	REV.B
Adm Clier Mr	. H. Raine & Prof. F	R. Rair	ne and Mr. Pa		nimact
Lo Site No Lo	N'S 2 and 1 Upper T ndon NW3 6RH Address: D. 2 and No. 1 Uppe ndon NW3 6RH				
Lo Ste No Lo	ndon NW3 6RH Address: 0. 2 and No. 1 Uppe				
Lo Ste No Lo Drav	ndon NW3 6RH Address: b, 2 and No, 1 Uppe ndon NW3 6RH			Checked	l þý:
Lo Site No Lo Draw FI Draw Sit	ndon NW3 6RH Address: , 2 and No. 1 Uppe ndon NW3 6RH why Status: INAL ISSUE why No. 3878/001 wing Table: te Plan, Location	Rev.	scate: As noted Plan,	Checked Drawn by: TMM	t by:
Lo Stre No Lo Draw FI Draw Sift Se pr	ndon NW3 6RH Address: , 2 and No. 1 Uppe ndon NW3 6RH why Status: INAL ISSUE why No. 3878/001 wing Title:	Rev. Plan, ion sh	scate: As noted Plan, wwing	Drawn by:	