



Drawing No. 1



Drawing No. 2

Drawing No. 1 is a typical window situation on Roger Street which is slowly disintegrating and is now unopenable.
Drawing No. 2 is a window in Doughty House and again is in a very poor state of repair, and no longer openable

**Pictures in support of application to renew or repair windows
To No.1 Roger street & No. 1 Doughty Street**

Charles E. Williams

90 Milton Avenue, Barnet Herts. EN5 2EU



Drawing No. 1

Drawing No. 1 is of Roger Street
Which is the end of the building
Where a new building is under
Construction with Aluminium

windows



Drawing No. 2

Drawing No. 2 is also of Roger
Street showing the bad
condition of the window and its
surround

Photos in support of the application to Camden Council to repair
and renew windows

CHARLES E. WILLIAMS

90 Milton Avenue, Barnet Herts EN5 2EU



1. DOUGHTY
STREET.
WCI.

PICTURE 2.



I. DOUGHTY
STREET
WC. 1.

PICTURE 1



Rear & Side Elevation of 1 Doughty Street
And front face of 1 Roger Street as Existing