




SECOND

CENTRE IN
ARCH OV



FIRST

VATS WINE BAR

INTERNAL CAST
IRON COLUMNS
FROM WINDOW
CILL TO FIRST
FLOOR TO
REMAIN

CRACKED/CORRODED
PAVEMENT LIGHT
TO BE REPLACED

CRACKED/CORRODED
PAVEMENT LIGHT
TO BE REPLACED

TEMPORARY
PROPS

PIER

740

GROUND

BASEMENT

3250 APPROX

2580 APPROX

FRONT ELEVATION 1:50

A
15 FEB 2012

P2	DETAIL ADDED. NOTES REVISED ISSUED FOR PRICING	MQ	LT
P1	ISSUED FOR PRICING	MQ	LT