

Damaged 2nd floor cornice
repaired and made good

Brick work re-pointed and soot
washed

Non-original windows removed.
All window replaced with single
glazed double hung timber
sash. Refer to drg SK/02 and
SK/06

Front elevation repaired and
restored. Stucco re-rendered
and banding reinstated

Non-original door case
removed and replaced refer to
drg: SK/02

2nd floor windows to 69
repositioned to align with
the remainder of the
terrace. Non-original
pelmet and balconies
removed

Street level railings
and steps repaired
and made good

