



Photo 2
Original Wall Construction:
Gate Pier leaning towards south
Original twice-weathered copings to be salvaged





3,5 & 7 Fitzjohns Avenue

Drawing Title

Existing Boundary Wall Photographs

Mayfair Property Developments Ltd








Photo 4 Original Wall Construction: Original twice-weathered copings to be salvaged Concrete coping infils where missing Cracks to plinth wall





3,5 & 7 Fitzjohns Avenue Drawing Title

Existing Boundary Wall Photographs

Mayfair Property Developments Ltd

Project Title








Photo 6 Original Wall Construction: Original twice-weathered copings to be salvaged Crack / displacement to plinth wall



lawray architects tel: 020 7138 3560 fax: 020 7138 3567

Drawing Title Existing Boundary Wall Photographs

3,5 & 7 Fitzjohns Avenue

Mayfair Property Developments Ltd

Project Title








Photo 8 Non-original wall construction: Brick on edge coping Modern machine made brick Pointing not struck when re-built against ground



lawray architects

Drawing Title Existing Boundary Wall Photographs

3,5 & 7 Fitzjohns Avenue

Mayfair Property Developments Ltd

Project Title








Photo 11 Non-original wall construction: Brick on edge coping Modern machine made brick



lawray architects tel: 020 7138 3560 fax: 020 7138 3567

3,5 & 7 Fitzjohns Avenue

Drawing Title

Project Title

Existing Boundary Wall Photographs

Mayfair Property Developments Ltd








Photo 9 Non-original wall construction: Non-original pier cap Stretcher bond pier Modern machine made brick



lawray architects

3,5 & 7 Fitzjohns Avenue

Drawing Title

Project Title

Existing Boundary Wall Photographs

Mayfair Property Developments Ltd